

PERMIT INFORMATION

Permit Number: C-1981-044 Mine Name: Williams Fork Mines Operator: Moffat County Mining, LLC Operator Address: Mrs Miranda Kawcak 29515 Routt County Road #27 Oak Creek, CO 80467 **County:** Moffat **Operation Type:** Underground **Permit Status:** Active **Ownership:** Private

Operator Representative Present:

Miranda Kawcak

Operator Representative Signature: (Field Issuance Only)

This report was issued electronically from the Divisions' Denver Office.

INSPECTION INFORMATION

Inspection Start Date: April 19, 1 Inspection Start Time: 15:45 Inspection End Date: April 19, 2 Inspection End Time: 17:00			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Cloudy
Joint Inspection Agency:		Joint Inspection Contacts:	
None			
Post Inspection Agency:		Post Inspection Contacts:	
None			
Inspector(s):	Inspector's Signature: Signature Date:		
Robin Reilley, GISP	Bobi	in s	villey
			24 April 2023

Inspection Topic Summary

Y - Air Resource Protection	R - Roads
N - Availability of Records	Y - Reclamation Success
R - Backfill & Grading	R - Revegetation
NA - Excess Spoil and Dev. Waste	N - Subsidence
NA - Explosives	Y - Slides and Other Damage
R - Fish & Wildlife	Y - Support Facilities On-site
R - Hydrologic Balance	Y - Signs and Markers
R - Gen. Compliance With Mine Plan	NA - Support Facilities Not On-site
N - Other	NA - Special Categories Of Mining
NA - Processing Waste	R - Topsoil
-	-
	COMMENTS

This was a partial inspection of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The inspection was conducted and the report and photos prepared by me, Robin Reilley of the DRMS. The temperature hovered around 45 degrees F. There was a light breeze and conditions were cloudy. Wildlife, particularly deer and elk frequent the site. Numerous carcasses littered the landscape due to the severe winter.

PERMITTING ACTIONS in PROGRESS: MAINTENANCE ITEMS MAINTENANCE ITEMS ADDRESSED

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

Reclamation will resume as snow melts. Facilities have been removed throughout the site and reclamation has been completed. Topsoil at the 5A Portal was placed and will be seeded this spring.

SIGNS and MARKERS – Rule 4.02

• Ponds were staked and topsoil piles were adequately marked.

ROADS - Rule 4.03

Construction 4.03.1(3) I 4.03.2(3); Drainage 4.03.1(4) I 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) I 4.03.2(5) and (6); Reclamation 4.03.1(7) I 4.03.2(7)

• The Haul Road at the entrance off State Highway 13 was passable and the site was accessible.

HYDROLOGIC BALANCE – Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Drainage-Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18

Ponds were holding small amounts of snowmelt.

- Pond at portal holding small amount of water no discharge.
- Areas around the portal has some rills that will be graded.
- Pond 5A-P1 at 5A portal was holding a small amount of water.
- Ponds SH- P1 and SH-P2 above the portal were dry at the time of inspection.

TOPSOIL – RULE 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4

• No instability was noted at the time of inspection and piles were marked with sakes.

BACKFILL and GRADING - RULE 4.14

Backfilling and grading has been completed with the exception of grading some rilling at the 5A Portal resulting from rapid spring snowmelt.

REVEGETATION - Rule 4.15

General Requirements 4.15.1; Use of Species 4.15.2, Grazing 4.15.5 Reclamation, (topsoil and seeding) has been completed with the exception seeding at the 5A Portal, scheduled for this spring.

INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5 Inspections 5.02; Availability of Records

Permit documents were not inspected as this was a partial inspection.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Photo 2: North facing slope at 5A Portal.



Photo 3: Pond SH-P2, not holding water/



Photo 4: Ponds HR-P1a and HR-P1b located just east of bridge over the Williams Fork River.



Photo 5: Main ditch in the Williams Fork Bottomlands.



Photo 6: Williams Fork Bottomland where hay is cropped.