

## QUARTERLY POND INSPECTION REPORT

Operator:	Bowie Resources LLC	Quarter:	First 2023
Mine:	Bowie No. 2 Mine - C-1996-083	Inspection Date:	29-Mar-23

<b>Pond Identification</b>	B	C	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Type of Pond	Sediment	Sediment	Sediment	Sediment	Sediment	Sediment

<b>Status During Inspection:</b>	5944'	5992'	5971'	5946	5848	5819
Approximate Water Level	90%	90%	80%	60%	80%	80%
Sediment (% remaining)	0	0	0	0	0	0
Outflow (cfs)						

<b>Features</b>	Problem	Problem	Problem	Problem	Problem	Problem
	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No

<b>Erosional</b>	No	No	No	No	No	No
Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No

<b>Structural</b>	No	No	No	No	No	No
Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No

<b>Appurtenant Structures</b>	No	No	No	No	No	No
Defective Spillways	No	No	No	No	No	No
Dewatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

<b>Additional Comments</b>	<p>Design depth measured from pond bottom to invert of emergency spillway:</p> <p>Pond B=10, C=10, D=10, J=10, K=3, F=10' TD</p> <p>Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819</p> <p>Pond C was covered in snow and, held approximately 2' of water.</p> <p>Pond B was covered in snow and ice, held approximately 2' of water.</p> <p>Pond D held approximately 1' of water.</p> <p>Pond J was covered in ice held between 1-2' of water.</p> <p>Pond K was damp.</p> <p>Pond F held about 2' of water.</p>
----------------------------	--

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: Tamme Bishop

