



Seneca Yoast Mine
29515 Routt County Road 27
Oak Creek, CO 80467

November 4, 2022

Robin Reilley
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Seneca Yoast Mine, Permit C-94-082, Fourth Quarter 2022 IIR

CDRMS-

In accordance with Rule 4.05.9(17), please find enclosed the Seneca Yoast Mine (SYM) Impoundment Inspection Report (IIR) and Impoundment Inspection Log (IIL). Please contact me with any comments and/or questions.

Best regards,

Miranda Kawcak
Environmental Manager
Peabody, Colorado Operations

Enclosure: SYM 4Q22 IIR

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Valley Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #010		NW¼ NE¼, Sec. 8, T5N, R87W	
	CO-0000221 D.P. 010		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.3 FT
Existing Embankment Freeboard (10.1 ft)		X		11.4 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	OUTLET RUSTED BUT REMAINS FUNCTIONAL
Maintenance Performed			X	
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yeast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/21/2022		9/13/2022	
	Pond #011		NW¼ SW¼, Sec. 16, T5N, R87W	
	CO-0000221 D.P.011		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.8 FT
Existing Embankment Freeboard (5.1 ft)		X		6.9 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #011A		SW¼ NW¼, Sec. 16, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	2.8 FT
Existing Embankment Freeboard (4.6 ft)		X		7.4 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Top of Sediment Storage = 2.1 feet below top of pipe

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #012		NE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 012		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)		X		0.1 FT
Existing Embankment Freeboard (9.0 ft)		X		8.9 FT
Outflow (gpm)		X		32.1 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #012A		NE¼ NW¼, Sec. 19, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.7 FT
Existing Embankment Freeboard (4.6 ft)		X		6.3 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #013		SE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 013		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.5 FT
Existing Embankment Freeboard (4.0 ft)		X		5.5 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	10/20/2022		9/13/2022	
	Pond #014		NE¼ SW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 014		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.6 FT
Existing Embankment Freeboard (6.8 ft)		X		8.4 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

IMPOUNDMENT INSPECTION LOG

JOB DATA

JOB NAME: PEC Hydrologic Services	CLIENT: Peabody	JOB(s): 2021-095 (PSCM), 2021-096 (SCC)
-----------------------------------	-----------------	---

FLOW DATA

SITE ID	COMPANY	MINE	DATE	WATER LEVEL (FT)	OUTFLOW (GPM)	OBSERVATIONS	MAINTENANCE (Y/N)
002	Sage Creek	Sage Creek	10-20-22	0.1	19.1	Flume leaking under tilted	Y
003	Sage Creek	Sage Creek	10-20-22	-0.4	—	some animal burrows, no flow	N
004	Sage Creek	Sage Creek	10-20-22	0.1	22.3		N
Lower Sump	Sage Creek	Sage Creek	10-21-22	0.05	49		N
PECOCO	Sage Creek	Sage Creek	10-21-22	0.05	51		N
Portal Sump 1	Sage Creek	Sage Creek	10-21-22	-1.5	—	no flow	N
Portal Sump 2	Sage Creek	Sage Creek	10-21-22	—	—	not pumping	N
Spill Control 2	Sage Creek	Sage Creek	10-21-22	—	—	Dry	N
Truck Wash	Sage Creek	Sage Creek	10-21-22	—	—	Dry	N
Upper Sump	Sage Creek	Sage Creek	10-21-22	0.1	40		N
001	Seneca	Hayden Gulch	10-21-22	—	—	Dry	N
002	Seneca	Hayden Gulch	10-21-22	—	—	Dry	N
005	Seneca	Seneca II West	10-20-22	-3.2	—	no flow	N
006	Seneca	Seneca II West	10-20-22	0.1	31.7	stuff on S. side, no impact	N
009	Seneca	Seneca II West	10-20-22	-2.8	—	no flow	N
015	Seneca	Seneca II West	10-20-22	0.5	—	no flow	N
016	Seneca	Seneca II West	10-20-22	0.1	23.8		N
017	Seneca	Seneca II West	10-20-22	-0.3	—	no flow	N
T-1	Seneca	Seneca II West	10-20-22	—	—	Dry	N
T-18	Seneca	Seneca II West	10-20-22	—	—	Dry	N
T-2	Seneca	Seneca II West	10-20-22	—	—	Dry	N
T-20	Seneca	Seneca II West	10-20-22	—	—	Dry	N
T-22	Seneca	Seneca II West	10-20-22	-3.4	—	no flow	N
T-24	Seneca	Seneca II West	10-20-22	—	—	Dry	N
T-25	Seneca	Seneca II West	10-20-22	—	—	gone	N
T-26	Seneca	Seneca II West	10-20-22	-2.5	—	no flow	N

FIELD PERSONNEL: JH	FIELD PERSONNEL SIGNATURE: 
---------------------	---

[illegible]