

Notes:

Please refer to the 2023 Annual Report Map for the location of the areas discussed below.

8. The following list outlined the various areas of disturbance at the mine

<u>Description</u>	<u>Acres</u>
Growth medium Piles 47,200 cyd	2.9 (cross hatched)
Scale and Storage area	0.7 (brown)
Stripped area	9.8 (tan)
Plant site/part mined	36.0 (yellow)
Partially backfilled & sloped	2.5 (/////)

Mining continued on areas previously disturbed and has reached the setback limits on the east and south sides. The mined floor is being deepened and 4.9 acres was part mined north of the road. Slope reconstruction will continue this year along the south side using fines material from the processing plant.

9. Approximately 6.8 acres of new area was stripped and partially mined this year north of the mining area. Topsoil was placed along the west side of the striped area.

10. No reclamation is required at this time. Sloping will continue next year.

13. Backfilling and sloping continues on a 2.5 acre area along the south side.

19. The bond was evaluated in 9/9/2021 by the Division and increased to \$106,200.00 that is adequate to cover the reclamation costs for the disturbance at the mine.