



TRAPPER MINING INC.

July 11, 2023

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Second Quarter 2023 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on June 13th, 15th, 20th, 21st and 29th.

The following maintenance items were noted:


- Far East Buzzard #1 sediment marker needs to be replaced.
- West Pyeatt #2 sediment marker needs to be replaced.
- Middle Pyeatt #1 needs to be cleaned.
- East Pyeatt #1, #2 & #3 sediment markers may need to be replaced (could be under water).
- Jeffway #1 sediment marker and identification sign need to be replaced.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Second Quarter 2023
Impoundment Inspection - Pond Capacity Data


Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	70.00	0.98	0.42
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	20.00	0.20	0.79
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.
Second Quarter 2023
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	40.00	1.34	2.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	20.00	0.51	2.05
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	15.00	0.30	1.70
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Josiah Kuball

SIGNATURE: 

DRAINAGE: FAR EAST BUZZARD

DATE OF INSPECTION: 6-13-2022

POND IDENTIFICATION	Far East Buzzard #1			
Approximate water level:	10%			
Sediment level (% total storage):	10%			
Outflow (cfs):	0			
Sediment marker (install or replace)	Replace			
Identification sign (install or replace)	replace			
EROSIONAL:				
Rills and/or gullies on downstream face.	NO			
Rills and/or gullies on upstream face.	NO			
Inadequate vegetation.	NO			
Outlet channel erosion.	NO			
Burrows.	NO			
Erosion of toe.	NO			
Water impounded against downstream toe.	NO			
Other.	-			
STRUCTURAL:				
Differential settling.	NO			
Cracks, slides, or scarps.	NO			
Seepage (specify location, color, value).	NO			
Defective spillways.	NO			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	NO			
Dewatering device clogged.	NO			
Cracking or crushing of pipes.	NO			
Other.	-			
COMMENTS:				

~~NO issue~~ Sediment marker needs to be replaced



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Josiah Kuball

SIGNATURE: 

DRAINAGE: COYOTE

DATE OF INSPECTION: 6-13-23

POND IDENTIFICATION	Coyote #1		
Approximate water level:	58%		
Sediment level (% total storage):	Medium		
Outflow (cfs):	21		
Sediment marker (install or replace)	N/A		
Identification sign (install or replace)	In place		
EROSIONAL:			
Rills and/or gullies on downstream face.	NO		
Rills and/or gullies on upstream face.	NO		
Inadequate vegetation.	NO		
Outlet channel erosion.	NO		
Burrows.	NO		
Erosion of toe.	NO		
Water impounded against downstream toe.	NO		
Other.	—		
STRUCTURAL:			
Differential settling.	NO		
Cracks, slides, or scarps.	NO		
Seepage (specify location, color, value).	NO		
Defective spillways.	NO		
Other.	—		
APPURTENANT STRUCTURES:			
Defective spillways.	NO		
Dewatering device clogged.	NO		
Cracking or crushing of pipes.	NO		
Other.	—		

COMMENTS:


Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

No issues noted.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: NO NAME

DATE OF INSPECTION: 6/20/2023

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	55%	100%
Sediment level (% total storage):	10%	15%	25%
Outflow (cfs):	LCFS	0	LCFS
Sediment marker (install or replace)	Underwater	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:	#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%. #5: 60% level = top of post - 4.5'. Some vegetation in outflow of #4 & #5, not hindering water flow.		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: **JOHNSON GULCH**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 6/20/2023

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	25%	35%	35%	20%	25%
Outflow (cfs):	41 CFS	41 CFS	41 CFS	41 CFS	41 CFS
Sediment marker (install or replace)	In Place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no	no	no
Rills and/or gullies on upstream face.	no	no	no	no	no
Inadequate vegetation.	no	no	no	no	no
Outlet channel erosion.	no	no	no	no	no
Burrows.	no	no	no	no	no
Erosion of toe.	no	no	no	no	no
Water impounded against downstream toe.	no	no	no	no	no
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	no	no	no	no	no
Cracks, slides, or scarps.	no	no	no	no	no
Seepage (specify location, color, value).	no	no	no	no	no
Defective spillways.	no	no	no	no	no
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no	no	no
Dewatering device clogged.	no	no	no	no	no
Cracking or crushing of pipes.	no	no	no	no	no
Other.	-	-	-	-	-

COMMENTS:

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

Some vegetation is in outflow #7, 8 & 9. Water flow is not hindered.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Josiah Kuball

SIGNATURE: 

DRAINAGE: WEST PYEATT

DATE OF INSPECTION: 6-15-23

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2	
Approximate water level:	80%	60%	
Sediment level (% total storage):	45%	45%	
Outflow (cfs):	0 cfs	0 cfs	
Sediment marker (install or replace)	In place	Replace	
Identification sign (install or replace)	In place	In place	
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	
Rills and/or gullies on upstream face.	NO	NO	
Inadequate vegetation.	NO	NO	
Outlet channel erosion.	NO	NO	
Burrows.	NO	NO	
Erosion of toe.	NO	NO	
Water impounded against downstream toe.	NO	NO	
Other.	-	-	
STRUCTURAL:			
Differential settling.	NO	NO	
Cracks, slides, or scarps.	NO	NO	
Seepage (specify location, color, value).	NO	NO	
Defective spillways.	NO	NO	
Other.	-	-	
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	
Dewatering device clogged.	NO	NO	
Cracking or crushing of pipes.	NO	NO	
Other.	-	-	

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Josiah Kuball

SIGNATURE: 

DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION: 6-24-23

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	30%	10%	25%
Sediment level (% total storage):	70%	75%	40%
Outflow (cfs):	0 FPS	0 FPS	0 FPS
Sediment marker (install or replace)	In place	In place	In place
Identification sign (install or replace)	In place	In place	In place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.			
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.			
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.			
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Josiah Kuball

SIGNATURE: 

DRAINAGE: EAST PYEATT

DATE OF INSPECTION: 6-15-23

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	20%	20%	30%
Outflow (cfs):	6103	4153	4153
Sediment marker (install or replace)	Replace	Replace	Replace
Identification sign (install or replace)	Replace	Replace	Replace
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:			

Sediment markers may be under water.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

SIGNATURE: 

DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 6/29/23

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	4072	9510
Sediment level (% total storage):	10/100%	1910
Outflow (cfs):	070	070
Sediment marker (install or replace)	install in place	install in place
Identification sign (install or replace)	install in place	install in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

SIGNATURE: 

DRAINAGE: SAGE GULCH

DATE OF INSPECTION: 6/29/23

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	0%	0%
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	None	None
Rills and/or gullies on upstream face.	None	None
Inadequate vegetation.	None	None
Outlet channel erosion.	None	None
Burrows.	None	None
Erosion of toe.	None	None
Water impounded against downstream toe.	None	None
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	None	None
Cracks, slides, or scarp.	None	None
Seepage (specify location, color, value).	None	None
Defective spillways.	None	None
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	None	None
Dewatering device clogged.	None	None
Cracking or crushing of pipes.	None	None
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: OAK GULCH

DATE OF INSPECTION: 6/21/2023

POND IDENTIFICATION	Oak #1	Oak #2		
Approximate water level:	50%	0%		
Sediment level (% total storage):	45%	5%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	In Place	In Place		
Identification sign (install or replace)	In Place	In Place		
EROSIONAL:				
Rills and/or gullies on downstream face.	NO	NO		
Rills and/or gullies on upstream face.	NO	NO		
Inadequate vegetation.	NO	NO		
Outlet channel erosion.	NO	NO		
Burrows.	NO	NO		
Erosion of toe.	NO	NO		
Water impounded against downstream toe.	NO	NO		
Other.	-	-		
STRUCTURAL:				
Differential settling.	NO	NO		
Cracks, slides, or scarps.	NO	NO		
Seepage (specify location, color, value).	NO	NO		
Defective spillways.	NO	NO		
Other.	-	-		
APPURTENANT STRUCTURES:				
Defective spillways.	NO	NO		
Dewatering device clogged.	NO	NO		
Cracking or crushing of pipes.	NO	NO		
Other.	-	-		

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

DRAINAGE: WEST FLUME

SIGNATURE: 


DATE OF INSPECTION: 6/27/23

POND IDENTIFICATION	West Flume #1
Approximate water level:	0% ↓
Sediment level (% total storage):	0% ↓
Outflow (cfs):	0 ↓
Sediment marker (install or replace)	in place ↓
Identification sign (install or replace)	in place ↓
EROSIONAL:	
Rills and/or gullies on downstream face.	No ↓
Rills and/or gullies on upstream face.	No ↓
Inadequate vegetation.	No ↓
Outlet channel erosion.	No ↓
Burrows.	No ↓
Erosion of toe.	No ↓
Water impounded against downstream toe.	No ↓
Other.	N/A ↓
STRUCTURAL:	
Differential settling.	No ↓
Cracks, slides, or scarps.	No ↓
Seepage (specify location, color, value).	No ↓
Defective spillways.	No ↓
Other.	N/A ↓
APPURTENANT STRUCTURES:	
Defective spillways.	No ↓
Dewatering device clogged.	No ↓
Cracking or crushing of pipes.	No ↓
Other.	N/A ↓
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: MIDDLE FLUME

DATE OF INSPECTION: 6/20/2023

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3	
Approximate water level:	75%	98%	
Sediment level (% total storage):	40%	40%	
Outflow (cfs):	0	0	
Sediment marker (install or replace)	In Place	Underwater	
Identification sign (install or replace)	In Place	In Place	
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	
Rills and/or gullies on upstream face.	NO	NO	
Inadequate vegetation.	NO	NO	
Outlet channel erosion.	NO	NO	
Burrows.	NO	NO	
Erosion of toe.	NO	NO	
Water impounded against downstream toe.	NO	NO	
Other.	-	-	
STRUCTURAL:			
Differential settling.	NO	NO	
Cracks, slides, or scarps.	NO	NO	
Seepage (specify location, color, value).	NO	NO	
Defective spillways.	NO	NO	
Other.	-	-	
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	
Dewatering device clogged.	NO	NO	
Cracking or crushing of pipes.	NO	NO	
Other.	-	-	

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: EAST MIDDLE FLUME

SIGNATURE:

DATE OF INSPECTION:

6/20/2023

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	100%
Sediment level (% total storage):	20%
Outflow (cfs):	< 1 CFS
Sediment marker (install or replace)	Underwater
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-

COMMENTS:



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: EAST FLUME

DATE OF INSPECTION: 6/20/2023

POND IDENTIFICATION	East Flume #1
Approximate water level:	55%
Sediment level (% total storage):	15%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: UTE GULCH

DATE OF INSPECTION: *6/20/2023*

POND IDENTIFICATION	Ute #1			
Approximate water level:	<i>95%</i>			
Sediment level (% total storage):	<i>45%</i>			
Outflow (cfs):	<i>0</i>			
Sediment marker (install or replace)	<i>In Place</i>			
Identification sign (install or replace)	<i>In Place</i>			
EROSIONAL:				
Rills and/or gullies on downstream face.	<i>no</i>			
Rills and/or gullies on upstream face.	<i>no</i>			
Inadequate vegetation.	<i>no</i>			
Outlet channel erosion.	<i>no</i>			
Burrows.	<i>no</i>			
Erosion of toe.	<i>no</i>			
Water impounded against downstream toe.	<i>no</i>			
Other.	<i>-</i>			
STRUCTURAL:				
Differential settling.	<i>no</i>			
Cracks, slides, or scarps.	<i>no</i>			
Seepage (specify location, color, value).	<i>no</i>			
Defective spillways.	<i>no</i>			
Other.	<i>-</i>			
APPURTENANT STRUCTURES:				
Defective spillways.	<i>no</i>			
Dewatering device clogged.	<i>no</i>			
Cracking or crushing of pipes.	<i>no</i>			
Other.	<i>-</i>			

Same vegetation in outlet, not hindering water flow.

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: HORSE GULCH

DATE OF INSPECTION: 6/21/2023

POND IDENTIFICATION	Horse #1			
Approximate water level:	80' L			
Sediment level (% total storage):	55.1			
Outflow (cfs):	0			
Sediment marker (install or replace)	Underwater			
Identification sign (install or replace)	In Place			
EROSIONAL:				
Rills and/or gullies on downstream face.	NO			
Rills and/or gullies on upstream face.	NO			
Inadequate vegetation.	NO			
Outlet channel erosion.	NO			
Burrows.	NO			
Erosion of toe.	NO			
Water impounded against downstream toe.	NO			
Other.	-			
STRUCTURAL:				
Differential settling.	NO			
Cracks, slides, or scarps.	NO			
Seepage (specify location, color, value).	NO			
Defective spillways.	NO			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	NO			
Dewatering device clogged.	NO			
Cracking or crushing of pipes.	NO			
Other.	-			
COMMENTS:				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: WEST HORSE GULCH

DATE OF INSPECTION: 6/21/2023

POND IDENTIFICATION	West Horse #1
Approximate water level:	85%
Sediment level (% total storage):	20%
Outflow (cfs):	0
Sediment marker (install or replace)	Under water
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: DEAL GULCH

DATE OF INSPECTION: 6/21/2023

POND IDENTIFICATION	Deal #1	Deal #2		
Approximate water level:	100%	40%		
Sediment level (% total storage):	15%	0%		
Outflow (cfs):	41 CFS	0		
Sediment marker (install or replace)	Underwater	In Place		
Identification sign (install or replace)	In place	In place		
EROSIONAL:				
Rills and/or gullies on downstream face.	no	no		
Rills and/or gullies on upstream face.	no	no		
Inadequate vegetation.	no	no		
Outlet channel erosion.	no	no		
Burrows.	no	no		
Erosion of toe.	no	no		
Water impounded against downstream toe.	no	no		
Other.	-	-		
STRUCTURAL:				
Differential settling.	no	no		
Cracks, slides, or scarps.	no	no		
Seepage (specify location, color, value).	no	no		
Defective spillways.	no	no		
Other.	-	-		
APPURTENANT STRUCTURES:				
Defective spillways.	no	no		
Dewatering device clogged.	no	no		
Cracking or crushing of pipes.	no	no		
Other.	-	-		

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: DEACON

DATE OF INSPECTION: 6/21/2023

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins Jessica Koball

SIGNATURE: [Signature]

DRAINAGE: **JEFFWAY** DATE OF INSPECTION: 6-29-23

POND IDENTIFICATION	Jeffway #1		
Approximate water level:	50%		
Sediment level (% total storage):	0		
Outflow (cfs):	0		
Sediment marker (install or replace)	Replace		
Identification sign (install or replace)	Replace		
EROSIONAL:			
Rills and/or gullies on downstream face.	NP		
Rills and/or gullies on upstream face.			
Inadequate vegetation.			
Outlet channel erosion.			
Burrows.			
Erosion of toe.			
Water impounded against downstream toe.			
Other.			
STRUCTURAL:			
Differential settling.	NP		
Cracks, slides, or scarps.			
Seepage (specify location, color, value).			
Defective spillways.			
Other.			
APPURTENANT STRUCTURES:			
Defective spillways.	NP		
Dewatering device clogged.			
Cracking or crushing of pipes.			
Other.			

COMMENTS:



TRAPPER MINING INC.

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: 6/20/2023

POND IDENTIFICATION	Impoundment H
Approximate water level:	80%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	to Place
Identification sign (install or replace)	to Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 6/26/2023

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	70%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

