




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Climax Mine	MINE/PROSPECTING ID#: M-1977-493	MINERAL: Molybdenum	COUNTY: Lake, Summit
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: July 12, 2023	INSP. TIME: 11:00
OPERATOR: Climax Molybdenum Company	OPERATOR REPRESENTATIVE: Megan Graham	TYPE OF OPERATION: 112d-3 - Designated Mining Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$91,011,850.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla Todd Jesse	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: July 14, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Climax representative, Megan Graham, guided DRMS for the inspection.

The inspection was focused on the following areas:

- East Interceptor
- West Interceptor
- Chalk Mountain Interceptor

East Interceptor

The East Interceptor conveys non-contact water to Clinton Reservoir. The interceptor consists of open channel, culverts and pipeline. Portions of the open channel were observed. No problems were noted with the East Interceptor.



East Interceptor

West Interceptor

The West Interceptor captures non-contact water from the north side of the tailings ponds and conveys the freshwater east, around the mine area and into Tenmile Creek, just upstream of the PWDTP. The West Interceptor consists of open channel, pipeline and culverts. For the most part, much of the West Interceptor flows along the road on the north side of the tailings area, so much of the interceptor was observed during this inspection. No problems with the West Interceptor were noted.



West Interceptor

Chalk Mountain Interceptor

The Chalk Mountain Interceptor captures non-contact water from the Chalk Mountain drainages and conveys the freshwater to Chalk Mountain Reservoir. The Chalk Mountain Interceptor consists of open channel and culverts. The interceptor channel was observed along most of its reach, from the access road. No problems were noted with the Chalk Mountain Interceptor.



Chalk Mountain Interceptor

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.

Inspection Contact Address

Eric Detmer
Climax Molybdenum Company
Highway 91, Fremont Pass
Climax, CO 80429