



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

July 19, 2023

Jodi Schreiber
Fremont Paving and Redi Mix, Inc.
839 MacKenzie Avenue
Canon City, CO 81212

**Re: Letter of Groundwater Monitoring Compliance, Pueblo East Groundwater Monitoring;
Pueblo East, Permit No. M-2000-041**

Dear Ms. Schreiber:

On July 3, 2023, the Division of Reclamation, Mining and Safety (Division) received your annual groundwater level monitoring data for 2021 to 2022. Upon review of the data the Division has the following comments:

1. The Depth to Water (DTW) entry for Monitoring Hole #2 on June 9, 2020 was entered as 114.0 ft from the top of casing (toc). Please indicate whether or not this was an error, and if so, adjust the spreadsheet entry.
2. The Elevation (ft AMSL) entry for Monitoring Hole #3 on July 20, 2020 shows a formula error. Please correct this entry on the spreadsheet.
3. The Depth to Water (DTW) entry for Monitoring Hole #3 on November 10, 2022 was entered as 197 ft from the top of casing (toc). Please indicate whether or not this was an error, and if so, adjust the spreadsheet entry.

Please respond to these comments by **August 2, 2023**.

Please note that groundwater level monitoring data are to be submitted yearly with the annual report, map and fee in accordance with the commitment made in AM-1.

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **720-836-0967**, or by email at amber.michels@state.co.us.

Sincerely,



Amber Michels
Environmental Protection Specialist

cc: Jared Ebert, DRMS

ec: Jodi Schreiber, Fremont Paving and Redi Mix, Inc., jodi@arycorp.com