

Reilley - DNR, Robin <robin.reilley@state.co.us>

2023 August Inspection Reports Partial: Williams Fork, Yoast SEneca IIW

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Fri, Aug 18, 2023 at 9:50 AM To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Please find the August 2023 partial inspections for Williams Fork, Yoast and Seneca IIW.

I'm available to discuss any questions or concerns

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 ext 8105 | F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

3 attachments

Ins_Partial_Seneca_2023_08August.pdf 1283K

Ins_Partial_Yoast_2023_08August.pdf 2372K

INSP_Partial_WF_2023_08August.pdf



PERMIT INFORMATION

Permit Number: C-1981-044 **Mine Name:** Williams Fork Mines **Operator:** Moffat County Mining, LLC

Operator Address: MS Miranda Kawcak 29515 Routt County Road #27 Oak Creek, CO 80467 County: Moffat Operation Type: Underground Permit Status: Active Ownership: Private

Operator Representative Present:

Miranda Kawcak

Operator Representative Signature: (Field Issuance Only)

This report was issued electronically from the Divisions' Denver Office.

INSPECTION INFORMATION

Inspection Start Date: 17. August, 2023 Inspection Start Time: 13:00 Inspection End Date: 17 August, 2023 Inspection End Time: 14:00 p.m.			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Partly Cloudy
Joint Inspection Agency:		Joint Inspection Contacts:	
None			
Post Inspection Agency:		Post Inspection Contacts:	
None			
Inspector(s):	Inspector's Signature: Signature Date:		
Robin Reilley, GISP	Bobin Beilley		
			18 August 2023

Inspection Topic Summary N=Not Inspected V=Violation Issued NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable N=Not Inspected R=Comments Noted V=Violation Issued		
R - Air Resource Protection	R - Roads	
N - Availability of Records	R - Reclamation Success	
R - Backfill & Grading	R - Revegetation	
NA - Excess Spoil and Dev. Waste	Y - Subsidence	
NA - Explosives	Y - Slides and Other Damage	
R - Fish & Wildlife	Y - Support Facilities On-site	
R - Hydrologic Balance	R - Signs and Markers	
R - Gen. Compliance With Mine Plan	NA - Support Facilities Not On-site	
N - Other	NA - Special Categories Of Mining	
NA - Processing Waste	R - Topsoil	

COMMENTS

This was a partial inspection of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The inspection was conducted and the report and photos prepared by me, Robin Reilley of the DRMS. Miranda Kawcak, mine representative, was present throughout the inspection. The temperature hovered around 90 degrees Fahrenheit. There air was calm and conditions were partly cloudy.

PERMITTING ACTIONS in PROGRESS: RN8

MAINTENANCE ITEMS Rills and gullies at the slope below the No 5 Portal to the 5A-P1 Pond require grading.

MAINTENANCE ITEMS ADDRESSED

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

Reclamation is progressing as permitted. Facilities have been removed throughout the site and reclamation has been completed. Topsoil below the 5A Portal was placed and will be seeded within the next weeks. Hydroseeding the portal slope was completed, and a few grasses appeared to be emerging.

SIGNS and MARKERS – Rule 4.02

 \circ $\;$ Ponds were staked and topsoil piles were marked.

ROADS – Rule 4.03

Construction 4.03.1(3) *I* 4.03.2(3); *Drainage* 4.03.1(4) *I* 4.03.2(4); *Surfacing and Maintenance* 4.03.1(5) *and* (6) *I* 4.03.2(5) *and* (6); *Reclamation* 4.03.1(7) *I* 4.03.2(7)

• The Haul Road at the entrance off State Highway 13 was in good repair and the site was accessible.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 1

HYDROLOGIC BALANCE – Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Drainage- Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18

None of the ponds held water.

Pond 5A-P1 at 5A at portal was dry at the time of inspection. Pond slopes and bottom are vegetated.
Sloped area to the pond had been topsoiled but not seeded. The slope has rills and gullies the length of the slope to the pond.

TOPSOIL – RULE 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4

 \circ No instability was noted on the piles at the time of inspection and piles were marked with sakes.

SLIDES and OTHER DAMAGE- Rule 4.12

No recent slumping was observed.

BACKFILL and GRADING - RULE 4.14

- Backfilling and grading has been completed.
- Rills and gullies on the slope below the 5A Portal to 5A-P1 Pond will be graded and repaired.

REVEGETATION - Rule 4.15

General Requirements 4.15.1; Use of Species 4.15.2, Grazing 4.15.5

- With the eception of the slope to the 5A-P1 Pond, reclamation, (topsoil and seeding) has been completed as has hydroseeding at the 5A Portal.
- Cropland areas along the Williams Fork River were dry stubble having been harvested earlier in the season. Alfalfa was present in the field.

FISH and WILDLIFE–RULE 4.18

Wildlife observed comprised a group of pronghorn and a variety of raptors.

INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5 Inspections 5.02; Availability of Records

Permit documents were not inspected as this was a partial inspection.

DOCUMENTS RECEIVED

None

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 1

PHOTOGRAPHS



Photo 1: Hydroseeded slope at o the 5A Portal.



Photo 2: Overview of the cropland area along the Willliams Fork River looking northwest from above.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 1



Photo 3: Cropland area along the Williams Fork River, looking north.