

Zuber - DNR, Rob <rob.zuber@state.co.us>

# Keenesburg inspection report

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us> To: "Moline, Ben" <ben.moline@molsoncoors.com> Mon, Sep 11, 2023 at 12:54 PM

Ben -

Please see the attached report from my inspection on Friday morning.

Rob

Rob Zuber, P.E. **Environmental Protection Specialist** Active Mines Regulatory Program



I am working remotely and can be reached by cell at 720.601.2276.

Physical Address:

1313 Sherman Street, Room 215 Denver, CO 80203 Mailing Address: Division of Reclamation, Mining and Safety, Room 215 1001 East 62nd Avenue Denver, CO 80216

rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC\_C1981028\_RDZ\_09112023.pdf 1381K



# **PERMIT INFORMATION**

Permit Number: C-1981-028 Mine Name: Keenesburg Strip Mine Operator: Coors Energy Company Operator Address: Mr. Ben Moline	County: Weld Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private			
P.O. Box 4030	Operator Representative Present:			
Golden, CO 80402	<b>F</b>			
00.000	None			
Operator Representative Signature: (Field Issuance Only)				

# **INSPECTION INFORMATION**

Inspection Start Date: September Inspection End Date: September Inspection End Time: 10:45			Inspection Type: Coal Compl Inspection Reason: Normal Is Weather: Clear	*
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Robert Zuber, P.E.	Phot D. Zh			
				9/11/2023

### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection NA - Roads

**R** - Availability of Records **R** - Reclamation Success

NA - Backfill & Grading R - Revegetation

NA - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives Y - Slides and Other Damage Y - Fish & Wildlife NA - Support Facilities On-site

 ${f R}\,$  - Hydrologic Balance  ${f R}\,$  - Signs and Markers

R - Gen. Compliance With Mine Plan
 N - Other
 NA - Support Facilities Not On-site
 NA - Special Categories Of Mining

NA - Processing Waste NA - Topsoil

## **COMMENTS**

A complete inspection was conducted by Rob Zuber of DRMS on September 8, 2023. No Coors Energy Company (CEC) representative was present at the inspection.

The site is in Permanent Cessation. Reclamation activities were completed in the fall of 2020. However, due to poor success in some areas, Coors Energy reclaimed these areas a second time in spring 2022.

The weather was clear and warm (approximately 80 degrees F). The ground was dry.

### AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records were lacking several current documents. These include:

- The permit document
- The findings from RN-08
- The insurance document
- The bond document
- The Annual Reclamation Report for 2022
- Quarterly reports for ponds.

The operator needs to update the records in the near future. This should be done prior to October 1, 2023.

Please see the list of records below. (Note that some records have been updated recently, including DRMS reports and pest and weed reports.)

### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Sediment Pond 2 and the Dugout Pond contained little to no water (thick vegetation obscures the bottoms). They were not discharging during the inspection. There were no signs that either pond had discharged recently. No problems were observed.

### GENERAL MINE PLAN COMPLIANCE:

The northern boundary of the site was observed, and no signs of pollutant loading from the mine site, or any other problems, were seen.

### RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion problems were seen onsite. Bare spots were seen in some areas. The steep area east of the Dugout Pond was stable.

#### **REVEGETATION – Rule 4.15**

Vegetative Cover; Timing:

Poor vegetation growth was seen in some areas, including Areas 36, 37, and 38 (the reclaimed soil piles south of the facilities) and the reclaimed roads. In these areas, many sunflowers were seen, but grasses have not emerged well. In Area 25, tall grasses were seen (including, smooth brome and sand bluestem) in addition to the many sunflowers.

As in past inspections, the older reclamation near the southwest corner of the site contains thick grass cover.

### SIGNS AND MARKERS – Rule 4.02:

The entrance sign was seen beside the locked gate near the Dugout Pond, and it is in compliance.

#### **DOCUMENTS RECEIVED - none**

**OTHER (SPECIFY)** - none

# ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

# **PHOTOGRAPHS**



**Entrance sign (recently installed at this location)** 



**Area below Sediment Pond 2** 



Reclaimed road near Sediment Pond 2



Area 37 – poor grass growth



Area 44 – better grass growth than many of the other newly reclaimed areas



Area 31 – excellent grass growth



Area 38 – poor grass growth

## **AVAILABILITY OF RECORDS**

PERMIT RECORDS		HYDROLOGIC RECORDS			
DRMS Permit	Exp. 11/3/2021	NPDES Permit	NA		
Permit Application w/Revisions	yes	NPDES Records	NA		
Findings Document	RN-07 (Aug 2017)	Stormwater Management Plan	NA		
Insurance Certificate	Exp. 11/1/2022	SPCC Plan	Updated 2012		
Bond Document	\$1,197,459	MSHA Pond Inspections	NA		
	(2016, not current)	•			
Phased Bond Release	SL-11		NA		
Documents/Findings	(12/1/2022)	State Engineer's Pond Inspection			
Air Emission Permits	123008803	Quarterly Pond Inspections	10/11/2022		
County Special Use Permits	Weld #1160, #386	Annual Hydrology Reports	2021		
UG Mining Landowner Notification	NA	<ul> <li>Ground Water Monitoring</li> </ul>	yes		
Subsidence Monitoring Reports	NA	<ul> <li>Surface Water Monitoring</li> </ul>	NA		
Subsidence Monitoring Data	NA	<ul> <li>Spring &amp; Seep Monitoring</li> </ul>	NA		
Rill & Gully Survey	NA	<ul> <li>Mine Water Discharge Monitoring</li> </ul>	NA		
Vegetation Monitoring Data	2021 ARR	<ul> <li>Mine Inflow Study</li> </ul>	NA		
Specific Variance Approvals	NA	<ul> <li>Water Consumption Records</li> </ul>	NA		
Annual Reclamation Reports	2021	Well Permits	*2		
Midterm Review Documents	MT-07 (May 2019)				
DRMS/OSM Inspection	Through				
Reports/Enforcement Actions (3 Yrs)	July 2023	BLASTING RECORDS			
Transfers/Succession of Operator	NA	Blasting Publication	NA		
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA		
Reclamation Cost Estimate	*1	ATFE Explosives Permit	NA *3		
CERTIFICATIONS		Blasting Variances	NA		
Pond Certifications	Yes	Pre-Blast Surveys	NA		
Annual Certifications for Large	NA	1 10 Black Galveyo	107		
Impoundments					
Fill Certifications for Excess Spoil or	NA	ADDITIONAL RECORDS (specify)			
Underground Development Waste		( )			
<ul> <li>Quarterly Inspections</li> </ul>	NA	Pest and Weed report	6/30/2023		
Compaction Testing	NA				
Final Certification	NA				
Coal Processing Waste Banks	NA				
Haul Road Certifications	NA				
Access Road Certifications	NA				
COMMENTS:					
*1 RCE is \$818,406 (SL-11)					
*2 Domestic use well and fire protection well (048289f, 24650f)					
*3 No explosives used since 1995.					
			1		