



TRAPPER MINING INC.

October 3, 2023

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Third Quarter 2023 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on August 29th, September 11th, 12th, 13th, 16th and 28th.

The following maintenance items were noted:

- East Pyeatt #1, #2 & #3 sediment markers need to be replaced.


Trapper will address these maintenance items in a timely matter.

Middle Pyeatt #1 and East Pyeatt #1 were being cleaned at the time of the inspection.


Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Third Quarter 2023
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	10.00	0.14	1.26
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	2.00	0.02	0.97
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

Trapper Mining Inc.
Third Quarter 2023
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	40.00	1.34	2.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	20.00	0.51	2.05
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	15.00	0.30	1.70
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: FAR EAST BUZZARD

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/14/2023

POND IDENTIFICATION	Far East Buzzard #1		
Approximate water level:	<i>Dry</i>		
Sediment level (% total storage):	<i>10%</i>		
Outflow (cfs):	<i>0</i>		
Sediment marker (install or replace)	<i>In Place</i>		
Identification sign (install or replace)	<i>In Place</i>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<i>no</i>		
Rills and/or gullies on upstream face.	<i>no</i>		
Inadequate vegetation.	<i>no</i>		
Outlet channel erosion.	<i>no</i>		
Burrows.	<i>minimal</i>		
Erosion of toe.	<i>no</i>		
Water impounded against downstream toe.	<i>no</i>		
Other.	<i>_</i>		
STRUCTURAL:			
Differential settling.	<i>no</i>		
Cracks, slides, or scarps.	<i>no</i>		
Seepage (specify location, color, value).	<i>no</i>		
Defective spillways.	<i>no</i>		
Other.	<i>_</i>		
APPURTENANT STRUCTURES:			
Defective spillways.	<i>no</i>		
Dewatering device clogged.	<i>no</i>		
Cracking or crushing of pipes.	<i>no</i>		
Other.	<i>_</i>		
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **COYOTE**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 8/29/2023

POND IDENTIFICATION	Coyote #1	
Approximate water level:	30 1/4	
Sediment level (% total storage):	Minimal	
Outflow (cfs):	0	
Sediment marker (install or replace)	N/A	
Identification sign (install or replace)	In Place	
EROSIONAL:		
Rills and/or gullies on downstream face.	no	
Rills and/or gullies on upstream face.	no	
Inadequate vegetation.	no	
Outlet channel erosion.	no	
Burrows.	no	
Erosion of toe.	no	
Water impounded against downstream toe.	no	
Other.	-	
STRUCTURAL:		
Differential settling.	no	
Cracks, slides, or scarps.	no	
Seepage (specify location, color, value).	no	
Defective spillways.	no	
Other.	-	
APPURTENANT STRUCTURES:		
Defective spillways.	no	
Dewatering device clogged.	no	
Cracking or crushing of pipes.	no	
Other.	-	
COMMENTS:		

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: NO NAME

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/11/2023

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	10%	15%	25%
Outflow (cfs):	4CFS	4CFS	20CFS
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	no	no	no
Rills and/or gullies on upstream face.	no	no	no
Inadequate vegetation.	no	no	no
Outlet channel erosion.	no	no	no
Burrows.	no	no	no
Erosion of toe.	no	no	no
Water impounded against downstream toe.	no	no	no
Other.	-	-	-
STRUCTURAL:			
Differential settling.	no	no	no
Cracks, slides, or scarps.	no	no	no
Seepage (specify location, color, value).	no	no	no
Defective spillways.	no	no	no
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	no	no	no
Dewatering device clogged.	no	no	no
Cracking or crushing of pipes.	no	no	no
Other.	-	-	-
COMMENTS:			

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
#5: 60% level = top of post - 4.5'.
*Some vegetation in outflows of #4 & #5,
no hindering waterflow.*



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: JOHNSON GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: *9/11/2023*

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	<i>100%</i>	<i>100%</i>	<i>100%</i>	<i>100%</i>	<i>100%</i>
Sediment level (% total storage):	<i>25%</i>	<i>35%</i>	<i>35%</i>	<i>20%</i>	<i>25%</i>
Outflow (cfs):	<i>21 CFS</i>	<i>21 CFS</i>	<i>21 CFS</i>	<i>21 CFS</i>	<i>21 CFS</i>
Sediment marker (install or replace)	<i>In Place</i>	<i>Underwater</i>	<i>Underwater</i>	<i>Underwater</i>	<i>Underwater</i>
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Rills and/or gullies on upstream face.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Inadequate vegetation.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Outlet channel erosion.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Burrows.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Erosion of toe.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Water impounded against downstream toe.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>
STRUCTURAL:					
Differential settling.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Cracks, slides, or scarps.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Seepage (specify location, color, value).	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Defective spillways.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>
APPURTENANT STRUCTURES:					
Defective spillways.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Dewatering device clogged.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Cracking or crushing of pipes.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

Some vegetation is in outflows #7, 8 & 9, not hindering water flow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

DRAINAGE: WEST PYEATT

SIGNATURE: Tim CumminsDATE OF INSPECTION: 9/16/23 Sat.

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	0 % dry	0 % dry
Sediment level (% total storage):	45 %	45 %
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	—	—
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

DRAINAGE: MIDDLE PYEATT

SIGNATURE: *Jim Cummins*
 DATE OF INSPECTION: 9/16/23 Sat

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	(2.) 100%	0% dry	0% dry
Sediment level (% total storage):	100%	25%	40%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.			
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.			
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.			

COMMENTS: (1.) Large rock in flume of Middle Pyeatt #3 - Removed rock
 (2.) Middle Pyeatt #1 in process of being de-silted.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

DRAINAGE: EAST PYEATT

SIGNATURE: *Tim Cummins*

DATE OF INSPECTION: 9/16/23 Sat

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	* 20%	20%	30%
Outflow (cfs):	< 1 cfs	< 1	< 1
Sediment marker (install or replace)	Needs replaced	Needs replaced	Needs replaced
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	—	—	—
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	—	—	—

COMMENTS: * East Pyeatt #1 in process of being de-silted



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Andrew P. McCaslin
Josiah Kutball

DRAINAGE: **GROUSE GULCH**

SIGNATURE: *John J. McFarland*
DATE OF INSPECTION: 9/28/2023

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	50%	10%
Sediment level (% total storage):	40%	15%
Outflow (cfs):	0%	0%
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Andrew P. McCaskin
Josiah Kuball

DRAINAGE: **SAGE GULCH**

SIGNATURE: 
DATE OF INSPECTION: 7/28/2023


POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	070	070
Sediment level (% total storage):	1070	1070
Outflow (cfs):	070	070
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

DRAINAGE: OAK GULCH

SIGNATURE: 

DATE OF INSPECTION: 7/23/2023

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	55%	0%
Sediment level (% total storage):	45%	10%
Outflow (cfs):	0%	0%
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

DRAINAGE: WEST FLUME

SIGNATURE: 

DATE OF INSPECTION: 9/28/2023

POND IDENTIFICATION	West Flume #1
Approximate water level:	0% 1070
Sediment level (% total storage):	0%
Outflow (cfs):	in place
Sediment marker (install or replace)	in place
Identification sign (install or replace)	
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	N/A
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	N/A
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	N/A
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: MIDDLE FLUME

SIGNATURE: 

DATE OF INSPECTION: 9/12/2023

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	4'5"	80%
Sediment level (% total storage):	40%	40%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Underwater
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: EAST MIDDLE FLUME

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	100%
Sediment level (% total storage):	20%
Outflow (cfs):	21 CFS
Sediment marker (install or replace)	Underwater
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: EAST FLUME

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	East Flume #1
Approximate water level:	DRY
Sediment level (% total storage):	15%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: UTE GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	Ute #1		
Approximate water level:	50%		
Sediment level (% total storage):	45%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: HORSE GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/12/2023

POND IDENTIFICATION	Horse #1			
Approximate water level:	70%			
Sediment level (% total storage):	55%			
Outflow (cfs):	0.1			
Sediment marker (install or replace)	Underwater			
Identification sign (install or replace)	In Place			
EROSIONAL:				
Rills and/or gullies on downstream face.	no			
Rills and/or gullies on upstream face.	no			
Inadequate vegetation.	no			
Outlet channel erosion.	no			
Burrows.	no			
Erosion of toe.	no			
Water impounded against downstream toe.	no			
Other.	-			
STRUCTURAL:				
Differential settling.	no			
Cracks, slides, or scarps.	no			
Seepage (specify location, color, value).	no			
Defective spillways.	no			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	no			
Dewatering device clogged.	no			
Cracking or crushing of pipes.	ny			
Other.	-			
COMMENTS:				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: WEST HORSE GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/12/2023

POND IDENTIFICATION	West Horse #1
Approximate water level:	15'
Sediment level (% total storage):	20%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: DEAL GULCH

DATE OF INSPECTION: 8/9/2023

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	98%	By minimal
Sediment level (% total storage):	15%	
Outflow (cfs):	0	0
Sediment marker (install or replace)	Underwater	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: JEFFWAY

SIGNATURE:

DATE OF INSPECTION:

9/13/2023

POND IDENTIFICATION	Jeffway #1
Approximate water level:	10'1"
Sediment level (% total storage):	0
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	Impoundment H		
Approximate water level:	15'1.		
Sediment level (% total storage):	5'1.		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 9/13/2023

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	95%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

