




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Henderson Mine	MINE/PROSPECTING ID#: M-1977-342	MINERAL: Molybdenum	COUNTY: Clear Creek, Grand
INSPECTION TYPE: Monitoring	WEATHER: Cloudy	INSP. DATE: October 12, 2023	INSP. TIME: 09:00
OPERATOR: Climax Molybdenum Company	OPERATOR REPRESENTATIVE: Geoff Niggeler	TYPE OF OPERATION: 112d-3 - Designated Mining Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$135,204,778.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Brock Bowles	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 17, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Brock Bowles of the Division of Reclamation, Mining and Safety (Division). Geoff Niggeler of Climax Molybdenum- Henderson Operations (Henderson) was present for the inspection. The Henderson Mill is located 15 miles south of Parshall in Grand County. This site is a 112d-3 Designated Mining Operation (DMO) permitted for 11,877.5 acres. At the time of the inspection, it was cool, cloudy with scattered snow showers.

This inspection consisted of a debrief of the past year's events, a discussion of next years and future projects and records check.

The current Environmental Protection Plan (EPP) for the Mine and Mill was approved by the Division under TR34. Table 4-1 within the EPP lists the other permit and licenses required to operator the Mine and Mill. A records check was conducted by the Division during the inspection. All permits and licenses listed in the table were current and available for review by the Division.

During the past calendar year, AM8 was submitted and approved. AM8 added 224.0 acres of affected area below 1-Dam and 3-Dam to provide additional acreage for the water management and monitoring program. Drilling the monitoring wells in the additional area had not begun at the time of this inspection. The monitoring wells are expected to be installed soon and data collected.

The vegetation plots on the face of 1-Dam are partially installed and will be seeded within the next month.

During the next calendar year, Henderson expects to:

- Submit a TR for 3-Dam buttress project.
- Submit a TR to move the cyclone discharge further up Ute Creek
- Close 4 shaft
- Revegetate some of the drill pads on Red Mountain

No photos were taken for this inspection.

PHOTOGRAPHS

Inspection Contact Address

Geoff Niggeler
Climax Molybdenum Company
19302 County Rd. #3
Parshall, CO 80468