



Bowie No. 1 Mine  
PO Box 1488  
Paonia, CO. 81428  
(970)986-6236

October 18, 2023

Mr. Rob Zuber  
Department of Natural Resources  
Division of Reclamation, Mining and Safety  
1313 Sherman Street, Room 215  
Denver, CO. 80203

RE: Bowie Resources LLC  
Bowie No. 1 Mine  
DRMS Permit No. C-1981-038  
Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 3<sup>rd</sup> quarter of 2023.  
If you have any questions or concerns regarding this submittal, contact me at (970)986-6236.

Sincerely;

Basil R. Bear  
Mine Manager

Bowie Resources LLC  
Bowie #1 Mine  
Sedimentation Pond

**Loadout Pond**

Quarter:	3
Inspection Date:	28-Sep-23
Inspected By:	brb

Primary Elevation:	5724.00
Cleanout Elevation:	5721.00


Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	5720.00'
Outflow (C.F.S.)	0.00

<b>Features:</b>		Comments
Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other		

<b>Structural:</b>	
Differential Settling	No
Cracks or Slides	No
Seepage	No
Other	

<b>Appurtenant Structures</b>	
Defective Spillway	No
Dewatering Device Clogged	No
Faulty Gates, Baffles, Pumps	No
Other	Gate Closed

<b>Additional Comments</b>



Bowie Resources LLC  
Bowie #1 Mine  
Sedimentation Pond

**Highway Pond**

Quarter:	3
Inspection Date:	28-Sep-23
Inspected By:	brb

Primary Elevation:	5734.00
Cleanout Elevation:	5734.00

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	5727.00'
Outflow (C.F.S.)	0.00

**Features:**

		Comments
Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other		


**Structural:**

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

**Appurtenant Structures**

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other		

**Additional Comments**

Bowie Resources LLC  
Bowie #1 Mine  
Sedimentation Pond

**WM WS-1 Pond**

Quarter:	3
Inspection Date:	28-Sep-23
Inspected By:	brb

Primary Elevation:	7,064.50
Cleanout Elevation:	7,064.50

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	7061.00'
Outflow (C.F.S.)	0.00

**Features:**

		Comments
Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other	No	


**Structural:**

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

**Appurtenant Structures**

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Closed	

**Additional Comments**

Bowie Resources LLC  
Bowie #1 Mine  
Sedimentation Pond

**WM WS-2 Pond**

Quarter:	3
Inspection Date:	28-Sep-23
Inspected By:	brb

Primary Elevation:	7095.80
Cleanout Elevation:	7095.80

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	7091.00'
Outflow (C.F.S.)	0.00

**Features:**

Comments

Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other	No	

**Structural:**

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

**Appurtenant Structures**

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Open	

**Additional Comments**

