

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/P	PROSPECTING ID#:	MINERAL:	COUNTY:	
Blue Creek Staging Area	M-2021-	016	Aggregate	Gunnison	
INSPECTION TYPE:	INSPEC	CTOR(S):	INSP. DATE:	INSP. TIME:	
Monitoring	Dustin C	zapla	October 10, 2023	14:30	
OPERATOR:	OPERA	TOR REPRESENTATIVE:	TYPE OF OPERA	TYPE OF OPERATION:	
Cornerstone Materials LLC			111 - Construction b	y Goverment Agency	
REASON FOR INSPECTION:	BOND (CALCULATION TYPE:	BOND AMOUNT:		
Normal I&E Program	Complet	e Bond	\$49,825.00		
DATE OF COMPLAINT:	POST II	NSP. CONTACTS:	JOINT INSP. AGENCY:		
NA	None		None		
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:		
Clear	De		October 19, 2023		

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE N	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION <u>N</u>	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report in order to illustrate some of the conditions observed.

The Blue Creek Staging Area is located approximately three miles west of Blue Mesa Reservoir and accessed from Hwy 50. The site is a 111 operation that includes a total of 19.93 permitted acres. The Division currently holds a financial warranty amount of \$49,825.00 for this site. Mining has not yet commenced so this amount is considered adequate at this time.

The permit was issued May 27, 2021. Mining has not yet commenced at the site. Material generated from the Hwy 50 construction project is stockpiled at the site. Prior to stockpiling imported material, topsoil was stripped from the area and pushed into berms around the perimeter of the disturbed area.

The affected area was marked by fencing that was clearly visible and adequate to delineate the permit area boundary.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.



Inspection Contact Address

Zane Luttrell Cornerstone Materials LLC 23625 Uncompanyer Road Montrose, CO 81403