

STATE OF  
COLORADO

Reilley - DNR, Robin &lt;robin.reilley@state.co.us&gt;

---

**Review\_2023 Q3, Q4 Sed Pond and Q4 HG Fill Reports Trapper**

1 message

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Thu, Oct 19, 2023 at 1:20 PM

To: Tonia Perkins &lt;tonia.perkins@trappermine.com&gt;, Robin Reilley - DNR &lt;robin.reilley@state.co.us&gt;

Dear Ms. Perkins,

Thank you for the timely submission of the above referenced reports. DRMS has no question or concerns at this time.

Sincerely

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural ResourcesP [303.866.3567](tel:303.866.3567) ext 8105 |F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>

---

**3 attachments****SedPondReview\_2023\_Q3\_Trapper.pdf**

255K

**HorseFill\_Review\_2023\_Q4.pdf**

233K

**SedPondReview\_2023\_Q4\_Trapper.pdf**

267K



19 October 2023

Tonia Perkins  
Trapper Mine, Inc.  
P.O. Box 187  
Craig, Colorado 81626

**RE: Trapper Mining Inc., Permit; C1981010**  
**Review: Horse Gulch Fill Monitoring 2023 Q4**

Dear Ms. Perkins:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in general compliance with the following CDRMS regulations:

*4.09.1(11)(a) Inspected at least quarterly by a registered engineer, or other qualified professional specialist in construction of earth and rockfill embankments under the direction of a qualified engineer throughout the construction.*

The certified report covers the fourth quarter monitoring period from October 2023 through December 2023, and the inspection was conducted by yourself, a certified engineer on 17 October 2023.

*4.09.1(11)(b) Provide to the Division a certified report within 2 weeks after each inspection that the fill has been constructed as specified in the design approved by the Division. The report shall include a description of any appearances of instability, structural weakness, and other hazardous conditions.*

The Division received the report via electronic transmission on 18 October 2023. Portions of the fill inspected comprised the southeast and northeast sides of the fill, as these areas are not fully bond released. No instability, structural weakness, or other hazardous conditions were noted during this inspection of the fill. The area where cracks were detected on the top south portion of the fill during the first quarter of 2013 was inspected and no additional cracking was observed.

No organic material removal was conducted. All fill has been placed and compacted.



DRMS has no questions at this time. Thank you for the timely submission of the 2023 Q4 fill report.

Best Regards

A handwritten signature in blue ink that reads "Robin Reilley". The signature is written in a cursive, flowing style.

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II  
[Robin.reilley@state.co.us](mailto:Robin.reilley@state.co.us)