ANNUAL & QUARTERLY POND INSPECTION

COORS ENERGY COMPANY

KEENESBURG MINE SITE

| KEENESBURG MINE SITE | | | |
|---------------------------------------|---------------------|-----------------|--|
| Date of Inspection 8/9/2 | 2023 | | |
| | | | |
| Pond Identification: | Sediment Pond #2 | Dugout | |
| Type of Pond | Sediment | Permanent | |
| Capacities | 15.6 acre ft. | 19.7 acre ft. | |
| | 5,097,925 gals. | 6,437,760 gals. | |
| Approx. water level - (% of capacity) | None | None | |
| Sediment level - | | | |
| (% of capacity) | 0 | 0 | |
| Out flow | | | |
| Erosional Features | yes - no | yes - no | |
| Rills / Gullies | No | No | |
| Inadequate | | | |
| Vegetation | No | No | |
| Outlet Channel | | | |
| Erosion | No | No | |
| Burrows | No | No | |
| Other | NA | NA | |
| Structural Issues | | | |
| Settlement | No | No | |
| Cracks/Slides | No | No | |
| Seepage | None | None | |
| Spillways (cond.) | Good | Good | |
| Other | NA | NA | |
| | | | |

Signature (P.E. or Authorized Inspector): Ben Moline, PE

Moline