

Zuber - DNR, Rob <rob.zuber@state.co.us>

## **Bowie #1 inspection report**

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>

Thu, Nov 16, 2023 at 7:42 AM

To: Basil Bear <basilbear@wolverinefuels.com>, Tamme Bishop <tammekb@gmail.com>

Good morning. Brock flew over the Bowie sites on Tuesday and took some photos. Attached is the related report.

Rob

Rob Zuber, P.E. **Environmental Protection Specialist** Active Mines Regulatory Program



I am working remotely and can be reached by cell at 720.601.2276.

Physical Address:

1313 Sherman Street, Room 215 Denver, CO 80203 Mailing Address: Division of Reclamation, Mining and Safety, Room 215 1001 East 62nd Avenue Denver, CO 80216 rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC\_C1981038\_RDZ\_11152023.pdf 1373K



# **PERMIT INFORMATION**

<b></b>				
Permit Number: C-1981-038 Mine Name: Bowie No. 1 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil R Bear	County: Delta Operation Type: Underground Permit Status: Active Ownership: Private			
P.O. Box 1488	<b>Operator Representative Present:</b>			
Paonia, CO 81428				
,	None			
Operator Representative Signature: (Field Issuance Only)				

# **INSPECTION INFORMATION**

Inspection Start Date: November 14, 2023 Inspection Start Time: 10:00 (estimated) Inspection End Date: November 14, 2023 Inspection End Time: 10:30 (estimated)			Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear		
Joint Inspection Agency:		Joint	<b>Joint Inspection Contacts:</b>		
None					
Post Inspection Agency:		Post	Post Inspection Contacts:		
None					
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:	
Robert Zuber, P.E.	Phot	D	21		
Brock Bowles				11/15/2023	

### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection N - Roads

N - Availability of Records R - Reclamation Success

NA - Backfill & Grading N - Revegetation

N - Excess Spoil and Dev. Waste Y - Subsidence

NA - Explosives Y - Slides and Other Damage
N - Fish & Wildlife NA - Support Facilities On-site

 $\boldsymbol{R}\,$  - Hydrologic Balance  $\,$   $\,$   $\,$   $\boldsymbol{N}\,$  - Signs and Markers

Y - Gen. Compliance With Mine Plan

R - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

N - Processing Waste N - Topsoil

## **COMMENTS**

On November 14, 2023, Brock Bowles of DRMS took aerial photographs of the mine. The weather was clear. Rob Zuber of DRMS reviewed the photos on November 15 and 16, 2023.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the West Mine were completely dry. No problems were seen with the embankments or other portions of these ponds. The ponds at the coal storage by the highway and the loadout also appeared to have no problems.

## RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Reclaimed Ponds 1-4 southeast of the East Mine were inspected. The West Mine was also inspected, especially the area near the creek and the road at the north end. No erosion or other problems were identified.

#### OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No erosion or other problems were identified at the loadout. This includes the eastern portion, along the UPRR tracks and adjacent to Grange Road and Black Bridge Road.

#### **DOCUMENTS RECEIVED - none**

OTHER (SPECIFY) - none

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 1

# ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

## **PHOTOGRAPHS**



Loadout with pond (blue circle) and coal storage by highway (yellow circle)

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 1



"Y" northeast of loadout



Tracks south of "Y"



East mine with Ponds 1 – 4 indicated with arrows



West Mine with ponds indicated with arrows

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 1