

Chase Hiatt chiatt@archrsc.com Phone: 970.929.2226

Mountain Coal Company, LLC A subsidiary of Arch Resources, Inc. West Elk Mine 5174 Highway 133 Somerset, CO 81434

January 17, 2024

Mr. Leigh D. Simmons Colorado Division of Reclamation, Mining and Safety Office of Mined Land Reclamation 1313 Sherman Street, Room 215 Denver, Colorado 80203

Re: Mountain Coal Company, LLC, West Elk Mine; Permit No. C-1980-007; Quarterly Summary of Subsidence Observations; 4th Quarter 2023

Dear Mr. Simmons:

Mountain Coal Company, LLC (MCC) began longwall mining the E-Seam in December 2008. MCC has completed longwall mining of longwall panels LWE1 through LWE8, LWE14, LWE15 and LWSS1 through 4. MCC is currently in a Longwall move in which we're moving to LWE12.

There were no stock ponds within the angle-of-draw of the mined area of LWE15 during this quarter. A portion of LWE15 was within a mile of Monument Dam, monitoring showed no movement. October and November inspections were done but winter weather and ground conditions did not permit inspections for December of this quarter. All inspections will continue when weather and ground conditions allow. Routine inspection reports for Monument Dam, Forest Service Roads and Stock Ponds are included with this letter report.

Please don't hesitate to contact me should you have questions regarding this submittal. I can be reached by phone at (970) 929-2226.

Sincerely,

hoo that

Chase Hiatt Mine Engineer Tech

cc: W. Norris J. Wilczek

Date: 10/20 Time: 12:000 Name of Inspector: C. Hiatt Current Panel Being Mined: LWEII0 □ Weekly Inspection (Monthly Inspection Yes No X Is mining within 1 mile of Monument Dam? Are there visible surface cracks on the dam? X If yes, indicate length and size of crack. Is there evidence of subsided areas on or around the dam? Ņ If yes, indicate where and degree. Are there bulges on the dam? M If yes, indicate where and degree. _____. Are there signs of seeps on the dam? If yes, indicate where and estimated flow. Are there any other potentially damaging features on the dam? If yes, describe. Are there any recent evidences of slope failure on the landside south of the dam (perform visual inspection and data analysis of inclinometers)? If yes, describe.

Notes:

e that Signature of Inspector

Inspections are performed under the direction of Mike Peacock, P.E.

If cracks or other potentially damaging features occur, notify Mike Peacock or Kathy Welt immediately.

(W:MCC-Engineering/ENV PERMITTING/REG AGENCIES/CDRMS/Monument Dam/Monument Dam Inspection Procedure/Monument Dam Inspection Form)

Stock Pond Inspection Form

Date: 11/21/23 Time: 11:30 ann Name of Inspector: C. Hight Current Panel and XC Being Mined: LWE/6 Stock Pond(s) Being Inspected: Dryfork Deep Creek

Yes No

M

Is the stock pond within twice the projected angle of draw of subsidence? If yes, which pond(s):

Are there visible surface cracks in or near the stock pond? If yes, describe (location, width, length, etc.):

Is there any evidence of potential subsidence induced water loss? If yes, describe:

Is there water in the pond? If yes, describe:

Is mitigation needed? If yes, list suggestions:

Notes:

Signature of Inspector

* If any potential subsidence induced features are observed that could cause harm to the pond, notify Jessica Wilczek immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Inspection-Survey_USFS Ponds & Rds\Ponds\Stock Pond Inspection Form)

Stock Pond **Inspection Form**

Date: 12/15/23							
1 me: 7:31 am							
Name of Inspector: Chase Hiatt							
Current Panel and XC Being Mined: LwElle							
Stock	Pond(s	s) Being Inspected:					
Yes	No						
	X	Is the stock pond within twice the projected angle of draw of subsidence? If yes, which pond(s):					
		Are there visible surface cracks in or near the stock pond? If yes, describe (location, width, length, etc.):					
		Is there any evidence of potential subsidence induced water loss? If yes, describe:					
		Is there water in the pond? If yes, describe:					
		Is mitigation needed? If yes, list suggestions:					
Notes:	No	acsess due to weather					

Signature of Inspector: Un that

* If any potential subsidence induced features are observed that could cause harm to the pond, notify Jessica Wilczek immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Inspection-Survey USFS Ponds & Rds\Ponds\Stock Pond Inspection Form)

Date: 11/21/23 Time: 12:00p Name of Inspector: Chase Hiatt Current Panel Being Mined: LWE15 D Weekly Inspection & Monthly Inspection

Yes	No	
X		Is mining within 1 mile of Monument Dam?
	X	Are there visible surface cracks on the dam? If yes, indicate length and size of crack
	×	Is there evidence of subsided areas on or around the dam? If yes, indicate where and degree
	X	Are there bulges on the dam? If yes, indicate where and degree
	X	Are there signs of seeps on the dam? If yes, indicate where and estimated flow
	X	Are there any other potentially damaging features on the dam? If yes, describe
	X	Are there any recent evidences of slope failure on the landside south of the dam (perform visual inspection and data analysis of inclinometers)? If yes, describe

Notes:

2

-72# Signature of Inspector:

Inspections are performed under the direction of Mike Peacock, P.E.

If cracks or other potentially damaging features occur, notify Mike Peacock or Kathy Welt immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Monument Dam\Monument Dam Inspection Procedure\Monument Dam Inspection Form)

Date: 10/20/23 Time: 11:45am Name of Inspector: Chase Hiatt Current Panel Being Mined: CwE15 D Weekly Inspection & Monthly Inspection

Yes	No	
X		Is mining within 1 mile of Monument Dam?
D	×	Are there visible surface cracks on the dam? If yes, indicate length and size of crack
	×	Is there evidence of subsided areas on or around the dam? If yes, indicate where and degree
	×	Are there bulges on the dam? If yes, indicate where and degree
٥	×	Are there signs of seeps on the dam? If yes, indicate where and estimated flow
	×	Are there any other potentially damaging features on the dam? If yes, describe
	×	Are there any recent evidences of slope failure on the landside south of the dam (perform visual inspection and data analysis of inclinometers)? If yes, describe

Notes:

2

Signature of Inspector:

Inspections are performed under the direction of Mike Peacock, P.E.

If cracks or other potentially damaging features occur, notify Mike Peacock or Kathy Welt immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Monument Dam\Monument Dam Inspection Procedure\Monument Dam Inspection Form)

Date: 12/15/23Time: 8:00 km Name of Inspector: Chase Hight Current Panel Being Mined: LwE15 \Box Weekly Inspection Monthly Inspection

Yes	No □	Is mining within 1 mile of Monument Dam?
	X	Are there visible surface cracks on the dam? If yes, indicate length and size of crack.
	×	Is there evidence of subsided areas on or around the dam? If yes, indicate where and degree.
	X	Are there bulges on the dam? If yes, indicate where and degree
	×	Are there signs of seeps on the dam? If yes, indicate where and estimated flow
	X	Are there any other potentially damaging features on the dam? If yes, describe
	×	Are there any recent evidences of slope failure on the landside south of the dam (perform visual inspection and data analysis of inclinometers)? If yes, describe
Notes	Con Wear	Idn't Preform 3:te Inspections Because of thes
Signat	ture of I	nspector: Chase That

Inspections are performed under the direction of Mike Peacock, P.E.

3

If cracks or other potentially damaging features occur, notify Mike Peacock or Kathy Welt immediately.

(W:MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Monument Dam\Monument Dam Inspection Procedure\Monument Dam Inspection Form)

Forest Service Roads Inspection Form

Date: 10/20/23 Time: 11:30 and Name of Inspector: C. Hinth Current Panel and XC Being Mined: LWE 16 Road(s) Being Inspected: Dryfork Deep Creek

Yes No

 \square

X

Π

Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):

Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):

Π

Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:

Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:

Is mitigation needed? If yes, list suggestions:

Notes:

have that Signature of Inspector:

* If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.

Forest Service Roads Inspection Form

Date: 11/21/23 Time: 11:00 am Name of Inspector: C. Hiatt Current Panel and XC Being Mined: LWEIG Road(s) Being Inspected: Dry Fork Deep Creek Yes No Is the Forest Service road within the projected angle of draw of \square subsidence? If yes, which road(s): Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.): \mathbf{X} Π Is there any recent evidence of potential subsidence induced slope failure? If yes, describe: X Π Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe: X Is mitigation needed? If yes, list suggestions: Notes:

Signature of Inspector:

* If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.

Forest Service Roads Inspection Form				
Date: 12/15/23 Time: 7:3/am Name of Inspector: Chase Hiett Current Panel and XC Being Mined: Lw E14 Road(s) Being Inspected:				
Yes	No			
	K	Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):		
		Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):		
		Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:		
		Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:		
		Is mitigation needed? If yes, list suggestions:		
Notes: Wo acsess due to weather				

Signature of Inspector: Chose that

* If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Inspection-Survey USFS Ponds & Rds\Roads\forest service roads inspection form)