

STATE OF  
COLORADO

Reilley - DNR, Robin &lt;robin.reilley@state.co.us&gt;

---

## Review: Sediment Pond Reports 2023 Q4

1 message

---

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Thu, Feb 1, 2024 at 7:30 AM

To: "Kawcak, Miranda" &lt;MKawcak@peabodyenergy.com&gt;, Robin Reilley - DNR &lt;robin.reilley@state.co.us&gt;

Good Morning Miranda,

Thank you for the timely submission of the 2023 Q4 Sediment Pond Reports for the Williams Fork, Yoast and Seneca IIW mine sites. Please find DRMS's reviews of Sediment Pond reports.

The Division has no concerns at this time.

Thank you

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) ext 8105 |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>

---

### 3 attachments

**Review\_Ponds\_2023\_Q4\_Yoast.pdf**

236K

**Review\_Ponds\_2023\_Q4\_Seneca.pdf**

243K

**Review\_Ponds\_2023\_Q4\_WF.pdf**

250K



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

31 January 2024

Miranda Kawcak  
Environmental Manger  
Peabody, Colorado Operations

**Re: Williams Fork (Permit No. C1981044)**  
**Review Impoundment Report 2023 Q4**

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2023 quarter four refuse pile and pond reports for the Williams Fork Mine. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 23 January 2024. Sediment pond inspections were conducted by Miranda Kawcak of Peabody, Colorado Operations on 15 November 2023. The report complies with the applicable sections of Rule 4.05.9.

The following ponds were dry at the time of inspection:

<i>Pond</i>	<i>Pond</i>	<i>Pond</i>	<i>Pond</i>
5-P1	5-P2	5-P3	9A-P2
9-P1	9-P2	9-P2	9-P3
9-P4	9-P5	9-P6	9-P7
9-P8	HR-P1A	HR-P1B	SH-P1
SH-P2	5-A		

The Spoil Spring (1SP) was not flowing at the time of inspection. Sediment levels were acceptable, and no maintenance items were identified.

The following structures have achieved bond release:

- Ponds 9A-P1, 9A-3 and 9A-P4,

Sincerely,

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II  
[Robin.reilley@state.co.us](mailto:Robin.reilley@state.co.us)

