

Reilley - DNR, Robin <robin.reilley@state.co.us>

DERMS Feb 2024 Inspection Reports Yoast and Seneca

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Tue, Feb 6, 2024 at 1:42 PM

To: "Kawcak, Miranda" < MKawcak@peabodyenergy.com>, Robin Reilley - DNR < robin.reilley@state.co.us>

Good Afternoon Miranda,

Attached please find the Division's February 2024 inspection reports for the Yoast and Seneca IIW sites. The inspections comprised partials.

Kind Regards

Robin Reilley, M.S. GISP Environmental Protection Specialist II




P 303.866.3567 ext 8105 | F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

2 attachments



Ins_Partial_Seneca_2024_02Feb.pdf 431K



PERMIT INFORMATION

Mine Name: Yoast Mine Operation Type: Surface

Operator Address:

Permit Status: Permanent Cessation
Ownership: Private

Seneca Property LLC

Ownership: Private

29515 Routt County Road No. 27

Oak Creek, CO 80467

Ms Miranda Kawcak

Operator Representative Present:

No, as the site was inaccessible.

Operator Representative Signature: (Field Issuance Only)

This report was issued electronically from the Divisions' Denver Office.

INSPECTION INFORMATION

Inspection Start Date: 6 Feb 2024
Inspection Start Time: 10:15 a.m.
Inspection End Date: 6 Feb 2024
Inspection End Time: 10:15 a.m.

Joint Inspection Agency:

None

Post Inspection Agency:

None

Inspection Type: Coal Partial Inspection
Inspection Reason: Normal I&E Program
Weather: Partly Cloudy

Foot Inspection Contacts:

Post Inspection Contacts:

Inspector(s): Inspector's Signature:

Robin Reilley, M.S. GISP

Robin Leilley

Signature Date:

6 February 2024

Inspection Topic Summary NOTE: Y=Inspected N=Not Inspected V=Violation Issued NA=Not Applica	
 N - Air Resource Protection N - Availability of Records NA - Backfill & Grading NA - Excess Spoil and Dev. Waste NA - Explosives N - Fish & Wildlife N - Hydrologic Balance Y - Gen. Compliance With Mine Plan NA - Other NA - Processing Waste 	 R - Roads N - Reclamation Success N - Revegetation N - Subsidence N - Slides and Other Damage NA - Support Facilities on site Y - Signs and Markers NA - Support Facilities Not on site NA - Special Categories Of Mining N - Topsoil

COMMENTS

This was a Partial inspection of the Yoast Mine, C1994082, operated by Seneca Property LLC. The inspection was conducted, and the report prepared by me, Robin Reilley of the DRMS. The weather was partly cloudy and calm with temperatures hovering around 35 degrees Fahrenheit. The ground was snow covered and the site was inaccessible.

PERMITTING ACTIONS:

NA

OUTSTANDING MAINTENANCE ITEMS

NA

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

Reclamation has been completed at the site with the exception of the hillside above Pond 12.

SIGNS and MARKERS – Rule 4.02

Sign at entrance was in place.

ROADS Rule 4.03

Construction 4.03.1(3), 4.03.2(3); Drainage 4.03.1(4), 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) 4.03.2(5) and (6).

The site was inaccessible as roads into the site are not plowed in the winter.

INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5

Inspections 5.02; Availability of Records

As this was a partial inspection, records were not checked.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of Complete Inspections this Fiscal Year: 3

DOCUMENTS RECEIVED

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Photo 1: Yoast sign at entrance.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of <u>Complete</u> Inspections this Fiscal Year: 3