

STATE OF
COLORADO

Lennberg - DNR, Patrick <patrick.lennberg@state.co.us>

Additional Information Required, 4Q2023 GW/SW Monitoring Report, Cresson Project, M1980-244

Joshua Adams <Joshua.Adams@newmont.com>

Mon, Feb 19, 2024 at 3:25 PM

To: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>, Elliott Russell - DNR <elliott.russell@state.co.us>

Cc: Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Antonio Matarrese <Antonio.Matarrese@newmont.com>

Patrick,

Attached is photo documentation of our inspection of the GV-06 location today. No flowing water was observed. We will plan on inspecting the location on Mondays moving forward; I will let you know if the schedule changes. Let me know if you have questions and thank you.

**Newmont**
CRIPPLE CREEK & VICTOR**Josh Adams, PG**

SITE WATER COORDINATOR

Cripple Creek & Victor Gold Mining Company

Victor, CO 80860

O 719.851.4260

M 719.323.0438

NEWMONT.COM

[Quoted text hidden]

**Photographic Log - GV06 021924.pdf**
1229K

PHOTOGRAPHIC LOG



Photograph 1: View of the GV-06 surface water monitoring location, looking south

PHOTOGRAPHIC LOG



Photograph 2: View of the GV-06 surface water monitoring location, looking southwest

PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location after layer of ice was removed. No flowing water was observed at the location.

PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location showing the depth of the snow.

PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location. No flowing water was observed at the location.