

STATE OF  
COLORADO

Lennberg - DNR, Patrick &lt;patrick.lennberg@state.co.us&gt;

---

## Additional Information Required, 4Q2023 GW/SW Monitoring Report, Cresson Project, M1980-244

---

Joshua Adams &lt;Joshua.Adams@newmont.com&gt;

Mon, Feb 26, 2024 at 3:03 PM

To: "Elliott Russell (DNR-DRMS)" &lt;elliott.russell@state.co.us&gt;

Cc: "Lennberg - DNR, Patrick" &lt;patrick.lennberg@state.co.us&gt;, Katie Blake &lt;Katie.Blake@newmont.com&gt;, Johnna Gonzalez &lt;Johnna.Gonzalez@newmont.com&gt;, Antonio Matarrese &lt;Antonio.Matarrese@newmont.com&gt;

Elliott/Patrick,

See the attached photo documentation of our inspection of the GV-06 location today. No flowing water was observed. Pictures were taken at approximately 13:20 MST. Temperature registered at the thermometer in the truck was 38°F. At the Rigi station, the temperature at 13:30 was 35.66°F, with approximately 30-mph winds and gusts up to 40mph. Temperature with the wind chill is estimated to be about 23°F. Please let me know if you have questions. Thank you!

**Newmont**  
CRIPPLE CREEK & VICTOR**Josh Adams, PG**

SITE WATER COORDINATOR

Cripple Creek &amp; Victor Gold Mining Company

Victor, CO 80860

O 719.851.4260

M 719.323.0438

NEWMONT.COM

[Quoted text hidden]

**Photographic Log - GV06 022624.pdf**

409K

## PHOTOGRAPHIC LOG



Photograph 1: View of the GV-06 surface water monitoring location, looking south. Photo taken 2/19/2024.

## PHOTOGRAPHIC LOG



Photograph 2: View of the GV-06 surface water monitoring location, looking southeast. Photo taken 2/26/2024 at approximately 13:20 MST.

## PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location after layer of ice was removed. No flowing water was observed at the location. Photo taken 2/26/2024 at approximately 13:20 MST.

## PHOTOGRAPHIC LOG



Photograph 4: View of the GV-06 surface water monitoring location showing the depth of the snow, looking west. Photo taken 2/26/2024 at approximately 13:20 MST.