

STATE OF
COLORADO

Lennberg - DNR, Patrick <patrick.lennberg@state.co.us>

Additional Information Required, 4Q2023 GW/SW Monitoring Report, Cresson Project, M1980-244

Joshua Adams <Joshua.Adams@newmont.com>

Mon, Mar 4, 2024 at 2:18 PM

To: "Elliott Russell (DNR-DRMS)" <elliott.russell@state.co.us>

Cc: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>, Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Antonio Matarrese <Antonio.Matarrese@newmont.com>

Elliott/Patrick,

See the attached photo documentation of our inspection of the GV-06 location today. No flowing water was observed. Pictures were taken at approximately 07:30 MST. Temperature registered at the thermometer in the truck was 18°F. At the Rigi station, the temperature at 07:30 was 19.4°F, with approximately 7-mph winds. Please let me know if you have questions. Thank you!

**Newmont**
CRIPPLE CREEK & VICTOR**Josh Adams, PG**

SITE WATER COORDINATOR

Cripple Creek & Victor Gold Mining Company

Victor, CO 80860

O 719.851.4260

M 719.323.0438

NEWMONT.COM

[Quoted text hidden]

**Photographic Log - GV06 030424.pdf**
1074K

PHOTOGRAPHIC LOG



Photograph 1: View of the GV-06 surface water monitoring location, looking west. Photo taken 3/4/2024 at approximately 07:30 MST.

PHOTOGRAPHIC LOG



Photograph 2: View of the GV-06 surface water monitoring location, looking southeast. Photo taken 3/4/2024 at approximately 07:30 MST.

PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/4/2024 at approximately 07:30 MST.

PHOTOGRAPHIC LOG



Photograph 4: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/4/2024 at approximately 07:30 MST.