



STATE OF
COLORADO

Lennberg - DNR, Patrick <patrick.lennberg@state.co.us>

Additional Information Required, 4Q2023 GW/SW Monitoring Report, Cresson Project, M1980-244

Joshua Adams <Joshua.Adams@newmont.com>

Tue, Mar 12, 2024 at 6:37 AM

To: "Elliott Russell (DNR-DRMS)" <elliott.russell@state.co.us>

Cc: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>, Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Antonio Matarrese <Antonio.Matarrese@newmont.com>

Elliott/Patrick,

See the attached photo documentation of our inspection of the GV-06 location yesterday. No flowing water was observed. Pictures were taken at approximately 09:30 MDT. Temperature registered at the thermometer in the truck was 34°F. At the Rigi station, the temperature at 09:30 was 31.6°F, with approximately 7.5-mph winds. Please let me know if you have questions. Thank you!

[Quoted text hidden]



Photographic Log - GV06 031124.pdf

254K

PHOTOGRAPHIC LOG



Photograph 1: View of the GV-06 surface water monitoring location, looking south. Photo taken 3/11/2024 at approximately 09:30 MDT.

PHOTOGRAPHIC LOG



Photograph 2: View of the GV-06 surface water monitoring location, looking southeast. Photo taken 3/11/2024 at approximately 09:30 MDT.

PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/11/2024 at approximately 09:30 MDT.

PHOTOGRAPHIC LOG



Photograph 4: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/11/2024 at approximately 09:30 MDT.