

STATE OF  
COLORADO

Lennberg - DNR, Patrick &lt;patrick.lennberg@state.co.us&gt;

## Additional Surface Water Monitoring Locations Required Letter, Grassy Valley, M1980-244

Joshua Adams &lt;Joshua.Adams@newmont.com&gt;

Mon, Apr 1, 2024 at 4:33 PM

To: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>, Norma Townley <Norma.Townley2@newmont.com>, Katie Blake <Katie.Blake@newmont.com>, Johnna Gonzalez <Johnna.Gonzalez@newmont.com>, Antonio Matarrese <Antonio.Matarrese@newmont.com>

Cc: Elliott Russell - DNR <elliott.russell@state.co.us>, Amy Eschberger - DNR <amy.eschberger@state.co.us>, Nikie Gagnon - DNR <nikie.gagnon@state.co.us>, Hunter Ridley - DNR <hunter.ridley@state.co.us>, "West - DNR, Lucas" <lucas.west@state.co.us>

Elliott/Patrick,

See the attached photo documentation of our inspection of the GV-06 location and the suspected location of GV-4.5 Spring and GV-05 last Thursday (3/28). No flowing water was observed any of the locations. Pictures were taken at approximately 15:45-15:55 MDT. Temperature registered at the thermometer in the truck was 37°F. At the Rigi station, the temperature at 15:45 was 32°F, with approximately 12-mph winds.

Based on historic coordinates of the GV-04 location, it appears that the GV-06 and GV-04 locations have been combined. There was minimal lateral distance between the GV-06 location and the coordinates for the GV-04 location, so they were assumed to be the same.

GV-4.5 Spring and GV-05 are located on private property so only a visual observation from the county road could be conducted. Based on field observations, it's anticipated that water was not flowing at these locations at the time of inspection. CC&V is currently reviewing historical records to identify if an easement is in place that would allow access to these locations.

Please let me know if you have questions. Thank you!

**Newmont**  
CRIPPLE CREEK & VICTOR**Josh Adams, PG**

SITE WATER COORDINATOR

Cripple Creek &amp; Victor Gold Mining Company

Victor, CO 80860

4/2/24, 4:52 AM

State.co.us Executive Branch Mail - Additional Surface Water Monitoring Locations Required Letter, Grassy Valley, M1980-244

[O 719.851.4260](tel:719.851.4260)

[M 719.323.0438](tel:719.323.0438)

[NEWMONT.COM](https://www.newmont.com)

[Quoted text hidden]



**Photographic Log - GV06 032824\_V2.pdf**  
1696K

## PHOTOGRAPHIC LOG



Photograph 1: View of the GV-06 surface water monitoring location, looking south. Photo taken 3/28/2024 at approximately 15:45 MDT.

## PHOTOGRAPHIC LOG



Photograph 2: View of the GV-06 surface water monitoring location, looking southwest. Photo taken 3/28/2024 at approximately 15:45 MDT.

## PHOTOGRAPHIC LOG



Photograph 3: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/28/2024 at approximately 15:45 MDT.

## PHOTOGRAPHIC LOG



Photograph 4: View of the GV-06 surface water monitoring location after snow and ice was removed. No flowing water was observed at the location. Photo taken 3/28/2024 at approximately 15:45 MDT.

## PHOTOGRAPHIC LOG



Photograph 5: View of the suspected location of the GV-4.5 Spring looking south. Photo taken 3/28/2024 at approximately 15:55 MDT.

## PHOTOGRAPHIC LOG



Photograph 6: View of the suspected location of the GV-4.5 Spring looking southwest showing snow accumulation. Photo taken 3/28/2024 at approximately 15:55 MDT.

## PHOTOGRAPHIC LOG



Photograph 7: View of the suspected location of the GV-05 looking south showing snow accumulation.  
Photo taken 3/28/2024 at approximately 15:55 MDT.