

Mountain Coal Company, LLC- West Elk Mine
Quarterly Self Pond Inspection Report
Somerset, Colorado Gunnison County

3/13/2024
Date

1st 2024
Quarter/Year
C. Hiatt
Inspector

Pond ID	FW-1	SG-1	RPE West	RPE East	NSSA	Deepwell
Pond Type	Fresh Water	Sediment	Sediment	Sediment	Sediment	Fault Water
Sediment Level %	N/A	5%	<15%	<30%	0	<5%
Water Level (Approx.)	80%	75%	10%	80%	0	50%
Discharge? Y/N	N/A	N	N	N	N	N

Features	Problems?*		Maintenance?*		Repairs?*		Comments
* If Yes add comments							
Erosional:	Yes	No	Yes	No	Yes	No	
Rill & Gullies		X		X		X	
Inadequate Vegetation		X		X		X	
Outlet Channel Erosion		X		X		X	
Burrows		X		X		X	
Other		X		X		X	
Structural:							
Differential Settling		X		X		X	
Cracks and Slides		X		X		X	
Seepage		X		X		X	
Other		X		X		X	
Appurtenant Structures							
Defective Spillways		X		X		X	
De-Watering Device clogged		X		X		X	
Faulty Gates, Baffles, Pumps		X		X		X	
Other		X		X		X	
Additional Comments:	Water is recycled from the sediment ponds for use as dust control on roadways, as well as pumped to the CPP (as needed) and/or into the sealed area of the mine for storage and later use per MCC's adjudicated water storage right						
Action Needed:	RPE East needs sediment cleaned out. Reported to Surface Superintendent. Cleaning needs to happen this spring.						

Mountain Coal Company, LLC- West Elk Mine
Quarterly Self Pond Inspection Report
Somerset, Colorado Gunnison County

3/13/2024

1st 2024

Date

Quarter/ Year

C. Hiatt

Inspector

Pond ID	FW-2 North	FW-2 South	MB-3	MB-4	MB-5 North	MB-5 South
Pond Type	Fresh Water	Fresh Water	Sediment	Sediment	Sediment	Sediment
Sediment Level %	N/A	N/A	<15%	<5%	<10%	<15%
Water Level (Approx.)	Full	Full	30%	45%	25%	70%
Discharge? Y/N	N/A	N/A	N	N	N	N

Features	Problems?*		Maintenance?*		Repairs?*		Comments
* If Yes add comments							
Erosional:	Yes	No	Yes	No	Yes	No	
Rill & Gullies		X		X		X	
Inadequate Vegetation		X		X		X	
Outlet Channel Erosion		X		X		X	
Burrows		X		X		X	
Other		X		X		X	
Structural:							
Differential Settling		X		X		X	
Cracks and Slides		X		X		X	
Seepage		X		X		X	
Other		X		X		X	
Appurtenant Structures							
Defective Spillways		X		X		X	
De-Watering Device clogged		X		X		X	
Faulty Gates, Baffles, Pumps		X		X		X	
Other		X		X		X	
Additional Comments:	Water is recycled from the sediment ponds for use as dust control on roadways, as well as pumped to the CPP (as needed) and/or into the sealed area of the mine for storage and later use per MCC's adjudicated water storage right						
Action Needed:	Cleaning needs to happen this spring.						