

<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Williams Fork Mine	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Spoil Spring Outfall	<b>Quarterly Impoundment Inspection Form</b>
	3/28/2024		9/19/2023	
	Site 1SP		SE/4 NW/4 Sec.31 T6N R91W	
			7 mi. S of Craig, CO	
	Miranda Kawcak		Mike Howard	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)		X		8.1 gpm
Outflow (gpm)		X		
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENANCE</b>				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	