

PERMIT INFORMATION

Permit Number: C-1983-059	County: Delta	
Mine Name: Terror Creek Loadout	Operation Type: Loadout	
Operator: Oxbow Mining, LLC	Permit Status: Active	
Operator Address:	Ownership: Private	
Mr Doug Smith		
PO Box 535	Operator Representative Present:	
Paonia, CO 81434		
	N/A	
Operator Representative Signature: (Field Issuance Only)		

INSPECTION INFORMATION

Inspection Start Date: May 22, 2 Inspection Start Time: 14:00 Inspection End Date: Inspection End Time:	2024		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:		Join	Inspection Contacts:	
None				
Post Inspection Agency: Post		Post	Post Inspection Contacts:	
None				
Inspector(s):	Inspector's Signature: Signature Date:			
Leigh Simmons	Ri	\sim	May 31, 2024	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

- **N** Air Resource Protection
- **N** Availability of Records
- $N\,$ Backfill & Grading
- N Excess Spoil and Dev. Waste
- N Explosives
- N Fish & Wildlife
- Y Hydrologic Balance
- **R** Gen. Compliance With Mine Plan
- N Other
- N Processing Waste

- N Roads
- N Reclamation Success
- N Revegetation
- N Subsidence
- ${\bf N}\,$ Slides and Other Damage
- Y Support Facilities On-site
- Y Signs and Markers
- N Support Facilities Not On-site
- N Special Categories Of Mining
- Y Topsoil

COMMENTS

This was a partial inspection by Leigh Simmons of the Division of Reclamation, Mining and Safety (Division). The weather was clear and dry. The gate to the site was locked. There was no mining-related activity at the site, but the site was being used for the storage of equipment and materials for other industrial and commercial activities.

GENERAL MINE PLAN COMPLIANCE:

Oxbow had agreed a lease with a new tenant since the last inspection and some equipment had been moved to the upper pad. The tenant had also done some work to clean and rehabilitate the trailer.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Figure 1: Gate locked, Mine ID sign in place



Figure 2: Overview of upper pad

Number of <u>Partial</u> Inspection this Fiscal Year: 8 Number of <u>Complete</u> Inspections this Fiscal Year: 3



Figure 3: Trailer



Figure 4: Garage/shop foundation pad

Number of <u>Partial</u> Inspection this Fiscal Year: 8 Number of <u>Complete</u> Inspections this Fiscal Year: 3

LDS



Figure 5: Lower pad and temporary building



Figure 6: Western end of lower pad and temporary building

Number of <u>Partial</u> Inspection this Fiscal Year: 8 Number of <u>Complete</u> Inspections this Fiscal Year: 3