

Zuber - DNR, Rob <rob.zuber@state.co.us>

Inspection report for Bowie #1

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>

Fri, Jun 7, 2024 at 12:37 PM

To: Basil Bear <basilbear@wolverinefuels.com>, Tamme Bishop <tammekb@gmail.com>

Here is the report for Bowie #1.

Rob Zuber, P.E. Environmental Protection Specialist Active Mines Regulatory Program



I am working remotely and can be reached by cell at 720.601.2276.

Physical Address:
1313 Sherman Street, Room 215
Denver, CO 80203
Mailing Address:
Division of Reclamation, Mining and Safety, Room 215
1001 East 62nd Avenue
Denver, CO 80216

rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC_C1981038_RDZ_06072024.pdf



PERMIT INFORMATION

Permit Number: C-1981-038 Mine Name: Bowie No. 1 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil R Bear	County: Delta Operation Type: Underground Permit Status: Active Ownership: Private		
P.O. Box 1488	Operator Representative Present:		
11012011100	Sperator Representative Present.		
Paonia, CO 81428	None		
Operator Representative Signature: (Field Issuance Only)			

INSPECTION INFORMATION

Inspection Start Date: June 4, 2024 Inspection Start Time: 15:35 Inspection End Date: June 4, 2024 Inspection End Time: 16:20			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector's Signature: Signature Da		re Date:	
Robert Zuber, P.E.	Phot D. The			
			6/7/20	024

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection R - Roads

N - Availability of Records R - Reclamation Success

N - Backfill & Grading
NA - Excess Spoil and Dev. Waste
Y - Subsidence

NA - Explosives Y - Slides and Other Damage

N - Fish & Wildlife
NA - Support Facilities On-site
R - Hydrologic Balance
R - Signs and Markers

Y - Gen. Compliance With Mine Plan

R - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

NA - Processing Waste N - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS on June 4, 2024. No Bowie Resources Limited (BRL) representative was at the inspection.

No mining or reclamation activities were being conducted at this site. BRL is focusing on Bowie No. 2 in 2024.

The weather was hot and partly cloudy. The ground was dry.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the loadout, the Coal Storage Area (near Black Bridge Road), and the West Mine contained little to no water, and no problems were identified with these ponds.

The irrigation ditch that flows under the loadout (the Farmers Ditch) was flowing full. No problems were identified with the large culvert that contains this ditch.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No problems were seen with the road to the reclaimed ROM area.

Number of <u>Partial</u> Inspection this Fiscal Year: 7 Number of <u>Complete</u> Inspections this Fiscal Year: 4

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion was seen at the West Mine, including the reclaimed road. Cattle were grazing in this area. The Division recommends that this practice be limited to achieve good vegetation for final bond release.

REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

Thistle plants were observed near the pond at the loadout. These should be killed or removed.

SIGNS AND MARKERS – Rule 4.02:

No issues with signs or markers were identified during the inspection.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No erosion or other problems were seen with the Coal Storage Area beside the intersection of Highway 133 and Black Bridge Road.

No erosion was seen at the loadout, including the steep slope between the loadout and the orchard below. The trestle across the river appears stable.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Water in Farmers Ditch at outlet of long culvert at loadout



West Mine reclaimed road



Ponds at West Mine

Number of <u>Partial</u> Inspection this Fiscal Year: 7 Number of <u>Complete</u> Inspections this Fiscal Year: 4