



TRAPPER MINING INC.

June 19, 2024

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Second Quarter 2024 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on June 11th, 14th, 17th and 18th.

The following maintenance items were noted:


- Far East Buzzard #1 sediment marker needs to be replaced.
- No Name #2 sediment marker needs to be replaced.
- West Pyeatt #2 identification sign needs to be repaired.
- East Pyeatt #1 sediment marker needs to be replaced.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Second Quarter 2024
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	35.00	2.96	5.51
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	35.00	2.13	3.96
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	15.00	0.21	1.19
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	5.00	0.05	0.94
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

Trapper Mining Inc.

Second Quarter 2024

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	45.00	1.51	1.85
East Middle Flume	13.0	2.56	1.54	9.2	1.02	20.00	0.51	2.05
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	25.00	0.50	1.50
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: **FAR EAST BUZZARD**

SIGNATURE: Jim Gorman
DATE OF INSPECTION: 6/14/24

POND IDENTIFICATION	Far East Buzzard #1
Approximate water level:	
Sediment level (% total storage):	40 %
Outflow (cfs):	10 %
Sediment marker (install or replace)	0
Identification sign (install or replace)	Needs replaced in place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: ADAM BREWER

DRAINAGE: **COYOTE**

SIGNATURE: 

DATE OF INSPECTION: 6/11/24

POND IDENTIFICATION	Coyote #1		
Approximate water level:	39%		
Sediment level (% total storage):	MINIMAL		
Outflow (cfs):	0		
Sediment marker (install or replace)	N/A		
Identification sign (install or replace)	IN PLACE		
EROSIONAL:			
Rills and/or gullies on downstream face.	NONE		
Rills and/or gullies on upstream face.	NONE		
Inadequate vegetation.	NO		
Outlet channel erosion.	NONE		
Burrows.	NONE		
Erosion of toe.	NO		
Water impounded against downstream toe.	NO		
Other.	N/A		
STRUCTURAL:			
Differential settling.	NONE		
Cracks, slides, or scarps.	NONE		
Seepage (specify location, color, value).	YES *		
Defective spillways.	NO		
Other.	N/A		
APPURTENANT STRUCTURES:			
Defective spillways.			
Dewatering device clogged.	NO		
Cracking or crushing of pipes.	NO		
Other.	NO		
COMMENTS:			

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

* SLIGHT SEEPAGE, CLEAR COLOR, COMING OUT ON SPILLWAY NEXT TO DECANT PIPE OUTLET.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: **NO NAME**

SIGNATURE: Tim Cummins

DATE OF INSPECTION: 6/14/24

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	* 35%	15%	25%
Outflow (cfs):	21 CFS	< 1 CFS	< 1 CFS
Sediment marker (install or replace)	Need to replace	in place	underwater
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	-	-	-
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	-	-	-
COMMENTS:			

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
#5: 60% level = top of post - 4.5'

There is vegetation in spillways of all 3 impoundments, affecting water flow
* scheduled for sediment removal this summer



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: **JOHNSON GULCH**

SIGNATURE: Jim Gentry
DATE OF INSPECTION: 6/14/24

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	25%	35%	35%	20%	35%
Outflow (cfs):	21 cfs	21 cfs	21 cfs	21 cfs	21 cfs
Sediment marker (install or replace)	in place	under water	underwater	Best in place	underwater
Identification sign (install or replace)	in place	in place	in place	in place	in place
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No	No	No	No
Rills and/or gullies on upstream face.	No	No	No	No	No
Inadequate vegetation.	No	No	No	No	No
Outlet channel erosion.	No	No	No	No	No
Burrows.	No	No	No	No	No
Erosion of toe.	No	No	No	No	No
Water impounded against downstream toe.	No	No	No	No	No
Other.	—	—	—	—	—
STRUCTURAL:					
Differential settling.	No	No	No	No	No
Cracks, slides, or scarps.	No	No	No	No	No
Seepage (specify location, color, value).	No	No	No	No	No
Defective spillways.	No	No	No	No	No
Other.	—	—	—	—	—
APPURTENANT STRUCTURES:					
Defective spillways.	No	No	No	No	No
Dewatering device clogged.	No	No	No	No	No
Cracking or crushing of pipes.	No	No	No	No	No
Other.	—	—	—	—	—
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

Vegetation is present in impoundments #7, 8, & 9 but does not appear to impede flow of water.

** #9 scheduled for sediment removal this summer

* Best in place but sediment marker is missing



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **WEST PYEATT**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/10/2024

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	DRY	65%
Sediment level (% total storage):	45%	45%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Underwater
Identification sign (install or replace)	In Place	In Place *
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		

* Sign needs rebolted at the bottom.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **MIDDLE PYEATT**

SIGNATURE: [Signature]

DATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	40%	DRY	DRY
Sediment level (% total storage):	15%	25%	40%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	no	no	no
Rills and/or gullies on upstream face.	no	no	no
Inadequate vegetation.	no	no	no
Outlet channel erosion.	no	no	no
Burrows.	no	no	no
Erosion of toe.	no	no	no
Water impounded against downstream toe.	no	no	no
Other.	-	-	-
STRUCTURAL:			
Differential settling.	no	no	no
Cracks, slides, or scarps.	no	no	no
Seepage (specify location, color, value).	no	no	no
Defective spillways.	no	no	no
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	no	no	no
Dewatering device clogged.	no	no	no
Cracking or crushing of pipes.	no	no	no
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: **EAST PYEATT**

SIGNATURE: Jim Cummings
DATE OF INSPECTION: 6/14/24

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100 %	100 %	100 %
Sediment level (% total storage):	5 %	20 %	30 %
Outflow (cfs):	2.1 cfs	2.1 cfs	2.1 cfs
Sediment marker (install or replace)	Needs to be replaced	underwater	underwater
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	-	-	-
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonya Perkins

DRAINAGE: **GROUSE GULCH**

SIGNATURE: Tonya Perkins
DATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	65'	
Sediment level (% total storage):	40%	10%
Outflow (cfs):	0	15%
Sediment marker (install or replace)	Underwater	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins
DRAINAGE: **SAGE GULCH**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	dry	dry
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	+
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: OAK GULCH

SIGNATURE: [Signature]
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	58%	DRY
Sediment level (% total storage):	45%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-

COMMENTS: Some vegetation in both outflows, not hindering water flow.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **WEST FLUME**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	West Flume #1
Approximate water level:	<u>DRY</u>
Sediment level (% total storage):	<u>10%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In place</u>
Identification sign (install or replace)	<u>In place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>no</u>
Rills and/or gullies on upstream face.	<u>no</u>
Inadequate vegetation.	<u>no</u>
Outlet channel erosion.	<u>no</u>
Burrows.	<u>no</u>
Erosion of toe.	<u>no</u>
Water impounded against downstream toe.	<u>no</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>no</u>
Cracks, slides, or scarps.	<u>no</u>
Seepage (specify location, color, value).	<u>no</u>
Defective spillways.	<u>no</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>no</u>
Dewatering device clogged.	<u>no</u>
Cracking or crushing of pipes.	<u>no</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **MIDDLE FLUME**

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	40%	90%
Sediment level (% total storage):	40%	45%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Underwater
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **EAST MIDDLE FLUME**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	<u>120%</u>
Sediment level (% total storage):	<u>20%</u>
Outflow (cfs):	<u>41 CFS</u>
Sediment marker (install or replace)	<u>Underwater</u>
Identification sign (install or replace)	<u>In place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **EAST FLUME**

SIGNATURE: *Tonia Perkins*
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	East Flume #1
Approximate water level:	<u>DRY</u>
Sediment level (% total storage):	<u>15%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>NO</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **UTE GULCH**

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	Ute #1
Approximate water level:	80'.
Sediment level (% total storage):	45'.
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **HORSE GULCH**

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	Horse #1
Approximate water level:	
Sediment level (% total storage):	75%
Outflow (cfs):	55%
Sediment marker (install or replace)	0
Identification sign (install or replace)	underwater
EROSIONAL:	In Place
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins
DRAINAGE: WEST HORSE GULCH

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	West Horse #1
Approximate water level:	Minimal
Sediment level (% total storage):	20%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	# -
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: DEAL GULCH

SIGNATURE: [Signature]
DATE OF INSPECTION: 6/17/2024

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	99%	DRY
Sediment level (% total storage):	25%	Minimal
Outflow (cfs):	0%	0
Sediment marker (install or replace)	Underwater	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	*Minimal
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.		
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.		
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.		
COMMENTS:		

Burrow by weir, not compromising the structure.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: DEACONSIGNATURE: Tonia PerkinsDATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: **JEFFWAY**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Jeffway #1
Approximate water level:	40%
Sediment level (% total storage):	0%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: **IMPOUNDMENT H**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 6/18/2024

POND IDENTIFICATION	Impoundment H
Approximate water level:	50%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: **INDUSTRIAL WASTE POND**

SIGNATURE: Jim Cummins

DATE OF INSPECTION: 6/13/24

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	
Sediment level (% total storage):	80 %
Outflow (cfs):	5 %
Sediment marker (install or replace)	0
Identification sign (install or replace)	N/A
EROSIONAL:	In-Place
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	
COMMENTS:	

