

Wein - DNR, Clayton <clayton.wein@state.co.us>

Deserado Mine, C-1981-018, 1st Quarter 2024 Coal Waste Bank Report Review

1 message

Wein - DNR, Clayton <clayton.wein@state.co.us>
To: Kurt Blunt <kblunt@deserado.com>

Mon, Aug 12, 2024 at 10:11 AM

Good morning Kurt,

Attached is the Division's review letter for the 1st Quarter Coal Waste Bank Report for the Deserado Mine. Please note the adequacy questions in bold text within the report. Please feel free to contact me if you have any questions or concerns.

Sincerely, Clayton Wein Environmental Protection Specialist



P 720.762.6156 | F 303.832.8106 1313 Sherman Street, Room 215, Denver, CO 80203 clayton.wein@state.co.us | https://www.drms.colorado.gov

Deserado Mine, C-1981-018, 1st Quarter Coal Waste Bank Report Review Letter.pdf 408K



August 12, 2024

Kurt Blunt Blue Mountain Energy, Inc. 3607 County Rd. 65 Rangely, CO 81648

RE: Deserado Mine, Permit No. C-1981-018
1st Quarter 2024 Professional Certification for the Coal Processing Waste Banks

Dear Kurt,

The Division of Reclamation, Mining and Safety (the Division) has reviewed the Professional Certification for the Coal Processing Waste Banks for the 1st quarter of 2024. The Division finds the report to be in compliance with the following Rules and has the following adequacy comments and questions:

- **4.10.2(1)** The coal waste banks were inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer.
- **4.10.2(2)(a)** The inspection was conducted quarterly as required by the Division.
- **4.10.2(2)(b)** The inspection included observations necessary to evaluate the potential hazard to human life and property, to ensure that all organic material and topsoil have been removed and that proper construction and maintenance are occurring in accordance with the plan submitted under Rule 2.05.3(8) and approved by the Division.
- **4.10.2(2)(c)** The engineer considered the steepness of the slopes, seepage, and other visual factors which would indicate potential failure, and the results of failure with respect to the threat to human life and property.
- **4.10.2(2)(d)** Copies of the inspection findings are maintained at the mine site.
- **4.10.2(3)** There were no potential hazards identified in the 1st Quarter Professional Certification for the Coal Processing Waste Banks.

Refuse material was hauled and placed at the RP-A refuse pile during the 1st quarter. There were no indications of seepage or any indications of slope failure. The slopes of



the piles are stable and only some localized erosion has occurred. The surface drainage facilities are properly conveying surface runoff from the refuse bank areas.

Adequacy Questions:

- 1. The Quarterly Coal Waste Bank Report mentions that the topsoil and subsoil piles for sub areas 1, 2/3/4 and 5A have been seeded and are stable. Please provide the Division with information regarding the topsoil and subsoil piles for the refuse area RP-A.
- 2. The 1st quarter report does not discuss if compaction tests were performed. Please include in future quarterly reports a short discussion of whether or not compaction tests were performed during the quarter.

This concludes the Division's review of the 1st quarter 2024 Professional Certification of the Coal Processing Waste Banks for the Deserado Mine. If you have any questions, please contact me at (720)-762-6156 or clayton.wein@state.co.us.

Sincerely,

Clayton Wein

Environmental Protection Specialist

clayton.wein@state.co.us

Clayton Wein

cc: Travis Marshall, Senior Environmental Protection Specialist GJFO