



TRAPPER MINING INC.

September 12, 2024

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Third Quarter 2024 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on July 25th, and 30th, September 10th and 12th.

The following maintenance item was noted:


- Middle Flume #3 sediment marker needs to be replaced.

Trapper will address this maintenance item in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.

Third Quarter 2024

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	10.00	0.61	5.48
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	15.00	0.21	1.19
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	5.00	0.05	0.94
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse #2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

Trapper Mining Inc.

Third Quarter 2024

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	30.00	1.01	2.35
East Middle Flume	13.0	2.56	1.54	9.2	1.02	25.00	0.64	1.92
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	25.00	0.50	1.50
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**


INSPECTOR: Tim CummingsDRAINAGE: FAR EAST BUZZARDSIGNATURE: Jim GammieDATE OF INSPECTION: 9/12/24

POND IDENTIFICATION	Far East Buzzard #1
Approximate water level:	0%
Sediment level (% total storage):	10%
Outflow (cfs):	0
Sediment marker (install or replace)	in place
Identification sign (install or replace)	in place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	N/A
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	N/A
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	N/A
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: COYOTE

DATE OF INSPECTION: 7/30/2024

POND IDENTIFICATION	Coyote #1		
Approximate water level:	35%		
Sediment level (% total storage):	Minimal		
Outflow (cfs):	0%		
Sediment marker (install or replace)	N/A		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: NO NAMESIGNATURE: Tonia PerkinsDATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	10%	15%	25%
Outflow (cfs):	41 CFS	41 CFS	41 CFS
Sediment marker (install or replace)	Underwater in place	in place	underwater in place
IDENTIFICATION sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	no	no	no
Rills and/or gullies on upstream face.	no	no	no
Inadequate vegetation.	no	no	no
Outlet channel erosion.	no	no	no
Burrows.	no	no	no
Erosion of toe.	no	no	no
Water impounded against downstream toe.	no	no	no
Other.	-	-	-
STRUCTURAL:			
Differential settling.	no	no	no
Cracks, slides, or scarps.	no	no	no
Seepage (specify location, color, value).	no	no	no
Defective spillways.	no	no	no
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	no	no	no
Dewatering device clogged.	no	no	no
Cracking or crushing of pipes.	no	no	no
Other.	-	-	-
COMMENTS:			

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
 #5: 60% level = top of post - 4.5'.

Vegetation is spillway of #2, #4 & #5, not hindering water flow.
 #2 was recently cleaned



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Yonnie Perkins
DATE OF INSPECTION: 9/10/2024

DRAINAGE: JOHNSON GULCH

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	90%
Sediment level (% total storage):	25%	35%	35%	20%	10%
Outflow (cfs):	41 CFS	21 CFS	41 CFS	41 CFS	0
Sediment marker (install or replace)	in place	underwater	underwater	underwater	underwater
Identification sign (install or replace)	in place	in place	in place	in place	in place
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no	no	no
Rills and/or gullies on upstream face.	no	no	no	no	no
Inadequate vegetation.	no	no	no	no	no
Outlet channel erosion.	no	no	no	no	no
Burrows.	no	no	no	no	no
Erosion of toe.	no	no	no	no	no
Water impounded against downstream toe.	no	no	no	no	no
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	no	no	no	no	no
Cracks, slides, or scarps.	no	no	no	no	no
Seepage (specify location, color, value).	no	no	no	no	no
Defective spillways.	no	no	no	no	no
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no	no	no
Dewatering device clogged.	no	no	no	no	no
Cracking or crushing of pipes.	no	no	no	no	no
Other.	-	-	-	-	-

COMMENTS:
#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

Vegetation in inflow & outflow of #6, #7, #8, #9, & #10, not hindering water-flow.
#10 Recently cleaned



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: WEST PYEATT

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	<u>Minimal</u>	<u>OR Y</u>
Sediment level (% total storage):	<u>45%</u>	<u>45%</u>
Outflow (cfs):	<u>0</u>	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>	<u>In Place</u>
EROSIONAL:		
Rills and/or gullies on downstream face.	<u>NO</u>	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>	<u>NO</u>
Inadequate vegetation.	<u>NO</u>	<u>NO</u>
Outlet channel erosion.	<u>NO</u>	<u>NO</u>
Burrows.	<u>NO</u>	<u>NO</u>
Erosion of toe.	<u>NO</u>	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
STRUCTURAL:		
Differential settling.	<u>NO</u>	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>	<u>NO</u>
Defective spillways.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
APPURTENANT STRUCTURES:		
Defective spillways.	<u>NO</u>	<u>NO</u>
Dewatering device clogged.	<u>NO</u>	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Donna Perkins*

DATE OF INSPECTION: 9/10/2024

DRAINAGE: **MIDDLE PYEATT**

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	35'	DRY	DRY
Sediment level (% total storage):	15'	25'	40'
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	-	-	-

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: EAST PYEATT

SIGNATURE: [Signature]

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	5%	20%	30%
Outflow (cfs):	41 CFS	41 CFS	41 CFS
Sediment marker (install or replace)	Underwater In Place	Underwater In Place	Underwater In Place
Identification sign (install or replace)			
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **GROUSE GULCH**DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	55'1.	10'1.
Sediment level (% total storage):	40'1.	15'1.
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: SAGE GULCH

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face	no	no
Rills and/or gullies on upstream face	no	no
Inadequate vegetation	no	no
Outlet channel erosion	no	no
Burrows	no	no
Erosion of toe	no	no
Water impounded against downstream toe	no	no
Other	-	-
STRUCTURAL:		
Differential settling	no	no
Cracks, slides, or scarps	no	no
Seepage (specify location, color, value)	no	no
Defective spillways	no	no
Other	-	-
APPURTENANT STRUCTURES:		
Defective spillways	no	no
Dewatering device clogged	no	no
Cracking or crushing of pipes	no	no
Other	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: OAK GULCHDATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	30'±	DRY
Sediment level (% total storage):	45'±	101
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-

COMMENTS:

Some vegetation in both outflows, not hindering water flow



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: WEST FLUME

SIGNATURE: Dana Perkins

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	West Flume #1
Approximate water level:	DRY
Sediment level (% total storage):	10%
Outflow (cfs):	0
Sediment marker (install or replace)	to place
Identification sign (install or replace)	to place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

DRAINAGE: MIDDLE FLUME

SIGNATURE: Jim Cummins

DATE OF INSPECTION: 9/12/24

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	35%	50%
Sediment level (% total storage):	40%	30%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	Replace
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe	No	No
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, volume).	No	No
Defective spillways.	No	No
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	N/A	N/A

COMMENTS:

Middle Flume #3 recently partially cleaned.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: EAST MIDDLE FLUME

SIGNATURE: *Tonia Perkins*
DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	
Sediment level (% total storage):	100%
Outflow (cfs):	25%
Sediment marker (install or replace)	210FS
Identification sign (install or replace)	Underwater In place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	no
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: [Signature]

DRAINAGE: EAST FLUME

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	East Flume #1
Approximate water level:	<u>DRY</u>
Sediment level (% total storage):	<u>15%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: UTE GULCH

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Ute #1
Approximate water level:	50'1
Sediment level (% total storage):	45'1
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	

Some veg. in the spillway outflow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDATE OF INSPECTION: 9/10/2024DRAINAGE: **HORSE GULCH**

POND IDENTIFICATION	Horse #1			
Approximate water level:	75%			
Sediment level (% total storage):	55%			
Outflow (cfs):	0			
Sediment marker (install or replace)	Underwater			
Identification sign (install or replace)	In Place			
EROSIONAL:				
Rills and/or gullies on downstream face.	NO			
Rills and/or gullies on upstream face.	NO			
Inadequate vegetation.	NO			
Outlet channel erosion.	NO			
Burrows.	NO			
Erosion of toe.	NO			
Water impounded against downstream toe.	NO			
Other.	-			
STRUCTURAL:				
Differential settling.	NO			
Cracks, slides, or scarps.	NO			
Seepage (specify location, color, value).	NO			
Defective spillways.	NO			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	NO			
Dewatering device clogged.	NO			
Cracking or crushing of pipes.	NO			
Other.	-			
COMMENTS:				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: WEST HORSE GULCHSIGNATURE: Tonia PerkinsDATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	West Horse #1
Approximate water level:	<u>dry</u>
Sediment level (% total storage):	<u>201</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>No</u>
Rills and/or gullies on upstream face.	<u>No</u>
Inadequate vegetation.	<u>No</u>
Outlet channel erosion.	<u>No</u>
Burrows.	<u>No</u>
Erosion of toe.	<u>No</u>
Water impounded against downstream toe.	<u>No</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>No</u>
Cracks, slides, or scarps.	<u>No</u>
Seepage (specify location, color, value).	<u>No</u>
Defective spillways.	<u>No</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>No</u>
Dewatering device clogged.	<u>No</u>
Cracking or crushing of pipes.	<u>No</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: DEAL GULCHDATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	90'1"	DRY
Sediment level (% total storage):	25'1"	Minimal
Outflow (cfs):	0	In Place
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)		
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	-
Other.		
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	-
Other.		
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	-
Other.		

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **JEFFWAY**

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: *7/25/2024*

POND IDENTIFICATION	Jeffway #1		
Approximate water level:	<i>25%</i>		
Sediment level (% total storage):	<i>0%</i>		
Outflow (cfs):	<i>0</i>		
Sediment marker (install or replace)	<i>In Place</i>		
Identification sign (install or replace)	<i>In Place</i>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<i>no</i>		
Rills and/or gullies on upstream face.	<i>no</i>		
Inadequate vegetation.	<i>no</i>		
Outlet channel erosion.	<i>no</i>		
Burrows.	<i>no</i>		
Erosion of toe.	<i>no</i>		
Water impounded against downstream toe.	<i>no</i>		
Other.	<i>-</i>		
STRUCTURAL:			
Differential settling.	<i>no</i>		
Cracks, slides, or scarps.	<i>no</i>		
Seepage (specify location, color, value).	<i>no</i>		
Defective spillways.	<i>no</i>		
Other.	<i>-</i>		
APPURTENANT STRUCTURES:			
Defective spillways.	<i>no</i>		
Dewatering device clogged.	<i>no</i>		
Cracking or crushing of pipes.	<i>no</i>		
Other.	<i>-</i>		
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Torria PerkinsDRAINAGE: **IMPOUNDMENT H**SIGNATURE: *Donna Perkins*DATE OF INSPECTION: 9/10/2024

POND IDENTIFICATION	Impoundment H		
Approximate water level:	20'		
Sediment level (% total storage):	5%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			

- Veg. in front of sign.

Vegetation removed on 9/11/2024 TMP



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

SIGNATURE: Tim Cummins

DATE OF INSPECTION: 9/12/24

DRAINAGE: **INDUSTRIAL WASTE POND**

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	82%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	in place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	N/A
Other.	N/A
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	N/A
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	

COMMENTS:

