

# MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
BLM Pit No. 1	M-2001-100	Sand and gravel	Mesa
INSPECTION TYPE:	WEATHER:	INSP. DATE:	INSP. TIME:
Monitoring	Clear	September 24, 2024	12:15
OPERATOR:	<b>OPERATOR REPRESENTATIVE:</b>	TYPE OF OPERATION:	
Oldcastle SW Group, Inc. dba	Jesse Farmer	112c - Construction Regular Operation	
United Companies of Mesa County			
REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program	Complete Bond	\$95,739.00	
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA	None	U.S.BLM	
INSPECTOR(S):	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:	
Amy Yeldell	Amy Geldell	October 2, 2024	

## **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION <u>Y</u>	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety's (Division) normal monitoring program. The BLM Pit No. 1 is a 112c permitted site that includes a total of 35.6 permitted acres. The BLM Pit No. 1 is located adjacent to the Hall Pit (M-1983-142) also permitted by Oldcastle. This site is located approximately two mile south of Clifton, Colorado in Mesa County and is accessed from B ½ Road. Amy Yeldell of the Division conducted the inspection. Jesse Farmer with Oldcastle SW Group, Inc. dba United Companies of Mesa County represented the operator

## Availability Of Records:

Based on the 2024 annual report the Operator has indicated that they intend to begin final reclamation of the site.

#### Acid And Toxic Materials:

No fuel or other hazardous materials remain on site.

## Backfilling and Grading:

The southwestern portion of the pit has been recontoured. The main highwalls exist on the eastern side of the pit. Active highwalls are near vertical and approximately 15 feet high. Staff estimates that approximately 1200 LF of highwall requires grading. There are several smaller stockpiles located on the pit floor that will also require smoothing out if not removed prior to commencement of final reclamation.

## Explosives:

No explosives were used in conjunction with this mining operation.

#### Financial Warranty:

The Division currently requires a financial warranty amount of \$95,739 for this site. The bond was last updated in 2021 with SI-1. In an effort to ensure the Financial Warranty adequately, reflects the actual current cost of fulfilling the requirements of the approved reclamation plan the Division will be updating the reclamation cost estimate. If the current bond is found to be insufficient the Division will send a Notice of Surety Increase under a separate cover.

## Gen. Compliance With Mine Plan:

Based on the annual report the site has been active annually. However, the map of the annual report indicates little to not activity on site. Per Rule 1.13 Active status requires mining annually more than 180 days. If the mine ceases production for more than a year it shall go into temporary cessation or enter into final reclamation. Given that the operator has indicated that they intend to reclaim the site this is not cited as a problem.

#### Roads:

The access road to the BLM Pit No. 1 is shared with the Hall Pit. The removal of the road is covered under this site's bond. Removal of the scale and scale house is covered under the Hall Pit.

#### **Reclamation Success:**

No areas were evaluated for success of final reclamation.

## Revegetation:

There appears to be some revegetation right as you enter the pit from the Hall Pit. Vegetation was not evaluated sustainability, diversity or composition.

PERMIT #: M-2001-100 INSPECTOR'S INITIALS: ACY INSPECTION DATE: September 24, 2024

The pit floor had a fair amount of Russian Thistle and Halogeton. If reclamation is to occur in the near future the Division recommends aggressive treatment of noxious weeds to avoid accumulating a seedbank prior to initiating reclamation.

## Subsidence:

No subsidence was observed.

## **Sediment Control:**

No signs of sedimentation or erosion were observed.

## Support Facilities On-site:

No structures were observed on site.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, Rm 215, 1001 E 62nd Ave, Denver Co 80216. Direct contact can be made by phone at 303-866-3567 Ext 8183 or via email at amy.yeldell@state.co.us

## **Inspection Contact Address**

Jesse Farmer Oldcastle SW Group, Inc. dba United Companies of Mesa County 2273 River Road Grand Junction, CO 81502

Enclosure

#### CC:

Travis Marshall, Senior EPS, Grand Junction DRMS Jennifer Wittington, BLM









