



TRAPPER MINING INC.

October 22, 2024

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Fourth Quarter 2024 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on October 15th, 16th, and 21st.

The following maintenance item was noted:


- Grouse #1 sediment marker needs to be replaced.
- Middle Flume #3 sediment marker needs to be replaced.
- East Buzzard #3 sediment marker needs to be installed.
- West Buzzard #3 sediment marker needs to be installed.
- West Buzzard #4 sediment marker needs to be installed.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.

Fourth Quarter 2024

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	30.00	1.01	2.35
East Middle Flume	13.0	2.56	1.54	9.2	1.02	25.00	0.64	1.92
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	25.00	0.50	1.50
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	2.00	0.06	2.80
East Buzzard #3	7.0	2.21	0.80	3.3	1.41	0.00	0.00	2.21
West Buzzard #3	8.0	0.93	0.33	5.0	0.60	0.00	0.00	0.93
West Buzzard #4	9.0	1.53	0.55	5.0	0.98	0.00	0.00	1.53
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

Trapper Mining Inc.
Fourth Quarter 2024
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	10.00	0.61	5.48
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	15.00	0.21	1.19
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	5.00	0.05	0.94
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse #2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham Roberts

DRAINAGE: **FAR EAST BUZZARD**

SIGNATURE: Sh. Rk

DATE OF INSPECTION: 10-15-24

POND IDENTIFICATION	Far East Buzzard #1
Approximate water level:	0%
Sediment level (% total storage):	10%
Outflow (cfs):	0 cfs
Sediment marker (install or replace)	In place
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	NA
Cracking or crushing of pipes.	NA
Other.	
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: ~~Tonia Perkins~~ Graham Roberts

SIGNATURE: [Signature]

DATE OF INSPECTION: 10-15-24

DRAINAGE: COYOTE

POND IDENTIFICATION	Coyote #1
Approximate water level:	45%
Sediment level (% total storage):	Minimal
Outflow (cfs):	0 cfs
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No - minimal
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	-

COMMENTS:

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: NO NAME

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	10%	15%	25%
Outflow (cfs):	41 cfs	41 cfs	21 cfs
Sediment marker (install or replace)	Underwater	in place	Underwater
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	no	no	no
Rills and/or gullies on upstream face.	no	no	no
Inadequate vegetation.	no	no	no
Outlet channel erosion.	no	no	no
Burrows.	no	no	no
Erosion of toe.	no	no	no
Water impounded against downstream toe.	no	no	no
Other.	-	-	-
STRUCTURAL:			
Differential settling.	no	no	no
Cracks, slides, or scarps.	no	no	no
Seepage (specify location, color, value).	no	no	no
Defective spillways.	no	no	no
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	no	no	no
Dewatering device clogged.	no	no	no
Cracking or crushing of pipes.	no	no	no
Other.	-	-	-
COMMENTS:			

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
#5: 60% level = top of post - 4.5'.

Some vegetation in spill ways of all 3 ponds,
not hindering water-flow.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: **JOHNSON GULCH**

DATE OF INSPECTION: 10/17/2024

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	98%
Sediment level (% total storage):	25%	35%	35%	20%	10%
Outflow (cfs):	21 CFS	21 CFS	21 CFS	< 1 CFS	0
Sediment marker (install or replace)	In place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In place	In place	In place	In place	In place
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no	no	no
Rills and/or gullies on upstream face.	no	no	no	no	no
Inadequate vegetation.	no	no	no	no	no
Outlet channel erosion.	no	no	no	no	no
Burrows.	no	no	no	no	no
Erosion of toe.	no	no	no	no	no
Water impounded against downstream toe.	no	no	no	no	no
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	no	no	no	no	no
Cracks, slides, or scarps.	no	no	no	no	no
Seepage (specify location, color, value).	no	no	no	no	no
Defective spillways.	no	no	no	no	no
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no	no	no
Dewatering device clogged.	no	no	no	no	no
Cracking or crushing of pipes.	no	no	no	no	no
Other.	-	-	-	-	-

COMMENTS:

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

Some vegetation in all the outflows of the ponds, but no hindering waterflow



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: WEST PYEATT

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	<u>Minimal</u>	<u>DRY</u>
Sediment level (% total storage):	<u>45%</u>	<u>45%</u>
Outflow (cfs):	<u>0</u>	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>	<u>In Place</u>
EROSIONAL:		
Rills and/or gullies on downstream face.	<u>no</u>	<u>no</u>
Rills and/or gullies on upstream face.	<u>no</u>	<u>no</u>
Inadequate vegetation.	<u>no</u>	<u>no</u>
Outlet channel erosion.	<u>no</u>	<u>no</u>
Burrows.	<u>no</u>	<u>no</u>
Erosion of toe.	<u>no</u>	<u>no</u>
Water impounded against downstream toe.	<u>no</u>	<u>no</u>
Other.	<u>-</u>	<u>-</u>
STRUCTURAL:		
Differential settling.	<u>no</u>	<u>no</u>
Cracks, slides, or scarps.	<u>no</u>	<u>no</u>
Seepage (specify location, color, value).	<u>no</u>	<u>no</u>
Defective spillways.	<u>no</u>	<u>no</u>
Other.	<u>-</u>	<u>-</u>
APPURTENANT STRUCTURES:		
Defective spillways.	<u>no</u>	<u>no</u>
Dewatering device clogged.	<u>no</u>	<u>no</u>
Cracking or crushing of pipes.	<u>no</u>	<u>no</u>
Other.	<u>-</u>	<u>-</u>
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tonia Perkins

SIGNATURE:



DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION:

10/15/2024

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	35%	DRY	DRY
Sediment level (% total storage):	15%	25%	40%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: EAST PYEATT

SIGNATURE: Tonia Perkins
DATE OF INSPECTION: 10/15/2025

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	5%	20%	30%
Outflow (cfs):	21 CFS	21 CFS	21 CFS
Sediment marker (install or replace)	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **GROUSE GULCH**DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	45'.	DRY
Sediment level (% total storage):	40'.	15'.
Outflow (cfs):	0	0
Sediment marker (install or replace)	Replace	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.		
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.		
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.		

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **SAGE GULCH**DATE OF INSPECTION: 10/17/2024

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: OAK GULCH

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 10/15/2025

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	<u>25'</u>	<u>DRY</u>
Sediment level (% total storage):	<u>45%</u>	<u>10%</u>
Outflow (cfs):	<u>0</u>	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>	<u>In Place</u>
EROSIONAL:		
Rills and/or gullies on downstream face.	<u>NO</u>	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>	<u>NO</u>
Inadequate vegetation.	<u>NO</u>	<u>NO</u>
Outlet channel erosion.	<u>NO</u>	<u>NO</u>
Burrows.	<u>NO</u>	<u>NO</u>
Erosion of toe.	<u>NO</u>	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
STRUCTURAL:		
Differential settling.	<u>NO</u>	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>	<u>NO</u>
Defective spillways.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
APPURTENANT STRUCTURES:		
Defective spillways.	<u>NO</u>	<u>NO</u>
Dewatering device clogged.	<u>NO</u>	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
COMMENTS:		

Vegetation in both outflows, not hindering water flow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: [Signature]

DATE OF INSPECTION: 10/15/2024

DRAINAGE: **WEST FLUME**

POND IDENTIFICATION	West Flume #1
Approximate water level:	<u>dry</u>
Sediment level (% total storage):	<u>10%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>no</u>
Rills and/or gullies on upstream face.	<u>no</u>
Inadequate vegetation.	<u>no</u>
Outlet channel erosion.	<u>no</u>
Burrows.	<u>no</u>
Erosion of toe.	<u>no</u>
Water impounded against downstream toe.	<u>no</u>
Other.	
STRUCTURAL:	
Differential settling.	<u>no</u>
Cracks, slides, or scarps.	<u>no</u>
Seepage (specify location, color, value).	<u>no</u>
Defective spillways.	<u>no</u>
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	<u>no</u>
Dewatering device clogged.	<u>no</u>
Cracking or crushing of pipes.	<u>no</u>
Other.	

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: **MIDDLE FLUME**

SIGNATURE: [Signature]
DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	30'.	
Sediment level (% total storage):	40'.	30'.
Outflow (cfs):	0	30'.
Sediment marker (install or replace)	In Place	0
Identification sign (install or replace)	In Place	Replace *
EROSIONAL:	In Place	In Place
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	no	no
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	no	no
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	no	no
COMMENTS:		

* #3-Sediment marker possibly lost in cat-tails.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 10/15/2025

DRAINAGE: **EAST MIDDLE FLUME**

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	100%
Sediment level (% total storage):	25%
Outflow (cfs):	21 cfs
Sediment marker (install or replace)	Underwater
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: EAST FLUME

SIGNATURE: Gene Puffig
DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	East Flume #1
Approximate water level:	<u>DRY</u>
Sediment level (% total storage):	<u>15%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	
Identification sign (install or replace)	<u>No Place</u>
EROSIONAL:	<u>No Place</u>
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: [Signature]

DATE OF INSPECTION: 12/15/2024

DRAINAGE: UTE GULCH

POND IDENTIFICATION	Ute #1		
Approximate water level:	<u>40'.</u>		
Sediment level (% total storage):	<u>45'.</u>		
Outflow (cfs):	<u>0</u>		
Sediment marker (install or replace)	<u>In Place</u>		
Identification sign (install or replace)	<u>In Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>no</u>		
Rills and/or gullies on upstream face.	<u>no</u>		
Inadequate vegetation.	<u>no</u>		
Outlet channel erosion.	<u>no</u>		
Burrows.	<u>no</u>		
Erosion of toe.	<u>no</u>		
Water impounded against downstream toe.	<u>no</u>		
Other.			
STRUCTURAL:			
Differential settling.	<u>no</u>		
Cracks, slides, or scarps.	<u>no</u>		
Seepage (specify location, color, value).	<u>no</u>		
Defective spillways.	<u>no</u>		
Other.	<u>-</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>no</u>		
Dewatering device clogged.	<u>no</u>		
Cracking or crushing of pipes.	<u>no</u>		
Other.	<u>-</u>		

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: HORSE GULCH

SIGNATURE: [Signature]
DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	Horse #1
Approximate water level:	DRY
Sediment level (% total storage):	55%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: **WEST HORSE GULCH**

DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	West Horse #1
Approximate water level:	dry
Sediment level (% total storage):	20%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-

COMMENTS:



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: DEAL GULCHSIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	90%	DRY
Sediment level (% total storage):	25%	Minimal
Outflow (cfs):	0	0
Sediment marker (install or replace)	Undeclared	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 10/15/2024

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0%	0%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.		
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.		
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.		

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: [Signature] 4TH QUADRAINAGE: **JEFFWAY**DATE OF INSPECTION: 10/16/2024

POND IDENTIFICATION	Jeffway #1		
Approximate water level:	20'.		
Sediment level (% total storage):	2'.		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	minimal		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		

COMMENTS:



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham RobertsDRAINAGE: **EAST BUZZRD**SIGNATURE: *Sh. Rh*DATE OF INSPECTION: 10-15-24

POND IDENTIFICATION	East Buzzard #3		
Approximate water level:	<u>65%</u>		
Sediment level (% total storage):	<u>Min - 0%</u>		
Outflow (cfs):	<u>0 cfs</u>		
Sediment marker (install or replace)	<u>In process - install</u>		
Identification sign (install or replace)	<u>In place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>No</u>		
Rills and/or gullies on upstream face.	<u>No</u>		
Inadequate vegetation.	<u>No Yes</u>		
Outlet channel erosion.	<u>No</u>		
Burrows.	<u>No</u>		
Erosion of toe.	<u>No</u>		
Water impounded against downstream toe.	<u>No</u>		
Other.	<u>-</u>		
STRUCTURAL:			
Differential settling.	<u>No</u>		
Cracks, slides, or scarps.	<u>No</u>		
Seepage (specify location, color, value).	<u>No</u>		
Defective spillways.	<u>No</u>		
Other.	<u>-</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>No</u>		
Dewatering device clogged.	<u>NA</u>		
Cracking or crushing of pipes.	<u>NA</u>		
Other.	<u>-</u>		

COMMENTS: Pond constructed 2023, dam raised 2024. Sed marker to be installed.
Vegetation still filling in.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham RobertsSIGNATURE: *Sh Dh*DRAINAGE: **WEST BUZZRD**DATE OF INSPECTION: 10-15-24

POND IDENTIFICATION	West Buzzard #3	West Buzzard #4
Approximate water level:	0%	0%
Sediment level (% total storage):	Min-0%	Min-0%
Outflow (cfs):	0 cfs	0 cfs
Sediment marker (install or replace)	In progress - install	In progress - install
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	Yes
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	NA	NA
Cracking or crushing of pipes.	NA	NA
Other.	-	-
COMMENTS:		

WB#4 - Constructed 2023 - Veg still filling in. Seed marker to be installed

WB# - Recently cleaned, seed marker to be installed



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **IMPOUNDMENT H**DATE OF INSPECTION: 10/15/2025

POND IDENTIFICATION	Impoundment H		
Approximate water level:	15'.		
Sediment level (% total storage):	5'.		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			



DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 10/21/2024

POND IDENTIFICATION		Industrial Waste Pond #1
Approximate water level:		80%
Sediment level (% total storage):		5%
Outflow (cfs):		0
Sediment marker (install or replace)		N/A
Identification sign (install or replace)		In-Place
EROSIONAL:		
Rills and/or gullies on downstream face.		No
Rills and/or gullies on upstream face.		No
Inadequate vegetation.		No
Outlet channel erosion.		No
Burrows.		No
Erosion of toe.		No
Water impounded against downstream toe.		No
Other.		N/A
STRUCTURAL:		
Differential settling.		No
Cracks, slides, or scarps.		No
Seepage (specify location, color, value).		No
Defective spillways.		No
Other.		N/A
APPURTENANT STRUCTURES:		
Defective spillways.		N/A
Dewatering device clogged.		N/A
Cracking or crushing of pipes.		N/A
Other.		
COMMENTS:		

