

Jesse - DNR, Todd <todd.jesse@state.co.us>

## **Q3 Report Reviews**

1 message

Jesse - DNR, Todd <todd.jesse@state.co.us>

Wed, Nov 6, 2024 at 11:31 AM

To: Kurt Blunt <kblunt@deserado.com>

Cc: Clayton Wein - DNR <clayton.wein@state.co.us>, Travis Marshall - DNR <travis.marshall@state.co.us>

Kurt,

Please see the attached Review Letters from the Q3 Pond & Subsidence Report, DMR Report and Wastebank Report.

Hope you have a good day.

Thanks, Todd

**Environmental Protection Specialist** Minerals Program, Grand Junction Field Office

## 3 attachments



2024-11-05 3rdQuarter 2024 DMRs Review Letter C-1981-018.pdf



2024-11-05 3rd Quarter Coal Waste Bank Report Review Letter C-1981-018.pdf 171K

2024-11-05 3rd Quarter Pond Inspection Report and Subsidence Monitoring Report Review Letter C-1981-🔁 018.pdf

202K



November 5, 2024

Kurt Blunt Blue Mountain Energy, Inc. 3607 County Rd. 65 Rangely, CO 81648

RE: Deserado Mine, Permit No. C-1981-018
3rd Quarter 2024 Sediment Pond Inspection Report and 3rd Quarter 2024
County Road 65 Subsidence Monitoring Report

Dear Kurt,

The Division of Reclamation, Mining and Safety (the Division) has reviewed the Sediment Pond Inspection Report and the County Road 65 Subsidence Monitoring Report for the 3<sup>rd</sup> Quarter of 2024. The reports were received on October 29, 2024. The Division finds the reports to be in compliance with the following Rules:

## 3rd Quarter 2024 Sediment Pond Inspection Report

**4.05.9(17)** – All impoundments are inspected quarterly, by a qualified person designated by the operator, for the appearance of structural weakness and other hazardous conditions. The reports are retained at the Deserado Mine Office, and copies of the reports are submitted to the Division on a quarterly basis.

**4.05.9(15)(a)** – No indications of seepage, erosion or animal burrows were identified in the 3<sup>rd</sup> quarter. Spillways for the ponds were noted to be in good repair and functional. SDH-3M has been listed as having channel erosion and a defective spillway for multiple reports. The pond has not been used since this issue was observed. The SDH-3L pond substitutes for the SDH-3M pond.

**4.05.9(15)(b)** – The existing required monitoring procedures were met.

**4.05.9(15)(c)** - The amount of water impounded in the ponds was documented in the report.

**4.05.9(15)(d)** – The existing storage capacity of the impoundments was documented in the report.

**4.05.9(15)(e)** – The 3<sup>rd</sup> quarter report did not list any other aspects of the structure affecting stability or requiring maintenance.

During the 3<sup>rd</sup> quarter, the Portals Area Pond/DP-1 (001), the B Seam Dewatering System No. 1 (029), SDH 3/5 (026) and the Raw Water Lagoon (045) recorded discharging.



3<sup>rd</sup> Quarter Pond Inspection Report and Subsidence Monitoring Report Review

3<sup>rd</sup> Quarter 2024 County Road 65 Subsidence Monitoring Report 2.05.6(6) – The report stated that no mining had occurred under County Road during the 3<sup>rd</sup> quarter. No surface cracks or differential settlement were observed. No other indications of damage were indicated in the report.

This concludes the Division's review of the Sediment Pond Inspection Report and the County Road 65 Subsidence Monitoring Report for the 3<sup>rd</sup> Quarter of 2024. If you have any questions, please contact me at (720) 688-0626

Sincerely,

Todd Jesse

**Environmental Protection Specialist** 

todd.jesse@state.co.us

Travis Marshall, DRMS, Senior Environmental Protection Specialist GJFO cc:

Clayton Wein, DRMS, Environmental Protection Specialist