



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review 2024 Q3Compliance Reports: DMRs and Sed Pond Reports

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Nov 1, 2024 at 5:41 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Evening Miranda,

Please find DRMS's review of the 2024 Q3 DMRs and Sediment Pond reports for Peabody Sage Creek Mine. The Division has no concerns.

Thank you for the timely submission of the reports.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

2 attachments



Review_DMR_2024_Q3_SgCk.pdf

268K



Review_SEdPond_2024__Q3_SgCk.pdf

268K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

Peabody Sage Creek Mining, LLC
Ms. Miranda Kawcak
29515 Routt County Road No. 27
Oak Creek, CO 80467

1 November 2024

**Re: Peabody Sage Creek Mine (Permit No. C2009-087)
Review Sediment Pond Report 2024 Q3**

Dear Ms. Miranda Kawcak:

The Division has received and reviewed the quarter three Sediment Pond Report, for the Peabody Sage Creek Mine. The Sediment Pond Report was received electronically by the Division on 31 October 2024. Thank you for your timely submittal of this information. Peabody Sage Creek Mine submits Sediment Pond Report to the Division, in accordance with Rule 4.05.9(17). The inspection took place over several days in September 2024 and was conducted by Miranda Kawcak.

Peabody Sage Creek Mine reported the following Pond/outfalls discharged in September.

- Pond 2 NPDES 002
- Pond 3 NPDES 003
- Final Pit Impoundment
- Lower Sump, diked pond
- Upper Sump, diked pond
- Portal Sump #1 upper north
- Portal Sump #2 lower south

Pond banks were in good repair and trash racks were clear at the time of inspection. The Pond 2 flume requires resetting and rodent burrows around the site need ongoing maintenance. The Professional Engineer Certification was included in the submittal.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

