

Reilley - DNR, Robin <robin.reilley@state.co.us>

2024 Q3 Compliance Reports - Williams Fork Mine

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Wed, Nov 13, 2024 at 5:46 PM To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Evening Miranda,

Please find DRMS's review of the 2024 Q3 Compliance Reports for the Williams Fork Mine. The Division has no concerns.

Thank you for the timely submission of the reports.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II

image.png

P 303.866.3567 F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

3 attachments

Review_DMR_2024_Q3_WF.pdf

WastePile_Review_2024Q3_WF.pdf

Review_Ponds_2024_Q3_WF.pdf
251K



1 November 2024

Ms. Miranda Kawcak Moffat County Mining, LLC. 29515 Routt County Road #27 Oak Creek, CO 80467

RE: Refuse Pile Report Review: 2024 Quarter 3 Williams Fork Mines, Permit No. C1981044

Dear Ms. Kawcak;

The Colorado Division of Reclamation, Mining and Safety has completed its review of the above referenced report. Please see the Division's findings below regarding the report's compliance with the following Rules.

1. 4.10.2(1)

- a. The mine waste bank was inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer, or other qualified professional specialist.
- b. The waste bank was capped in December 2020 and topsoil was placed on the surface of the waste pile.
- c. The #9 excavation waste disposal area was reclaimed in 2009.
- 2. 4.10.2(2)
 - a. The submitted inspection report complies with the inspection requirement of rule 4.09.1(11).
 - This was a quarterly inspection.
 - The report indicated the stability of the fills was inspected and no appearances of instability, structural weakness or other hazardous conditions were noted. The inspection was conducted on 26 September 2024 and the report received by DRMS on 31 October 2024.
 - b. The stability of the fills was inspected. Tests were not necessary to evaluate any potential hazard to human life and property.
 - Stability of the waste disposal areas was inspected, and no problems were identified. No maintenance items were required at the time of inspection.
 - c. Copies of the inspection findings shall be maintained at the mine site.
- 3. 4.10.2(3)

No potential hazards were noted in the above referenced refuse pile inspection report.Vegetation is establishing.

Sincerely, Bobin Keilley

Robin Reilley M.S. GISP Environmental Protection Specialist II

