

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond A		SW/4 NW/4 Sec.32 T5N R86W	
	N/A		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)		X		433.2
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6937.3 Feet

Lowest Hole: 6933.5 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Recessed, Double Cell	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond B		SW/4 NE/4 Sec.31 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)		X		23.5
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required		X		Sediment sump cleared in October, Snow
Maintenance Performed		X		
Additional Comments			X	

Embankment Crest: 6,872 Feet

Weir: 6866.3 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond C		SW/4 NE/4 Sec.31 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other				
MAINTENACE				
Maintenance Required			X	Snow Covered
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6864.4 Feet

Lowest Hole: 6862.3 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond D		SW/4 NW/4 Sec.32 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)		X		374.2
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6849.9 Feet

Lowest Hole: 6846.5 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Recessed, Double Cell	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond E		SW/4 NW/4 Sec.32 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)		x		9.6 GPM
Outflow (gpm)		x		
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6843.4 Feet

Lowest Hole: 6840.6 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond F		SW/4 SE/4 Sec.29 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	Snow Covered
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6827 Feet

Dewatering Hole: 6823 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond G		SW/4 SE/4 Sec.29 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	Snow Covered
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6833.24 Feet

Lowest Hole: 6830.34 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pond T		NW/4 SW/4 Sec.31 T5N R86W	
	CO0027154		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6907.9 Feet

Lowest Hole: 6904.9 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Recessed Highwall Pit	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Pit Pond		SW/4 NW/4 Sec.32 T5N R86W	
	N/A		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Riser Crest: 6854.11 Feet

Bottom of Dewatering Culvert: 6851.47 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Fish Creek Tipple Pond		SE/4 NE/4 Sec.02 T5N R86W	
	CO0036684		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	0 GPM
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	Culvert Replaced, No Discharge Yet
Maintenance Performed			X	
Additional Comments		X		

Top of Rise Riser Crest: 55.0 Feet

Dewatering Hole: 51.8 Feet

Mining Area	Foidel Creek Mine	Facility Configuration	Embankment Pond		Quarterly Impoundment Inspection Form				
Date Inspected	11/27/2024		Date Last Inspected					9/30/2024	
Impoundment	Site 115 FCBH Ponds		Pond Location					SE/4 NE/4 Sec.02 T5N R86W	
NPDES ID No	CO0042161		Site Location					10 mi. NW of Oak Creek, CO	
Owner's Rep	Miranda Kawcak	Inspector	Mike Howard						
Mark or Write in Appropriate Response:									
FEATURE		PROBLEM					COMMENTS		
		YES (Above)	NO (Below)	YES (Above)	NO (Below)	YES (Above)		NO (Below)	
GENERAL		CELL #1		CELL #2		CELL #3			
Water Level (above or below principal spillway)			X		X		X		
Outflow (gpm)		0 GPM		0 GPM		0 GPM			
EROSION									
Rills & Gullies on Embankment			X		X		X		
Wave Erosion			X		X		X		
Spillway Erosion			X		X		X		
Burrows			X		X		X		
Other			X		X		X		
STRUCTURAL									
Differential Settling			X		X		X		
Cracks or Slides			X		X		X		
Seepage			X		X		X		
Other			X		X		X		
STRUCTURES									
Principal Spillway									
Clogged Orifice			X		X		X		
Clogged or Damaged Culvert			X		X		X		
Damaged Headgate			X		X		X		
Emergency Spillway									
Erosion			X		X		X		
Riprap			X		X		X		
Clogged or Damaged Culvert			X		X		X		
Other			X		X		X		
MAINTENACE									
Maintenance Required			X		X		X		
Maintenance Performed			X		X		X		
Additional Comments			X		X		X		

Discharge Flume: 6783 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond		Quarterly Impoundment Inspection Form					
	11/27/2024		9/30/2024							
	Waste Water Ponds		SW/4 SE/4 Sec.29 T5N R86W							
	CO0042161		10 mi. NW of Oak Creek, CO							
	Miranda Kawcak		Mike Howard							
Mark or Write in Appropriate Response:										
FEATURE		PROBLEM							COMMENTS	
		YES (Above)	NO (Below)	YES (Above)	NO (Below)	YES (Above)	NO (Below)	YES (Above)		NO (Below)
GENERAL		CELL #1		CELL #2		CELL #3		POLISHING POND		
Water Level (above or below principal spillway)			X		X		X		X	Inflow: 2.7 GPM Outflow: None
Outflow (gpm)										
EROSION										
Rills & Gullies on Embankment			X		X		X		X	
Wave Erosion			X		X		X		X	
Spillway Erosion			X		X		X		X	
Burrows			X		X		X		X	
Other			X		X		X		X	
STRUCTURAL										
Differential Settling			X		X		X		X	
Cracks or Slides			X		X		X		X	
Seepage			X		X		X		X	
Other			X		X		X		X	
STRUCTURES										
Principal Spillway										
Clogged Orifice			X		X		X		X	
Clogged or Damaged Culvert			X		X		X		X	
Damaged Headgate			X		X		X		X	
Emergency Spillway										
Erosion			X		X		X		X	
Riprap			X		X		X		X	
Clogged or Damaged Culvert			X		X		X		X	
Other			X		X		X		X	
MAINTENANCE										
Maintenance Required			X		X		X		X	No flow into cell #2
Maintenance Performed			X		X		X		X	
Additional Comments			X		X		X		X	

POND#1

Berm Crest: 6871.5; Pond Bottom: 6861.5

POND#2

Berm Crest: 6858.5; Pond Bottom: 6848.5

POND#3

Berm Crest: 6852.5; Pond Bottom: 6842.5

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	6MN Sediment Pond		SE/4 NW/4 Sec.17 T5N R86W	
	COG850051		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	No Discharge
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	Snow Covered
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Embankment Pond		Quarterly Impoundment Inspection Form	
	11/27/2024		9/30/2024			
	18Left Sediment Ponds		NW/4 SW/4 Sec.23 T5N R87W			
	COG850054		10 mi. NW of Oak Creek, CO			
	Miranda Kawcak		Mike Howard			
Mark or Write in Appropriate Response:						
FEATURE		PROBLEM				COMMENTS
		YES (Above)	NO (Below)	YES (Above)	NO (Below)	
GENERAL						
		UPPER POND		LOWER POND		
Water Level (above or below principal spillway)			X		X	No Discharge
Outflow (gpm)			X		X	
EROSION						
Rills & Gullies on Embankment			X		X	
Wave Erosion			X		X	
Spillway Erosion			X		X	
Burrows			X		X	
Other			X		X	
STRUCTURAL						
Differential Settling			X		X	
Cracks or Slides			X		X	
Seepage			X		X	
Other			X		X	
STRUCTURES						
Principal Spillway						
Clogged Orifice			X		X	
Clogged or Damaged Culvert			X		X	
Damaged Headgate			X		X	
Emergency Spillway						
Erosion			X		X	
Riprap			X		X	
Clogged or Damaged Culvert			X		X	
Other			X		X	
MAINTENACE						
Maintenance Required			X		X	
Maintenance Performed			X		X	
Additional Comments			X		X	

Upper Pond Riser Outet: 6860.5 Feet

Lower Pond Berm Embankment: 6855.5 Feet

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Foidel Creek Mine	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Recessed Pit	Quarterly Impoundment Inspection Form
	11/27/2024		9/30/2024	
	Thickener Holding Pond		SW/4 NW/4 Sec.32 T5N R86W	
	N/A		10 mi. NW of Oak Creek, CO	
	Miranda Kawcak		Mike Howard	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (above or below principal spillway)			X	
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			X	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Top of Riser Pipe = 6400 ft. (MSL)

Bottom of Headgate = 6397 ft.

Top of Sediment Storage 6395.3 ft.

Mining Area	Foidel Creek Mine	Facility Configuration	Embankment Pond		Quarterly Impoundment Inspection Form						
Date Inspected	11/27/2024		Date Last Inspected							9/30/2024	
Impoundment	Wetland Ponds		Pond Location							SW/4 SE/4 Sec.29 T5N R86W	
NPDES ID No	CO0042161		Site Location							10 mi. NW of Oak Creek, CO	
Owner's Rep	Miranda Kawcak		Inspector							Mike Howard	
Mark or Write in Appropriate Response:											
FEATURE		PROBLEM							COMMENTS		
		YES (Above)	NO (Below)	YES (Above)	NO (Below)	YES (Above)	NO (Below)	YES (Above)		NO (Below)	
GENERAL		CELL #1		CELL #2		CELL #3		CELL #4			
Water Level (above or below principal spillway)		X		X		X		X			
Outflow (gpm)		20 GPM		20 GPM		20 GPM		20 GPM			
EROSION											
Rills & Gullies on Embankment			X		X		X		X		
Wave Erosion			X		X		X		X		
Spillway Erosion			X		X		X		X		
Burrows			X		X		X		X		
Other			X		X		X		X		
STRUCTURAL											
Differential Settling			X		X		X		X		
Cracks or Slides			X		X		X		X		
Seepage			X		X		X		X		
Other			X		X		X		X		
STRUCTURES											
Principal Spillway											
Clogged Orifice			X		X		X		X		
Clogged or Damaged Culvert			X		X		X		X		
Damaged Headgate			X		X		X		X		
Emergency Spillway											
Erosion			X		X		X		X		
Riprap			X		X		X		X		
Clogged or Damaged Culvert			X		X		X		X		
Other			X		X		X		X		
MAINTENACE											
Maintenance Required										20 GPM to 6MN resevoir Inaccessable due to Snow	
Maintenance Performed											
Additional Comments		X		X		X		X			