

Bowie No. 1 Mine PO Box 1488 Paonia, CO. 81428 (970)986-6236

January 15, 2025

Mr. Rob Zuber Department of Natural Resources Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO. 80203

RE: Bowie Resources LLC Bowie No. 1 Mine DRMS Permit No. C-1981-038 Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 4th quarter of 2024. If you have any questions or concerns regarding this submittal, contact me at (970)986-6236.

Sincerely;

Baulkber

Basil R. Bear Mine Manager

	_					
Bowie Resources LLC						
Bowie #1 Mine						
Sedimentation Pond						
Loadout Pond						
Quarter:	4					
Inspection Date:	8-Oct-24					
Inspected By:	brb					
Primary Elevation:	5724.00					
Cleanout Elevation:	5721.00					
Approximate Water Elevat		nenection:		DRY		
Approximate Sediment Eleval				5720.00'		
Outflow (C.F.S.)		or mapection		0.00		
				0.00		
Features:				Comments		
Rills & Gullies on Embank	ment		No			
Inadequate Vegetation			No			
Outlet Channel Erosion			No			
Burrows			No			
Other						
Ctrustural:						
Structural:			Nie			
Differential Settling			No No			
Cracks or Slides						
Seepage Other			No			
Appurtenant Structu	ires					
Defective Spillway			No			
Dewatering Device Clogged			No			
Faulty Gates, Baffles, Pumps			No			
Other			Gate Closed			
	1-					
Additional Commen	ts					
<u></u>						

Bowie Resources LLC	2					
Bowie #1 Mine						
Sedimentation Pond						
Highway Pond						
Quarter:	4					
Inspection Date:	8-Oct-24					
Inspected By:	brb					
Primary Elevation:	5734.00					
Cleanout Elevation:	5734.00					
Approximate Water Elevat		nspection.		DRY		
Approximate Sediment Ele				5727.00'		
Outflow (C.F.S.)			•	0.00		
<b>F</b> actoria e 1						
Features:		ĺ		Comments		
Rills & Gullies on Embank	ment		No			
Inadequate Vegetation			No			
Outlet Channel Erosion			No			
Burrows			No			
Other						
Structural:						
Differential Settling			No			
Cracks or Slides			No			
Seepage			No			
Other						
Appurtenant Structu	ires					
Defective Spillway			No			
Dewatering Device Clogged			No			
Faulty Gates, Baffles, Pumps			No			
Other						
Additional Common	ta					
Additional Commen	15					

Bowie Resources LLC						
Bowie #1 Mine						
Sedimentation Pond						
WM WS-1 Pond						
Quarter: 4						
Inspection Date: 8-Oct-24						
Inspected By: brb						
Primary Elevation: 7,064.50						
Cleanout Elevation: 7,064.50						
Approximate Water Elevation at Time of Inspection:		7064.00'				
Approximate Sediment Elevation at Time of Inspectio	n:	7061.00'				
Outflow (C.F.S.)		0.00				
		•				
Features:		Comments				
Rills & Gullies on Embankment	No					
Inadequate Vegetation	No					
Outlet Channel Erosion	No					
Burrows	No					
Other	No					
		·				
Structural:						
Differential Settling	No					
Cracks or Slides	No					
Seepage	No					
Other						
	•	•				
Appurtenant Structures						
Defective Spillway	No	]				
Dewatering Device Clogged	No					
Faulty Gates, Baffles, Pumps	No					
Other	Gate Closed	1				
Additional Comments						

Bowie Resources LLC	2					
Bowie #1 Mine						
Sedimentation Pond						
WM WS-2 Pond						
Quarter:	4	]				
Inspection Date:	8-Oct-24					
Inspected By:	brb					
Primary Elevation:	7095.80	]				
Cleanout Elevation:	7095.80					
Approximate Water Elevat				7095.30'		
Approximate Sediment Ele				7091.00'		
Outflow (C.F.S.)				0.00		
Features:		L		Comments		
Rills & Gullies on Embank	ment		No			
Inadequate Vegetation			No			
Outlet Channel Erosion			No			
Burrows			No			
Other		No				
Structural:						
Differential Settling			No			
Cracks or Slides			No			
Seepage			No			
Other						
Appurtenant Structu	ires	<u> </u>				
Defective Spillway			No			
Dewatering Device Clogged			No			
Faulty Gates, Baffles, Pumps			No			
Other			Gate Open			
Additional Commen	ts					