



STATE OF COLORADO

Bowles - DNR, Brock <brock.bowles@state.co.us>

Inspection reports- aerials for January

1 message

Bowles - DNR, Brock <brock.bowles@state.co.us>

Mon, Feb 3, 2025 at 12:16 PM

To: Miranda Kawcak <mkawcak@peabodyenergy.com>, "Howard, Michael" <MHoward@peabodyenergy.com>

Miranda and Mike,
Attached are the aerial inspection reports for the Foidel Creek (C-1982-056) and Hayden Gulch LO (C-1992-081) on January 28, 2025.
Brock

--

Brock Bowles
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 720.774.0040 | O 303.866.3567
Physical: 1313 Sherman St., Room 215, Denver, CO 80203
Mailing: Room 215, 1001 E 62nd Ave, Denver, CO 80216
brock.bowles@state.co.us | <https://drms.colorado.gov>

2 attachments

INSP-REPORTC_C1992081_BFB_01302025120544.pdf
377K

INSP-REPORTC_C1982056_BFB_01312025125005.pdf
1080K



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms. Miranda Kawcak 29515 Routt County Road 27 Oak Creek, CO 80467	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private
	Operator Representative Present: N/a
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: January 28, 2025 Inspection Start Time: 13:00 Inspection End Date: January 28, 2025 Inspection End Time: 13:02	Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Brock Bowles	Inspector's Signature:  Signature Date: January 30, 2025

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

- | | |
|------------------------------------|------------------------------------|
| N - Air Resource Protection | N - Roads |
| N - Availability of Records | R - Reclamation Success |
| N - Backfill & Grading | N - Revegetation |
| N - Excess Spoil and Dev. Waste | N - Subsidence |
| N - Explosives | N - Slides and Other Damage |
| N - Fish & Wildlife | N - Support Facilities On-site |
| N - Hydrologic Balance | N - Signs and Markers |
| N - Gen. Compliance With Mine Plan | N - Support Facilities Not On-site |
| N - Other | N - Special Categories Of Mining |
| N - Processing Waste | N - Topsoil |

COMMENTS

This was an aerial inspection of the Hayden Gulch Loadout operated by Hayden Gulch Termnal, LLC. The photos were taken and evaluated by Brock Bowles with the Colorado Division of Reclamation, Mining, and Safety (Division).

The weather was clear on the day of inspection. The site is in final reclamation.

The remaining disturbed areas are the reclaimed railroad track bed directly north and south of Hwy 40. The post mining land use is agricultural hay fields.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The area between the trail head parking lot and Hwy 40 is snow covered (photo 1). The trail head parking lot had been plowed and the trail had been groomed. No other disturbance was noted. Very few grass clumps are seen through the snow indicating the snow is about 12 inches deep.

The area between Hwy 40 and the mainline is snow covered (photo 2). No disturbances were noted in this area. The grasses are more robust on this part of the reclamation and can be seen through the snow. The ditches are full of snow.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Photo 1- Area between Hwy 40 and Trail head parking lot



Photo 2- Area between Mainline and Hwy 40

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2