




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

| | | | |
|---|--|---|-----------------------------|
| MINE NAME: Mott Gravel Pit | MINE/PROSPECTING ID#: M-1980-049 | MINERAL: Sand and gravel | COUNTY: Montrose |
| INSPECTION TYPE: Monitoring | WEATHER: Clear | INSP. DATE: January 23, 2025 | INSP. TIME: 16:00 |
| OPERATOR: Delta County | OPERATOR REPRESENTATIVE: None | TYPE OF OPERATION: 110c - Construction Limited Impact | |
| REASON FOR INSPECTION: Normal I&E Program | BOND CALCULATION TYPE: None | BOND AMOUNT: \$0.00 | |
| DATE OF COMPLAINT: NA | POST INSP. CONTACTS: None | JOINT INSP. AGENCY: None | |
| INSPECTOR(S): Dustin Czapla | INSPECTOR'S SIGNATURE:  | SIGNATURE DATE: January 30, 2025 | |

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

| | | |
|---|---|----------------------------------|
| (AR) RECORDS----- <u>Y</u> | (FN) FINANCIAL WARRANTY----- <u>NA</u> | (RD) ROADS----- <u>Y</u> |
| (HB) HYDROLOGIC BALANCE----- <u>Y</u> | (BG) BACKFILL & GRADING----- <u>Y</u> | (EX) EXPLOSIVES----- <u>NA</u> |
| (PW) PROCESSING WASTE/TAILING---- <u>NA</u> | (SF) PROCESSING FACILITIES----- <u>NA</u> | (TS) TOPSOIL----- <u>Y</u> |
| (MP) GENL MINE PLAN COMPLIANCE- <u>Y</u> | (FW) FISH & WILDLIFE----- <u>Y</u> | (RV) REVEGETATION---- <u>N</u> |
| (SM) SIGNS AND MARKERS----- <u>Y</u> | (SP) STORM WATER MGT PLAN---- <u>NA</u> | (RS) RECL PLAN/COMP-- <u>N</u> |
| (ES) OVERBURDEN/DEV. WASTE----- <u>NA</u> | (SC) EROSION/SEDIMENTATION--- <u>Y</u> | (ST) STIPULATIONS----- <u>NA</u> |
| (AT) ACID OR TOXIC MATERIALS----- <u>NA</u> | (OD) OFF-SITE DAMAGE----- <u>NA</u> | |

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report to illustrate some of the conditions observed.

The Mott Gravel Pit is located approximately five miles south of Crawford and accessed from Clear Fork Road. The site is a 110c operation that includes a total of 9.74 permitted acres.

Pursuant to Rule 4.1.2 (2), a financial warranty is not required for this site.

Adequate mine identification signage was posted on the gate at the entrance to the site.

The affected area was marked by fencing and posts that were clearly visible and adequate to delineate the affected area boundary.

Mining was not occurring during this inspection. Crushed gravel stockpiles are located in the storage area on the north side of the pit. The pit currently covers approximately three acres. The pit is approximately twenty feet in depth, with a near vertical highwall that spans the perimeter of the pit, approximately 1,400 linear feet. Overburden is stockpiled above the southeast rim of the pit. The salvaged topsoil is stockpiled in a berm along the west side of the pit. No erosional concerns were noted. A scale and scale house are located on the west side of the pit.

No problems related to disturbance of the prevailing hydrologic balance were noted. The operation has not exposed groundwater.

There are no processing facilities on site, and thus no processing waste.

Fuels or toxic materials are not stored on site. Acid generating materials are not exposed by the mining operation.

No offsite damage was noted.

Explosives are not used for this mining operation.

Mining is ongoing and final reclamation has not yet commenced.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (303) 866-3567.

Inspection Contact Address

Tim McCracken
Delta County
295 West 6th Street
Delta, CO 81416



