



COLORADO


Division of Reclamation,
Mining and Safety

Department of Natural Resources

MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: BLM Olathe Pit	MINE/PROSPECTING ID#: M-1986-037	MINERAL: Sandstone	COUNTY: Montrose
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: January 23, 2025	INSP. TIME: 14:30
OPERATOR: Colorado Department of Transportation	OPERATOR REPRESENTATIVE: NONE	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: January 30, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>NA</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report to illustrate some of the conditions observed.

The BLM Olathe Pit is located approximately 5.5 miles southwest of Olathe and accessed from H-54 Road. The site is a 110c operation that includes a total of 4.8 permitted acres.

Pursuant to Rule 4.1.2 (2), a financial warranty is not required for this site.

Adequate mine identification signage was bolted to a boulder at the entrance to the site.

The affected area was marked by a perimeter berm that was clearly visible and adequate to delineate the affected area boundary.

The site was inactive during this inspection. Signs of any recent activity were not evident. No equipment was stored on site.

Piles of stone and dirt are located randomly within the bermed area. No processed materials stockpiles were seen on site.

No problems related to disturbance of the prevailing hydrologic balance were noted. The operation has not exposed groundwater. Stormwater runoff is contained within the pit. The porous nature of the pit walls prevents ponding through infiltration.

There are no processing facilities on site, and thus no processing waste.

Fuels or toxic materials are not stored on site. Acid generating materials are not exposed by the mining operation.

No offsite damage was noted.

Explosives are not used for this mining operation.

Final reclamation has not yet commenced.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (303) 866-3567.

Inspection Contact Address

Lee DeGraffenried
Colorado Department of Transportation
606 S. 9th. Street
Grand Junction, CO 81501

