

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Harold Eichman Gravel Pit		M-1985-105	Sand and gravel	Lincoln
INSPECTION TYPE:		WEATHER: Clear	INSP. DATE:	INSP. TIME:
Monitoring			February 12, 2025	11:00
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Lincoln County			112c - Construction Regular Operation	
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program			\$0.00	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
INSPECTOR(S):	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
Ben Hammar			February 20, 2025	
	Ellman			

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>NA</u>	(FN) FINANCIAL WARRANTY <u>NA</u>	(RD) ROADS <u>NA</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING <u>NA</u>	(SF) PROCESSING FACILITIES <u>NA</u>	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE <u>NA</u>	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN <u>NA</u>	(RS) RECL PLAN/COMP <u>N</u>
(ES) OVERBURDEN/DEV. WASTE <u>NA</u>	(SC) EROSION/SEDIMENTATION Y	(ST) STIPULATIONS <u>NA</u>
(AT) ACID OR TOXIC MATERIALS <u>NA</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Harold Eichman Pit was inspected by Ben Hammar of the Division of Mining, Reclamation, and Safety (The Division) as part of the Division's regular monitoring program, who was accompanied by Ty Stogsdill, a representative of Lincoln County. The Harold Eichman Pit is located approximately 13 miles southeast of Truckton, CO. The pit is a 110c operation permitted for 9.9 acres and the primary commodity is construction materials. The post-mining land use is rangeland. The weather was cold and dry at the time of inspection and the ground was covered in snow.

The site was not active at the time of inspection. This is an intermittent operation, so no recent activity is not an issue at this time. The mine sign was clearly posted at the site entrance, and appeared to be in good condition. Site boundaries were marked with T posts and appeared to be in good condition at the time of inspection.

A single topsoil stockpile is located on the northern portion of the site and appeared to be stable. No vegetation was able to be observed at the time of inspection due to snow cover. Mining appears to be proceeding along a single highwall located in the eastern portion of the pit. Material is then stockpiled within the middle of the permit.

Generally the site appeared to be in good condition, with no notable issues present. As this is a county site, no bond is held for this location.

Inspection Contact Address

Lincoln County P.O. Box 39 Hugo, CO 80821

Enclosure

CC:

PERMIT #: M-1985-105 INSPECTOR'S INITIALS: BEH INSPECTION DATE: February 12, 2025

PHOTOGRAPHS



Photo 1: Posted mine ID sign.



Photo 2: Representative photo of pit floor and associated product stockpiles.



Photo 3: Example boundary marker (right), and example topsoil stockpile (left).