

Reilley - DNR, Robin <robin.reilley@state.co.us>

# March Inspections Williams Fork, Seneca IIW and Yoast

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Mar 12, 2025 at 9:37 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Evening Miranda,

Please find DRMS's March 2025 inspection reports for the above referenced sites.

Robin Reilley, M.S. GISP Environmental Protection Specialist II




P 303.866.3567| F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

#### 3 attachments

Insp\_Complete\_WilliamsFork\_2025\_03\_March.pdf 1113K



Insp\_Partial\_Yoast\_2025\_03\_March.pdf



### 11 March 2025

## **PERMIT INFORMATION**

Permit Number: C-1981-044
Mine Name: Williams Fork Mines
Operator: Moffat County Mining, LLC
Operator Address:
Ms. Miranda Kawcak
29515 Routt County Road #27
Oak Creek, CO 80467

County: Moffat
Operation Type: Underground
Permit Status: Active
Ownership: Private

Operator Representative Present:
Miranda Kawcak

This report was issued electronically from the Divisions' Denver Office.

## **INSPECTION INFORMATION**

Inspection Start Date: 11 March 2025 Inspection Start Time: 12:00 a.m. Inspection End Date: 12 March 2025 Inspection End Time: 11:00 a.m.	Inspection Type: Complete Inspection Inspection Reason: Normal I&E Program Weather: Cloudy
Joint Inspection Agency:	Joint Inspection Contacts:
None	No
Post Inspection Agency:	Post Inspection Contacts:
None	No
Inspector(s):	Inspector's Signature: Signature Date:
Robin Reilley, M.S. GISP	Bobin Leiller 12 March 2025

# **AVAILABILITY OF RECORDS**

PERMIT RECORDS		HYDROLOGIC RECORDS		
DRMS Permit	RN 8 2023	NPDES Permit	Yes	
Permit Application w/Revisions	Yes	NPDES Records	Miranda's elec	
Findings Document	RN8 2023 MT8	Stormwater Management Plan	Yes	
Insurance Certificate	Exp. Aug 2025	SPCC Plan	Yes	
Bond Document	Yes	MSHA Pond Inspections	NA	
Phased Bond Release	SL 4 and 5		NA	
Documents/Findings	Miranda Office	State Engineer's Pond Inspection		
Air Emission Permits	Yes	Quarterly Pond Inspections	2024 Q3	
County Special Use Permits	Yes	Annual Hydrology Reports	2023	
<b>UG Mining Landowner Notification</b>	Yes	<ul> <li>Ground Water Monitoring</li> </ul>	Yes	
Subsidence Monitoring Reports	Yes	<ul> <li>Surface Water Monitoring</li> </ul>	Yes	
Subsidence Monitoring Data	NA	<ul> <li>Spring &amp; Seep Monitoring</li> </ul>	Yes	
Rill & Gully Survey	2018	<ul> <li>Mine Water Discharge Monitoring</li> </ul>	Yes	
Vegetation Monitoring Data	Miranda's office	<ul> <li>Mine Inflow Study</li> </ul>	Yes	
Specific Variance Approvals	NA	Water Consumption Records	Yes	
Annual Reclamation Reports	2023	Well Permits	Yes	
Midterm Review Documents	MT8 2021			
DRMS/OSM Inspection	Miranda's Office			
Reports/Enforcement Actions (3	elec			
Years)		BLASTING RECORDS		
Transfers/Succession of Operator	2006	Blasting Publication	NA	
Temporary Cessation Notification	2016 deactivated	Blasting Records (3 years)	NA	
Reclamation Cost Estimate	RN8	ATFE Explosives Permit	NA	
CERTIFICATIONS	Permit	Blasting Variances	NA	
Pond Certifications		Pre-Blast Surveys	NA	
Annual Certifications for	2024 Q3			
Impoundments				
Fill Certifications for Excess Spoil	NA	ADDITIONAL RECORDS		
or Underground Development Waste		(specify)		
<ul> <li>Quarterly Inspections</li> </ul>	NA			
<ul> <li>Compaction Testing</li> </ul>	NA			
<ul> <li>Final Certification</li> </ul>	NA			
Coal Processing Waste Banks	reclaimed 2020			
	2024 Q3			
Haul Road Certifications	Permit			
Access Road Certifications	Permit			
COMMENTS: Items highlighted in yellow require addressing.				
Refuse pile report is included with pond reports				

Inspection Topic Summary		
NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable		
R - Air Resource Protection	R - Roads	
R - Availability of Records	Y - Reclamation Success	
NA - Backfill & Grading	R - Revegetation	
R - Excess Spoil and Dev. Waste	Y - Subsidence	
NA - Explosives	Y - Slides and Other Damage	
R - Fish & Wildlife	Y - Support Facilities On-site	
R - Hydrologic Balance	R - Signs and Markers	
R - Gen. Compliance With Mine Plan	NA - Support Facilities Not On-site	
NA - Other	NA - Special Categories Of Mining	
NA - Processing Waste	R - Topsoil	

## **COMMENTS**

This was complete inspection of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The inspection was conducted, and the report prepared by me, Robin Reilley of the DRMS. Miranda Kawcak, mine representative was present throughout the inspection. No hydrologic or air quality issues were detected over the course of the inspection. Conditions were cloudy, with a stiff breeze, and the temperature was approximately 35 degrees Fahrenheit. Vegetation throughout the site was mostly dormant with some grasses beginning to green at the time of inspection.

#### **INSPECTION**

GENERAL MINE PLAN COMPLIANCE:

#### SIGNS and MARKERS – Rule 4.02

- o The mine identification signs were in place at the site entrances along State Highway 13.
- The signs were intact, displaying all required information: mine name, operator name, address, phone number, DRMS permit number and contact information.

## ROADS - Rule 4.03

Construction 4.03.1(3) I 4.03.2(3); Drainage 4.03.1(4) I 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) I 4.03.2(5) and (6); Reclamation 4.03.1(7) I 4.03.2(7)

- o Main haul roads were dry and in good repair.
- Ditches throughout the site and along haul roads appeared to be functioning adequately. All ditches were dry at the time of inspection.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Drainage-Acid and Toxic Materials 4.05.8; Impoundments 4.05.6,4.05.9; Stream Buffer Zones 4.05.18

- o Pond banks and dams appeared stable and vegetated with no signs of seepage.
- o North facing banks held snow.
- o Ditches throughout the site, along haul roads and in the cropland area appeared to be functioning adequately.
- o All ponds were dry at the time of inspection.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of <u>Complete</u> Inspections this Fiscal Year: 3

#### TOPSOIL - RULE 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4

- o No instability or rills were noted on the observed topsoil piles. Topsoil piles are vegetated.
- o Topsoil piles exist at the ponds for future pond reclamation.
- o Topsoil piles are marked with a t-stake.

#### COAL MINE WASTE BANKS-RULE 4.10

General Requirement 4.10.1; Site Inspection 4.10.2; Water Control Measures 4.10.3; Construction Requirements 4.10.4

- o Refuse pile was reclaimed, in 2020 and is capped, topsoiled and seeded.
- o The refuse pile appears stable with no significant rills or gullies forming.

#### SLIDES and OTHER DAMAGE- Rule 4.12

 No recent slides, slumps, cracking, subsidence or other damage was observed over the course of the inspection.

#### BACKFILL and GRADING - RULE 4.14

- o Reclamation of the 5A Portal area is complete.
- o Backfilling, grading, topsoil and seeding occurred in 2023 at the 5A Porta

#### REVEGETATION - Rule 4.15

General Requirements 4.15.1; Use of Species 4.15.2, Grazing 4.15.5

- o Revegetated areas of reclamation appeared stable and dormant the time of inspection.
- 5A Portal area exhibits predominantly dormant vegetation with some small chamisa and sage shrubs and grasses beginning to green.
- Vegetation throughout the site appeared dormant at the time of inspection.
- o Croplands exhibited dormant stubble.
- o No significant weeds were noted at the time of inspection.

#### FISH and WILDLIFE-RULE 4.18

o Wildlife sightings included red and white tailed hawks, ravens, and a few pronghorn.

## INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5

*Inspections 5.02; Availability of Records* 

o As this was a complete inspection, records were checked, see highlighted items.

#### **DOCUMENTS RECEIVED**

None

#### ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of <u>Complete</u> Inspections this Fiscal Year: 3

## **PHOTOGRAPHS**



**Photo 1:** Williams Fork bottom lands looking west from above.



Photo 2: Williams Fork bottom lands below the Portal, looking west.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of <u>Complete</u> Inspections this Fiscal Year: 3



Photo 3: Williams Fork



**Photo 3:** Williams Fork portal area, typical dormant weedy vegetation on recently reclaimed slopes.

Number of <u>Partial</u> Inspection this Fiscal Year: 5 Number of <u>Complete</u> Inspections this Fiscal Year: 3

Page **5** of **6**