

Zuber - DNR, Rob <rob.zuber@state.co.us>

Aerial inspection of Bowie #1

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>

Wed, Apr 2, 2025 at 8:39 AM

To: Art Etter <AEtter@wolverinefuels.com>, Ryan Wilson <RWilson@wolverinefuels.com>, Tamme Bishop <tammekb@gmail.com>

Hi, Art -

Due to turbulence and other issues, we did not take photos of the East Mine ponds or the loadout. But here is my report.

See you tomorrow if you are around.

Rob

Rob Zuber, P.E. Environmental Protection Specialist Active Mines Program



Phone: 720.601.2276 | Fax: 303.832.8106

Physical Address:

1313 Sherman Street, Room 215

Denver, CO 80203

Address for FedEx or UPS:

Division of Reclamation, Mining and Safety, Room 215

1001 East 62nd Avenue Denver, CO 80216

rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC_C1981038_RDZ_04022025.pdf 418K



PERMIT INFORMATION

Permit Number: C-1981-038 Mine Name: Bowie No. 1 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Art Etter P.O. Box 1488 Paonia, CO 81428	County: Delta Operation Type: Underground Permit Status: Active Ownership: Private Operator Representative Present:		
Operator Representative Signature: (Field Issuance Only)			

INSPECTION INFORMATION

Inspection Start Date: March 26, Inspection Start Time: 12:15 Inspection End Date: March 26, Inspection End Time: 12:30		Inspection Type: Ae Inspection Reason: Meather: Clear		
Joint Inspection Agency: Joint		Joint Inspection Contacts:	oint Inspection Contacts:	
None				
Post Inspection Agency: P		Post Inspection Contacts:		
None				
Inspector(s):	Inspector	r's Signature:	Signature Date:	
Robert Zuber, P.E. Hunter Ridley	Phot D. Th. 4/2/2025			

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection Y - Roads

N - Availability of Records R - Reclamation Success

NA - Backfill & Grading
N - Excess Spoil and Dev. Waste
R - Subsidence

NA - Explosives

Y - Slides and Other Damage

N - Fish & Wildlife

NA - Support Facilities On-site

R - Hydrologic Balance N - Signs and Markers

R - Gen. Compliance With Mine Plan
 N - Support Facilities Not On-site
 N - Other
 NA - Special Categories Of Mining

N - Processing Waste N - Topsoil

COMMENTS

On March 26, 2025, Hunter Ridley of DRMS took aerial photographs of the mine. The weather was clear. Rob Zuber of DRMS reviewed the photos on March 31, 2025.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the West Mine were dry or mostly dry. No erosion or other problems were seen with the embankments or other portions of these ponds. No other ponds were inspected.

GENERAL MINE PLAN COMPLIANCE:

None of the photographs indicated that any parts of the mine permit are contributing significant sediment loads or other pollutants to adjacent off-site areas.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The West Mine was inspected, including the area near the creek, the road to the creek, and the West Mine Fan area. No erosion or other problems were identified.

SUBSIDENCE – Rule 4.20:

Several photographs covered the area above mine workings. No evidence of subsidence was seen.

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3 **DOCUMENTS RECEIVED - none OTHER (SPECIFY) - none**

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS

Reclaimed West Mine Fan area



Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3