




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Dolezal Gravel Pit	MINE/PROSPECTING ID#: M-1996-073	MINERAL: Gravel	COUNTY: Sedgwick
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: March 25, 2025	INSP. TIME: 10:30
OPERATOR: Sedgwick County	OPERATOR REPRESENTATIVE: Kacey Campbell, Bob Coty	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Joel Renfro	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: April 30, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Dolezal Gravel Pit was inspected by Joel Renfro with the Division of Reclamation, Mining and Safety on March 25, 2025 as a part of the Divisions regular monitoring program. Kacey Campbell and Bob Coty with Sedgwick County Road and Bridge were present during the inspection. The Dolezal Gravel Pit is located approximately 4.5 miles south of Big Springs, Nebraska. The weather was clear at the time of inspection.

Photos 1-6 taken during the inspection are included with this report.

This is a 110c operation permitted for extracting gravel. The permit area is 9.9 acres. The post-mine land use is rangeland. The site was active at the time of inspection.

The gravel material from the site is mined and used in county road maintenance as needed. Material stockpiles were observed on the pit floor, which appeared to be new.

The Division observed construction equipment moving around mined material and a haul truck taking material off-site. The site is comprised of one main pit, and it appears that mining is moving to the south. Topsoil is stockpiled along the northern edge of the pit.

Permit boundary markers were checked during the inspection. All the markers are comprised of metal posts with a tire at the base. Each of these markers are placed in the corners of the permit boundary. Each permit boundary marker appeared to be well-maintained and accurately placed.

This concludes the report.

Any questions or comments regarding this inspection report should be forwarded to Joel Renfro at the Colorado Division of Reclamation, Mining, and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, via telephone at (720) 812-2002, or email at joel.renfro@state.co.us.

PHOTOGRAPHS



Photo 1. Mine entrance sign, looking east.



Photo 2. Mine entrance, looking east.



Photo 3. Undisturbed land just south of the pit, looking north.



Photo 4. Corner permit boundary marker south of the pit, looking north.



Photo 5. Mined pit, looking east.



Photo 6. Mined pit, looking north.

Inspection Contact Address

Kacey Campbell, Bob Coty
Sedgwick County
223 S Cedar
Julesburg, CO 80737

CC: Amy Eschberger, DRMS