



STATE OF
COLORADO

Bowles - DNR, Brock <brock.bowles@state.co.us>

Inspection reports

1 message

Bowles - DNR, Brock <brock.bowles@state.co.us>

Thu, May 1, 2025 at 5:20 PM

To: Miranda Kawcak <mkawcak@peabodyenergy.com>, "Howard, Michael" <MHoward@peabodyenergy.com>

Miranda and Michael,
Here are the inspection reports for the Foidel Creek, C-1982-056, and HGLO, C-1992-081.
Brock

--

Brock Bowles
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 720.774.0040 | O 303.866.3567
Physical: 1313 Sherman St., Room 215, Denver, CO 80203
Mailing: Room 215, 1001 E 62nd Ave, Denver, CO 80216
brock.bowles@state.co.us | <https://drms.colorado.gov>

2 attachments



INSP-REPORTC_C1992081_BFB_05012025040858.pdf
3239K




INSP-REPORTC_C1982056_BFB_05012025030134.pdf
4864K



PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms. Miranda Kawcak 29515 Routt County Road 27 Oak Creek, CO 80467	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private
	Operator Representative Present: N/a
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: April 22, 2025 Inspection Start Time: 15:00 Inspection End Date: April 22, 2025 Inspection End Time: 15:30	Inspection Type: OSM Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Brock Bowles	Inspector's Signature:  Signature Date: May 1, 2025

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Roads

N - Availability of Records

N - Reclamation Success

N - Backfill & Grading

R - Revegetation

N - Excess Spoil and Dev. Waste

N - Subsidence

N - Explosives

N - Slides and Other Damage

N - Fish & Wildlife

N - Support Facilities On-site

R - Hydrologic Balance

R - Signs and Markers

N - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

N - Processing Waste

N - Topsoil

COMMENTS

This was a partial inspection of the Hayden Gulch Loadout conducted by Brock Bowles with the Colorado Division of Reclamation, Mining, and Safety (Division). Twentymile Coal, LLC. (TC) was informed of the inspection but declined to attend. The weather at the time of the inspection was clear and warm. The ground was dry with only water in the ditches.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

All the snow had melted, and all the snowmelt water was gone. The site was dry. Some water was in the ditches that traverse the site from east to west (photo 1). No erosion features were seen as the grasses are well established and are controlling erosion.

REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

The grasses were starting to sprout on all parts of the site and adjacent areas (photo 2). The willows were not sprouting yet.

SIGNS AND MARKERS – Rule 4.02:

The mine identification signs were in place (photo 3).

DOCUMENTS RECEIVED**OTHER (SPECIFY)**

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 3

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS

Photo 1 – A small amount of water was still in the ditches



Photo 2- Grasses are starting to sprout for the season north of trailhead parking area.

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 3



Photo 3- Mine identification sign facing Hwy 40

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 3