

May 7, 2025

Ms. Hunter Ridley Environmental Protection Specialist Colorado Division of Reclamation Mining and Safety Department of Natural Resources 1313 Sherman Street, Room 215 Denver, CO 80203

RE: Colowyo Coal Mine L.P. Permit No. C-1981-019 Annual Impoundment Inspections

Dear Ms. Ridley,

Tri-State Generation and Transmission Association Inc. (Tri-State), is the parent company to Axial Basin Coal Company, which is the general partner to Colowyo Coal Company L.P. Therefore, Tri-State on behalf of Colowyo, and in accordance with Rules 4.05.9(14) and 4.05.9(15), is submitting the enclosed annual impoundment and stock pond inspection reports.

If you should have any additional questions, please feel free to contact Tony Tennyson at (970) 824-1232.

Sincerely,

— Docusigned by:

Clivis Gilbreath

D250C711D0BF450...

Chris Gilbreath Senior Manager Remediation and Reclamation

CG:TT Enclosure

cc: Tony Tennyson (via email) Tom Fry (via email) CF 17.18-2025 G471-11.3(21)h-4


### Colowyo Coal Company L.P. Permit No. C-1981-019

#### **Annual Impoundment Inspections** 2025

[	Work Area Pond	Gossard Pond	Stoker Siding Pond	Rail Loop Pond	Prospect Pond	West Pit Pond	Section 16 Pond	Section 15 Pond	Upper Section 3 Pond	Lower Section 3 Pond	East Taylor Pond	West Taylor Pond	Section 28 Pond	Warehouse Pond	Taylor Pump Holding Pond	Evaporation Pond #1	Evaporation Pond #2	Aeration Pond
Inspection Date:	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025
Inspector:	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale
Rule 4.05.9 (15)(a) Does the pond exhibit erosion, instability, structural weakness, or other hazardous conditions?	No	No	Ne Ne	No	No	No	No	No	No	No	No	No	No	No.	No	No	No	No
Rule 4.05.9(15)(b) Existing and required monitoring procedures.	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection
Rule 4.05.9(15)(b) Required Instrumentation	Not Applicable - Nondischarging Structure	Not Applicable - Nondischarging Structure	Parshall Flume In Place and functioning	Not Applicable - Nondischarging Structure	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Not Applicable - Nondischarging Structure	Not Applicable - Nondischarging Structure	11-11-1-1	Parshall Flume In Place and Functioning	Parshall Flume In Place and functioning	Parshall Flume In Place and Functioning	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable
Rule 4.05.9(15)(c) Depth of Impounded Water (ft)*	6.0	3.7	2.3	4.0	9.4	0.0	5.5	1.0	0.0	0.0	14.0	16.0	0.0	6	6	0.5	0	4
Rule 4.05.9(15)(c) Elevation of Impounded	7153.0	6386.7	6325.3	6349.0	6743.4	DRY	7745.5	7546.0	DRY	DRY	6944.0	7471.0	Dry	7200	7062	7060	Dry	7064
Water (ft)*  Rule 4.05.9(15)(d) Existing Storage Capacity (ac-ft)**	9.54	5.22	0,33	1.30	1.78	4.27	0.79	8.91	19.30	18.98	2.60	1.62	2.50	1.48	1.78	Not Applicable - Warehouse Pond Backflow Pond	Not Applicable - Warehouse Pond Backflow Pond	
Rule 4.05.9(15)(e) Any additional items affecting stability or	None	None	None	None	None	None	None	None	None	None	emergency spillway needs new riprap	None	None	None	None	None	None	None

<sup>\*</sup> Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.



<sup>\*\*</sup>Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumilated sediment,

# Colowyo Coal Company L.P. Permit No. C-1981-019

### **Annual Stock Pond Inspections**

### 2025

	PD1	PD2	NTEP1	EP1	EP2	EP3	TD1	TD2	ETD1
Inspection Date:	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025
Inspector:	Trevor Ragsdale	Trevor Ragsdale							
Rule 4.05.9 (15)(a)									
Does the pond exhibit									
erosion, instability,	NO	NO							
structural weakness, or	NO	NO	NO	INO.			Charles Warren		
other hazardous				- Y - 17					
conditions?									
Rule 4.05.9(15)(b)								A	Annual Inspection
Existing and required	Annual Inspection	Annual Inspection							
monitoring procedures.									
Rule 4.05.9(15)(b)		AL 4 A 15 1-1-	NI-+ Amulianda	Net Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable
Required Instrumentation	Not Applicable	1400 Applicable	Trocy, pp. neas.e						
Rule 4.05.9(15)(c)									
Depth of Impounded	7.0	7.0	1.0	3.0	8.0	0.0	3.0	1.0	2.0
Water (ft)*									
Rule 4.05.9(15)(c)							7205.0	7453.0	7285.0
Elevation of Impounded	7355.0	7563.0	7379.0	7373.0	7500.0	Dry	7286.0	7452.0	7205.0
Water (ft)*									
Rule 4.05.9(15)(d)			4.70	4.50	0.15	2.15	0.67	0.98	0.83
Existing Storage Capacity	0.97	1.42	1.70	1.50	9.15	2.15	0.07	0.56	0.05
(ac-ft)** Rule 4.05.9(15)(e)				-					
	Impounded water	Impounded water						cleaning should be	
Any additional items	scheduled to be	scheduled to be	None	None	None	None	None	scheduled in near	None
effecting stability or	pumped	pumped	pumped					future	
maintenance items	1								

<sup>\*</sup> Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.



<sup>\*\*</sup>Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumlated sediment.

## Colowyo Coal Company L.P. Permit No. C-1981-019

## Annual Impoundment Inspections 2025

	Temporary Facilities Pond	Wilson Storage Pond	Section 36 Pond	Middle Pond	Section 25 Pond	Coal Stockpile	Sidehill Pond	Section 26 Pond
Inspection Date:	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025	4/28/2025
Inspector:	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale
Rule 4.05.9 (15)(a)  Does the pond exhibit erosion, instability, structural weakness, or other hazardous conditions?	No	No	No	No	No	No	No	No
Rule 4.05.9(15)(b) Existing and required monitoring procedures.	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection
Rule 4.05.9(15)(b) Required Instrumentation	Not Applicable - Nondischarging Structure	Not Applicable - Nondischarging Structure	None	None	Parshall flume in place and functioning	Not Applicable - Nondischarging Structure	None	Parshall Flume in Place and functioning
Rule 4.05.9(15)(c) Depth of Impounded Water (ft)*	Dry	Dry	11.0	9.0	12.5	2.0	0.0	12.5
Rule 4.05.9(15)(c) Elevation of Impounded Water (ft)*	Dry	Dry	7116.0	7057.0	6867.5	7212.0	7154.0	6981.5
Rule 4.05.9(15)(d) Existing Storage Capacity (ac-ft)**	2.01	24.43	0.67	0.46	4.12	6.77	3.50	1.46
Rule 4.05.9(15)(e) Any additional items effecting stability or maintenance items	None	None	None	None	None	None	None	None

<sup>\*</sup> Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.



<sup>\*\*</sup>Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumlated sediment.