




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Tamarcaz Pit	MINE/PROSPECTING ID#: M-1985-072	MINERAL: Sand and gravel	COUNTY: Gunnison
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: April 29, 2025	INSP. TIME: 12:45
OPERATOR: Gunnison County	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: May 1, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report in order to illustrate some of the conditions observed.

The Tamarcaz Pit is located approximately eighteen miles southeast of Gunnison and accessed from Hwy 50. The site is a 110c operation that includes a total of 7.0 permitted acres. Pursuant to Rule 4.1.2, a financial warranty is not required for this site because the Operator is a unit of county government.

The affected area was marked by fencing that was clearly visible and adequate to delineate the affected area boundary.

The county typically mines and crushes enough material to last for approximately three years, so mining/processing is infrequent at this site. The highwall slopes, ranging from approximately 15-20 feet high and spanning approximately 1,400 linear feet around the pit, have been graded to 2H:1V or less and appear stable. Crushed gravel is stockpiled within the pit.

Disturbances to the hydrologic balance were not noted. There was no standing water observed in the pit. Issues related to erosion or stormwater control were not noted.

There was no processing equipment or processing waste on-site.

Fuels or toxic materials are not stored on-site. The operation has not exposed toxic or acid-forming materials.

Explosives are not used for this operation.

Noxious weed infestations were not noted.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (970) 433-8393, dustin.czapla@state.co.us.



Inspection Contact Address

Martin Schmidt
Gunnison County
195 Basin Park Dr.
Gunnison, CO 81230