

Zuber - DNR, Rob <rob.zuber@state.co.us>

Bowie #2 (C1996-083) inspection report

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>

Thu, May 8, 2025 at 2:16 PM

To: Art Etter <AEtter@wolverinefuels.com>

Cc: Ryan Wilson <RWilson@wolverinefuels.com>, Tamme Bishop <tammekb@gmail.com>

Hello, All -

Here is my report from my inspection this week.

Rob

Rob Zuber, P.E. Environmental Protection Specialist Active Mines Program



Phone: 720.601.2276 | Fax: 303.832.8106

Physical Address:

1313 Sherman Street, Room 215

Denver, CO 80203

Address for FedEx or UPS:

Division of Reclamation, Mining and Safety, Room 215

1001 East 62nd Avenue Denver, CO 80216

rob.zuber@state.co.us | http://drms.colorado.gov

NSP-REPORTC_C1996083_RDZ_05082025.pdf 2887K



PERMIT INFORMATION

Permit Number: C-1996-083 Mine Name: Bowie No. 2 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Art Etter	County: Delta Operation Type: Underground Permit Status: Active Ownership: Private			
P.O. Box 1488	Operator Representative Present:			
Paonia, CO 81428	P			
1 aoma, CO 01420	None in field			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: May 6, 20 Inspection Start Time: 14:00 Inspection End Date: May 6, 202 Inspection End Time: 16:30			Inspection Type: Coal Comp Inspection Reason: Normal I Weather: Cloudy		
Joint Inspection Agency: Jo		Joint	Joint Inspection Contacts:		
None					
Post Inspection Agency:		Post Inspection Contacts:			
None					
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:	
Robert Zuber, P.E.	Phot D. The				
				5/8/2025	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection R - Roads

R - Availability of Records Y - Reclamation Success

Y - Backfill & Grading

NA - Excess Spoil and Dev. Waste

R - Revegetation

Y - Subsidence

NA - Explosives
R - Slides and Other Damage
Y - Fish & Wildlife
R - Support Facilities On-site

R - Hydrologic Balance Y - Signs and Markers

Y - Gen. Compliance With Mine Plan N - Support Facilities Not On-site

N - Other Y - Special Categories Of Mining

R - Processing Waste R - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on May 6, 2025. No BRL representatives were present for the field portion of the inspection.

No reclamation activities were observed, but the inspector was told that staff were repairing a fence.

The weather was cloudy (it rained briefly) and cool. The ground was slightly muddy in some areas.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records were found to be well organized and complete. Please see the list of records included in this report. BRL is awaiting documentation from CDPHE for both the CDPS permit and the air emissions permit.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Six sediment ponds were inspected: B, C, D, F, J, and K. None of the ponds were close to discharging. All of them were dry or nearly dry. No significant problems were identified with embankments, spillways, inlet channels, or other features of the ponds.

The Fire Mountain Canal was flowing full.

PROCESSING WASTE/COAL MINE WASTE PILES - Rule 4.10 and 4.11

Drainage Control; Surface Stabilization; Placement:

Gob Piles 1, 2, 3, and 4 appeared stable, and no significant erosion was observed. The overburden pile that is southeast of Gob Pile #2 has been reduced to a small amount of material, as most of it has been spread on this pile.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

The road to the portals was in adequate condition. The slopes adjacent to this road are generally stable, except for the slide at Curve 10 (see Slides and Other Damage section).

REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

The vegetation on Gob Piles 1 and 4 was very green. No weed problems were identified.

SLIDES and DAMAGE - Rule 4.12:

No problems were seen on the slopes above and below the benches. The slides above the B Portal Bench and Curve 11 (noted in the past) look stable. The slide above Curve Number 10 also looked stable, compared to photographs taken in recent months.

SUPPORT FACILITIES - Rule 4.04:

The following areas appeared stable with no signs of erosion:

- Utility Bench
- D Portal Bench
- B Portal Bench
- Material storage area beside Topsoil Stockpile A
- Conveyor corridors
- Coal Stockpile Pad
- The area around the office
- Preparation Plant and nearby water tank
- Pump House and Filter Building
- Old power plant
- Unit Train Loadout.

The grading project at the D Portal Bench is still in progress.

TOPSOIL – Rule 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

Topsoil stockpiles appeared to be stable.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Pond F and adjacent soil pile



Gob Pile #3



Looking east toward Gob Piles 1,2, and 4



West slope above B Portal Bench



Slide at Curve 10



Slope below D Portal Bench



Slope above Utility Bench



Topsoil Stockpile A



Pond D



Upper portion of Gob Pile #2, looking west



Riprap ditch below Gob Pile #2



Recently reclaimed portion of Gob Pile #2, looking west

AVAILABILITY OF RECORDS

PERMIT RECORDS	E 44 110007	HYDROLOGIC RECORDS	CO 0044556
DRMS Permit	Exp. 4 April 2027	CDPS Permit	CO-0044776, Exp. Sept. 2024 (pending approval)
Permit Application w/Revisions	yes	CDPS Records (DMRs)	Through April 2025
Findings Document	RN-05, 12 January 2023	Stormwater Management Plan	Revised January 2020
Insurance Certificate	Expires 1 May 2026	SPCC Plan	August 2023
Bond Documents	SEE COMMENT 1	MSHA Pond Inspections	NA
Phased Bond Release	SL2,		NA
Documents/Findings	30 Decmbr. 2016	State Engineer's Pond Inspection	
Air Emission Permits	96DL103-1 Submitted Jan. 2025	Quarterly Pond Inspections	1Q 2025
County Special Use Permits	NA	Annual Hydrology Reports	2023
UG Mining Landowner Notification	Several years	 Ground Water Monitoring 	yes
Subsidence Monitoring Reports	NA	 Surface Water Monitoring 	yes
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	NA
Rill & Gully Survey	March 27, 2025	 Mine Water Discharge Monitoring 	NA
Vegetation Monitoring Data	NA	Mine Inflow Study	NA
Specific Variance Approvals	NA	 Water Consumption Records 	NA
Annual Reclamation Reports	2024	Well Permits	NA
Midterm Review Documents	MT5, 3 October 2019		
DRMS/OSM Inspection	Through	DI ACEDIC DE CODO	
Reports/Enforcement Actions	March 2025	BLASTING RECORDS	NIA
Transfers/Succession of Operator	10 August 2009	Blasting Publication	NA
Temporary Cessation Notification Reclamation Cost Estimate	NA SEE	Blasting Records (3 years) ATFE Explosives Permit	NA NA
Reclamation Cost Estimate	COMMENT 2	ATTE Explosives Permit	NA
CERTIFICATIONS	COMMENT 2	Blasting Variances	NA
Pond Certifications	1 April 2025	Pre-Blast Surveys	NA
Fill Certifications for Underground Development Waste	Vol. IV for Gob Pile #1	ADDITIONAL RECORDS (specify)	
Quarterly Inspections	1Q 2025	SWMP Report	November 2024
Compaction Testing	October 2022		
Final Certification	NA		
Certs. for Coal Processing Waste	Vols IX, XI (Gob		<u></u>
Banks	Piles 2, 3, 4)		
Haul Road Certifications	1998 and 2013		
Access Road Certifications	Map 15 series		

COMMENTS:

- 1. Bond documents entail five corporate sureties (Lexon Company) for total of \$11,448,977.58:
 - o Bond # 1071397 for \$3,154,277.10
 - o Bond # 1071402 for \$1,502,277.97
 - o Bond # 1071403 for \$2,500,000.00
 - o Bond # 1071404 for \$2,217,169.51
 - o Bond # 1071405 for \$2,075,253.00.
- 2. The RCE for RN-05 (total of \$11,448,977) is included in the records.