




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Rollins-Clapper Pit.	<b>MINE/PROSPECTING ID#:</b> M-2025-018	<b>MINERAL:</b> Aggregate	<b>COUNTY:</b> Kit Carson
<b>INSPECTION TYPE:</b> Preoperation Inspection	<b>WEATHER:</b> Raining	<b>INSP. DATE:</b> May 6, 2025	<b>INSP. TIME:</b> 11:00
<b>OPERATOR:</b> Rollins Construction and Trucking LLC	<b>OPERATOR REPRESENTATIVE:</b>	<b>TYPE OF OPERATION:</b> 110c - Construction Limited Impact	
<b>REASON FOR INSPECTION:</b> Preoperation Inspection	<b>BOND CALCULATION TYPE:</b>	<b>BOND AMOUNT:</b>	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>INSPECTOR(S):</b> Ben Hammar	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> May 12, 2025	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>NA</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>NA</u>	(FW) FISH & WILDLIFE----- <u>NA</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>NA</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was performed as a pre-operation inspection in support of DRMS Permit No. M20205018, the Rollins-Clapper Pit. The proposed site is a 9 acre sand and gravel operation located approximately 8 miles southwest of Stratton. This inspection was performed by Ben Hammar, and the weather at the time of inspection was lightly rainy.

The primary purpose of this inspection was to check the appropriate signage was in place as required by DRMS, and to ensure no structures or significant hydrologic features are present near the permit which have not been mentioned in the application.

Regarding the posted notice sign, the sign was observed during this inspection and was found to be in compliance with all Division requirements.

Regarding structures found within 200 feet, two significant structures were found within 200 feet of the permit boundary during this inspection. A fence was found, which the DRMS notice was posted on. In addition, a transmission line runs parallel to the fence. Please provide structure agreement or similar documentation as mentioned in the associated adequacy letter.

No significant hydrological features were observed near the permit boundary, and no other issues were found with the site during this inspection. No bond has been calculated at this time, and a reclamation bond will be calculated by the Division following a response to the first adequacy letter for this site.

## PHOTOGRAPHS



Photo 1: Posted notice sign.



Photo 2: Nearby transmission lines and fenceposts.



Photo 3: Pre-mining site conditions.

**Inspection Contact Address**

Rollins Construction and Trucking LLC  
893 South 120 East  
Milford, UT 84751

Enclosure

CC: